

SEND TO:

☐ COMPL. SECTION-7☐ MUNIC. WASTEWATER SECTION-10☐ PRIV. WATER SECTION-10☒ IND. WASTEWATER SECTION-11☐ PUBL. WATER SECTION-10☒ Horicon Area DISTRICT

DATE

7 9 10 16
Y Y M M D D

TIME (24-HOUR CLOCK)

11:00

CONTACT METHOD

☒ PERSONAL☐ TELEPHONE

FACILITY NAME

Romont Mfg.

LOCATION

Oakfield

COUNTY

Fond

FACILITY I.D.

WPDES PERMIT NO.

00425104

DISTRICT NO.

DNR CONTACT

Harpt

FACILITY REPRESENTATIVE CONTACTED

Mr. Paul

TITLE OR POSITION OF REPRESENTATIVE

Pl Mgr.

CONTACT TYPES (CHECK ONE BOX ONLY)

1. ☐ O&M INSPECTION (7500-5)

WATER SUPPLY CONTACT

2. ☐ CEI SURVEY5. ☐ INITIAL CONTACT6. ☐ FOLLOW-UP CONTACT3. ☐ CSI MONITORING SURVEY7. ☐ GENERAL COMPLAINTS4. ☐ MEETINGS/PUBLIC HEARINGS

ACTIVITY CODES

D R

DETAILED LETTER/REPORT TO BE WRITTEN

☐ YES☒ NO

SAMPLE TAKEN

☐ YES

SAMPLE LOCATION

☒ NO

COMMENTS (For Key punching - First 200 Characters Will Be Stored)

VEAT

talked to Mr. Paul about SEMORE for the
will start submitting + monitoring als per
permits -

ADDITIONAL COMMENTS:

not having complete knowledge of piping + sewer
system in plant looks like solely noncontact
cooling H₂O from parts cleaning chamber (vapors clean)went to receiving stream - point at which
storm sewer enters the surface H₂O -
oil coming out - sewer - quite a bit more
than a sheen -Several possibilities as to sources - dye investigation
needed

F/M	VIOL. DATE					VIOL. CODE	SEQ. NO.	ACTION CODE
	Y	Y	M	M	D			

T. M. Harpt