PLEASE PRINT

04-38-2/3653
State of Wisconsin Substance Release Notification Form

	24-Hour Emergency Hotline Nun	iber: 1-800-943	-0003		F	orm 4400-91 Rev. 11-95	
53	Date and Mil. Time of Incident	9-96 0930	7 Date and	Mil. Time Re	eported 100	28-96 1050	
36	Person Reporting Phil Eberi	hart		Teleph	one # (7/5	735-7633	
20	Representing Agency, Firm, or Citizen Spaciality Chem						
00	Responsible Party Roll Specalty Chem						
1.3	Contact Name	Phil &	Eberhor	Teleph	one # (MBOLL	
99	Address #2 STANTON ST				State, Zip Co	ode 45 54143	
	Substance Involved 1,2 Dipheroexthere	Amount & Units	and the second s	t. Recovered		304 (11004 42 USC) spill? I No □ Unknown	
	5 Solid □ Semisolid □ Liquid	□ Gas Co	dor Blue-gi	iner	Odor	ejes	
	Exact Location (inc. address, facility name, mileage, bldg. #, etc.) BLOG #38 EXHAUST/VENT						
	City MARINETTE	County Man	wette	Lat/long			
	DNR Region NER	1/41/4secT	-				
	Cause of Incident A Suppossed empty vesser, Discharge FLANGE TAKENOFF material inside peleased words BLDG exhaust system verted to cutside						
	Spilled Substance Impact To: Check () all that apply Air	Spill Source: ☐ Transportation Accident, Fuel Supply Tank Spill ☐ Transportation Accident, Load Spill ☐ Industrial Facility ☐ Paper Mill ☐ Chemical Co. ☐ Ag Coop/Facility/Food Factory/Facility ☐ Gas/Service Station/Garage/Auto Dealer, Repair Shop ☐ Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler ☐ Public Property (city, state, church, school, etc.) ☐ Utility Co., Power Generating/Transfer Facility ☐ Private Property (home/farm) ☐ Construction, Excavation, Wrecking, Quarry, Mine ☐ Airport Facility ☐ Railroad Facility ☐ Other				Action Taken By Spiller No Action Taken No Action Needed Monitor Cleanup Method: Sweep of Waste Destination: Med Fells Containment Contractor Hired Name: Other:	
	Injuries? ☐ Yes ☐ No If yes, how many? Has an evacuation occurred? ☐ Yes ☐ No Potential? ☐ Yes ☐ No						
	Are there any resource damages? Yes No Potential What kinds?						
	Other Agencies Notified (first column if notified); Check () both columns if on scene Fire Department/Hazmat Local DNR EPA known: Local Law Enforcement Div. Emer. Gov. Nat'l Resp. Ctr. 800-442-8802 LEPC or Local Emer. Gov. DATCP 608-224-4500 Chemtrec 800-424-9300 Phone: Phone: Phone:						
	Prepared By: (Print) STEVEN Days) (Sign)	two Day	L Date:	8-96 R _I	ot'd to DATCP? □Yes □No	
	Person Notified:		Region Notified	:	Time:	Date:	
	Invstgtd By:(Print)	ge (Sign)	ten Den	Datez		te Closed? Yes	
	Spill Coordinator Signoff:	111	Date: Transfer	red to ERP?		FA Letter Sent? Yes No	
	The sel all	7-28-	17 Lies; C	13C #	— Sp	oill Packet Sent? □Yes No	

Additional Comments on Reverse

State of Wisconsin Substance Release Report (Con't) Form 4400-91 Rev. 11-95

Date and Military Time of Incident 1028-96 0430	Responsible Party Specify Chen
Iditional Comments:	
employees walking with a	r vesser they thought
USS empty when they for	K off Florge, descharge
30 uned Bue glorgery nate	ing relessed whered
OUTSIDE BUDG. ONly Able to	recover what settled out
at went.	
1-31-97 Phil	
Certificate of Disposal	
Solid > Still Waiting	
waiting for rework -	
an Stuff was Se	nt co
Resend in everything	of well solid
has been reworked	



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Tommy G. Thompson, Governor George E. Meyer, Secretary William R. Selbig, Regional Director Northeast Regional Headquarters Solid Waste Office PO Box 10448, 1125 N. Military Ave. Green Bay, Wisconsin 54307-0448 TELEPHONE 414-492-5916 FAX 414-492-5859 TDD 414-492-5812

April 25, 1997

John Harris
Specialty Chem Products Corporation
Two Stanton Street
Marinette WI 54143

SUBJECT:

No Further Action Request, October 28, 1996, 1,2-Diphenoxyethane (DPE)

Release

Two Stanton Station, Marinette, Wisconsin

Dear Mr. Harris:

The Department has received the spill response and documentation summary. The Department of Natural Resources has reviewed the response summary and concur that the environment has been restored to the extent practicable as provided in ch. NR 708.09, Wis. Adm. Code. Therefore, the Department is requiring no further action at this time.

We appreciate your efforts to protect and restore the environment at this site. If you have any questions regarding this No Further Action determination, please contact me at the number listed below.

Sincerely,

Roxanne Nelezen Chronert

Spills Coordinator - Hydrogeologist

Telephone: (414)492-5592

Philip Everhart; Specialty Chem Products Corporation

CLOSURE\NFACTION.LET



A Bayer - Company

April 23, 1997

Two Stanton Street Marinette, WI 54143 Phone: 715 735-9033 Fax: 715 735-5304

Roxanne Nelezen Chronert Wisconsin Department of Natural Resources 1125 N. Military Avenue P.O. Box 10448 Green Bay, Wisconsin 54307-0448

Subject:

1,2-Diphenoxyethane(DPE) Release on 10/28/96

Final Disposition of Collected Materials

Dear Mrs. Nelezen Chronert:

In accordance with earlier correspondence and conversations, we are now able to document final disposition of DPE materials collected during cleanup following the subject release incident.

As reported earlier in our January 6, 1997 letter to DNR, that portion of the DPE cleanup materials that had been mixed with Oil Dri was shipped to the Environmental Systems Company (Ensco) incinerator in El Dorado, Arkansas for destruction. Four barrels weighing a total of 1,605 pounds were incinerated at a cost of \$ 1,444.50 (plus shipping expenses). Copies of the manifest, certificate of destruction, and invoice for payment for these are attached.

The portion of the DPE cleanup material that was not "contaminated" with Oil Dri was to be recovered via distillation at the end of the current production campaign. Five barrels of the DPE cleanup material were charged into the process still on February 28, 1997. This material was redistilled in conjunction with some off-spec DPE to provide batch 38-043-97 of DPE product. Two additional barrels of DPE cleanup material, which had been melted for charging, were found to contain some cleanup debris such as rubber gloves, some insulation, and some wood chips. We determined that contaminants of this type posed a safety risk during charging of the still and, thus, these two barrels were classified as unuseable.

The two barrels, described above, were then included in an April 1, 1997 shipment of waste materials sent to Ensco for incineration. Although part of a full truckload, these two barrels weighing a total of 924 pounds were shipped under a separate manifest and were incinerated at a cost of \$831.60 (plus shipping expenses). Copies of the manifest, certificate of destruction, and invoice for payment for these final two barrels are attached.

Should you have any questions or desire any additional information regarding handling of cleanup materials from this incident, please don't hesitate to contact either of us at (715) 735-9033.

Sincerely,

John W. Harris

irector,

Regulatory Affairs

Philip R. Everhart

Director

Health, Environment, and Safety



SpecialtyChemTM Products Corporation <u>Memorandum</u>

Safety Today for a Safer Tomorrow

Date:

24 March 1997

c: R. Bartos

To:

Jack Harris

From:

David Mielke Dym

Subject: DPE Spill Recovery

Five barrels of the DPE spill material were charged to 3812 on 2/28/97. This material was redistilled in conjunction with off-spec DPE to provide batch 38-043-97. The remaining two barrels, which were melted for charging, contained gloves, insulation and wood chips. Contaminants of this type pose a safety risk during the charging of the still and thereby determined unusable. The two barrels were allowed to resolidify and were then taken to the Hazardous Waste Pad for subsequent disposal.

JAN 0 9 1997

LMD SOLID WASTE

SpecialtyChem Products Corporation A Subsidiary of ChemDesign



January 6, 1997

Corrine Johnson Wisconsin Dept. of Natural Resources 1125 N. Military Avenue P.O. Box 10448 Green Bay, WI 54307-0448 A Bayer 🙌 Company

Two Stanton Street Marinette, WI 54143 Phone: 715 735-9033 Fax: 715 735-5304

Subject:

1.2 Diphenoxyethane Release on October 28, 1996

Status of disposition of collected materials

Dear Ms. Johnson

As we had discussed earlier, each of the two types of collected materials from this incident are being handled in different ways.

Cleanup materials that had been mixed with Oil Dri were consolidated, drummed, and shipped to the Environmental Systems Company (Ensco) incinerator in El Dorado, Arkansas for destruction. These materials, although part of a full truckload shipment to Ensco, were shipped under a separate manifest. A copy is attached. Also attached is a copy of the "Certificate of Treatment/Disposal" from Ensco which states that this material was incinerated on December 17, 1996. The invoice for incineration (copy attached) indicates that 1,605 pounds of material was incinerated at a cost of \$1,444.50.

Remaining cleanup materials which were not 'contaminated' with Oil Dri will be recovered. It is our intent to handle these materials just like any other 'off spec' product materials which may be produced during the current production campaign. Recovery will be via distillation at the end of the campaign. A copy of an internal memo regarding our intent to recover this material is attached.

Should you have any questions or desire any additional information regarding handling of cleanup materials from this incident, please don't hesitate to contact either of us at (715) 735-9033

Sincerely,

John W. Harris

Director,

Regulatory Affairs

Philip R. Everhart

Director,

Health, Environment, and Safety

Philip 1 2 part

JWH/jh Attachments

SpecialtyChem[™] Products Corporation Memorandum

Safety Today for a Safer Tomorrow

Date:

5 December 1996

cc: R. Bartos

To:

Jack Harris

From:

David Mielke

Subject: DPE Spill Recovery

The 7 x 55 gal drums (2497 lbs) of DPE scraps recovered from the spill(3820) will be recovered at the end of the DPE campaign. The solids will be melted and charged to 3812 for redistillation with other out of spec. material. After distillation the material will be isolated as an additional production lot. Any material that does not distill (still bottoms) will be disposed of in 55 gal closed top mild steel drums as Hazardous waste. Based on our current production rate I would expect this material to be incorporated into the process by February 15, 1997.



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Tommy G. Thompson, Governor George E. Meyer, Secretary William R. Selbig, District Director Lake Michigan District Headquarters PO Box 10448, 1125 N. Military Ave. Green Bay, WI 54307-0448 TELEPHONE 414-492-5800 FAX 414-492-5913 TDD 414-492-5812

October 31, 1996

Mr. Phil Eberhardt Speciality Chem 2 Stanton St. Marinette, WI 54143

Subject:

1,2 Diphenoexthene Release on October 28, 1996 at Speciality Chem

Dear Mr. Eberhardt:

In order to complete the Department's records for the above referenced incident, please submit documentation of disposal (example: landfill receipts) and a copy of the Remedial Action Summary Report as soon as they are available. When the report and disposal documentation are received, the Department will be able to review the file for completeness and a no further action determination.

Please send the above referenced documentation to me at the following address:

Corinne Johnson Wisconsin Department of Natural Resources 1125 N. Military Ave. P.O. Box 10448 Green Bay, WI 54307-0448

Thank you for your cooperation in this matter. If you have any questions regarding the content of this letter, please contact me at the number listed below.

Sincerely,

Corinne Johnson

Bureau of Remediation and Redevelopment

(414) 492-5943

