From: Stoltz, Carrie R - DNR

Sent: Tuesday, October 17, 2017 9:00 AM

To: 'Jason Powell, METCO - Staff Scientist (jasonp@metcohq.com)'

Subject: Port Wing Report review **Attachments:** 20171017074419878.pdf

Hi Jason, I just finished reviewing the Port Wing letter report. Just a couple of comments. Attached is the extent of soil contamination, excavation area and groundwater flow figures. The extent of soil contamination should reflect lab results. It does not appear as though the soil contamination extends as far as it is presented. Some of the lines should be dotted instead of solid. I would recommend updating this figure. Also, the contours of the GW flow map look strange (not enough points to accurate depict contours), but this can wait until we have more data. If you have any questions, let me know. Thanks, Carrie

We are committed to service excellence.

Visit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

Carrie Stoltz

Hydrogeologist-Remediation and Redevelopment, AWARE Division Wisconsin Department of Natural Resources 107 Sutliff Avenue, Rhinelander, WI 54501

Phone: (715)365-8942 Fax: (715)365-8932

Carrie.Stoltz@Wisconsin.gov







