

Stoltz, Carrie R - DNR

From: Stoltz, Carrie R - DNR
Sent: Tuesday, March 13, 2018 2:53 PM
To: 'Dave Larsen (dlarsen@reiengineering.com)'
Subject: Thomas Service SIR Comments

Hi Dave, I just finished reviewing the SIR for Thomas Service. I agree with your assessment; an excavation with GW monitoring is needed. I found a few borings that were not listed on the figures (S-1 thru S-16). The following were sampled (S-1,2,6,8,10). It would be nice to know where they are located. I feel degree and extent have been defined and the SI is complete. Please contact me with any questions. Thanks, Carrie

We are committed to service excellence.

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

Carrie Stoltz

Hydrogeologist-Remediation and Redevelopment, AWARE Division
Wisconsin Department of Natural Resources
107 Sutliff Avenue, Rhinelander, WI 54501
Phone: (715)365-8942
Fax: (715)365-8932
Carrie.Stoltz@Wisconsin.gov



dnr.wi.gov

