Department of Natural Resources

BRRTS CASE TRACKING FORM

ype of Case: LUS1 ERP 453M 453P	SER Form #1 July 1, 1997
ACTIVITY NO.: 02-68-305374	FID NO.: 268687826
County: Waskesha Site Name: Former Fabricare Property Address: 323 W. Sunset Dr. Municipality: Waskesha, WI Legal Desc.: 1/4 1/4 Sec Tn Rng E Lat.: Long.:	Initial Contact Date: Send RP Letter? Y DE C Date Mailed: / / Closure Date: Person/Firm Reporting: Phone: ()
PRIORITY: High RP Medium LTF Low EF Unknown SF None STHIS LUST CASE Y_N_ Potentially EPA Émergency Response Abandoned Containers LUST NR 600 Hazardous Waste SPINDLING SOURCE: RP Work LUST Spills Superfund	Wastewater (lagoons) Onse Haz Waste NR600
RESPONSIBLE PARTY is aCompany or a _K_Person Company Name: Contact Person: Address: 2201 Gulf view Rd. Punta Gorda, FL 33950 Phone: CC:	CONSULTANT: Company Name: Contact Name: Address: Phone: CC: (EG: lab)
IMPACTS: (enter P for potential, K for known) Fire/Explosion Threat Contaminated Private Well(s) No. of Wells Contaminated Public Well Groundwater Contamination Soil Contamination Surface Water Impacts Free Product Storm Sewer Contam. Sanitary Sewer Contam. Air Contamination Direct Contact Concrete/Asphalt Contained/Recovered Other: NEW FOLDER? Y N	SUBSTANCES: #Tanks/containers Size Leaded Gas Unleaded Gas Diesel Fuel Oil Unknown Hydrocbn Waste Oil Metals RCRA Haz. Waste VOCs Chlorinated Solvent PCBs Foundry Sand Misc. Fill Pesticides Leachate PAHs/SVOCs



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Scott McCallum, Governor Darrell Bazzell, Secretary Gloria L. McCutcheon, Regional Director Southeast Region Headquarters 2300 N. Dr. Martin Luther King, Jr. Drive PO Box 12436 Milwaukee, Wisconsin 53212-0436 Telephone 414-263-8500 FAX 414-263-8713

March 26, 2002

Inez Zillmer 2201 Gulfview Road Punta Gorda, FL 33950

Subject: Former Fabricare, 323 W. Sunset Dr., Waukesha, WI

Dear Ms. Zillmer:

The City of Waukesha's tax records identify you as the owner of the property at 323 West Sunset Drive in Waukesha, WI. The Department of Natural Resources was informed that tetrachloroethene (or perchloroethene) contamination was discovered at the KFC Restaurant site located at 331 West Sunset Drive (file reference FID #368007200, BRRTS #0768257076). Based on the following reasons it is believed that the tetrachloroethene contamination originated from your site:

- 1. A phase 1 environmental investigation for the KFC property did not indicate the use of tetrachloroethene.
- 2. Groundwater flow direction measured at sites near your location is generally from your location toward the KFC location.
- 3. Tetrachloroethene contamination on the KFC property was not found in shallow soil samples, but was only found near the groundwater interface, indicating that it migrated from another location.
- 4. Records show that the property at 323 West Sunset Drive was a dry cleaner from 1979 to 1999. Tetrachloroethene is a common cleaning agent used by dry cleaners.

Based on the information submitted to the WDNR, we believe you are responsible for restoring the environment at the referenced site under Section 292, Wisconsin Stats., known as the hazardous substances spills law.

This letter describes your legal responsibilities, explains what you need to do to investigate and clean up the contamination, and provides you with information about cleanups, environmental consultants, possible financial assistance, and working WDNR.



Legal Responsibilities:

Your legal responsibilities are defined both in statute and in administrative codes. The hazardous substances spill law, Section 292.11 (3) Wisconsin Statutes, states:

• RESPONSIBILITY. A person who possesses or controls a hazardous substance which is discharged or who causes the discharge of a hazardous substance shall take the actions necessary to restore the environment to the extent practicable and minimize the harmful effects from the discharge to the air, lands, or waters of the state.

Wisconsin Administrative Code chapters NR 700 through NR 749 establish requirements for emergency and interim actions, public information, site investigations, design and operation of remedial action systems, and case closure. Chapter NR 708 includes provisions for immediate actions in response to limited contamination. Wisconsin Administrative Code chapter NR 140 establishes groundwater standards for contaminants that reach groundwater.

Steps to Take:

The longer contamination is left in the environment the farther it can spread and the more it may cost to clean up. Quick action may lessen damage to your property and neighboring properties and reduce your costs in investigating and cleaning up the contamination. To ensure that your cleanup complies with Wisconsin's laws and administrative codes, you should hire a professional environmental consultant who understands what needs to be done. These are the <u>first</u> three steps to take:

- 1. Within the next **30 days**, you must submit <u>written</u> verification (such as a letter from the consultant) that you have hired an environmental consultant.
- 2. Within the next **60 days**, your consultant must submit a workplan and schedule for the investigation. The consultant must follow the WDNR administrative codes and technical guidance documents. To facilitate prompt agency review of your reports, your consultant should use the site investigation and closure formats which are available on-line at www.dnr.state.wi.us.
- 3. Within 30 days of completion of the site investigation, you or your consultant must provide a brief report at least every 90 days per NR 724.13(3). Quarterly reports need only include one or two pages of text, plus any relevant maps and tables. Should conditions at your site warrant, we may require more frequent contacts.
- 4. Sites where discharges to the environment have been reported are entered into the Bureau for Remediation and Redevelopment Tracking System (BRRTS), a version of which appears on the WDNR's internet site. You may view the information related to your site at any time (http://www.dnr.state.wi.us/org/aw/rr/brrts) and use the feedback system to alert us to any errors in the data.

If you want a formal response from the agency on a specific submittal, please be aware that a review fee is required in accordance with s. NR 749, Wis. Adm. Code. If a fee is not submitted with your reports, you should proceed under the advice of your consultant to complete the site investigation to maintain your compliance with the spills law and chs. NR 700 through NR 749. **Do not delay the investigation of your site by waiting for an agency response.** We have provided detailed technical guidance to environmental consultants. Your consultant is expected to know our technical procedures and administrative codes and should be able to answer your questions on meeting cleanup requirements.

All correspondence regarding this site should be sent to:

Victoria Stovall Remediation and Redevelopment Program Wisconsin Department of Natural Resources Box 12436 Milwaukee, WI 53212-0436

Unless otherwise requested, please send only one copy of plans and reports. To speed processing, correspondence should reference the BRRTS and FID numbers (if assigned) shown at the top of this letter.

Additional Information for Site Owners:

Information to help you select a consultant, and materials on controlling costs, understanding the cleanup process, and choosing a site cleanup method are enclosed. In addition, *Fact Sheet 2, Voluntary Party Remediation and Exemption from Liability* provides information on obtaining the protection of limited liability under s. 292.15, Stats.

Financial Assistance:

Funding is available for cleanup at some drycleaning sites. Call the DNR Gina Keenan at (414) 263-8589 for more information on eligibility or visit the RR web site. http://www.dnr.state.wi.us/org/aw/rr. You may also contact this person for all other questions regarding this letter.

Thank you for your cooperation.

Sincerely,

Victoria Stovall Program Assistant Bureau for Remediation and Redevelopment

Enclosures:

1. Selecting a consultant

2. Fact Sheet 2, VPLE