



State of Wisconsin

DEPARTMENT OF NATURAL RESOURCES

Cumberland Area Hdqrs.
Box 397
Cumberland, WI 54829

Area
Put on BRPS
12/17/88
(84)
per
Carroll D. Besadny
Secretary

November 16, 1987

3300

Ms. Martha C. Brand
Leonard Street and Deinard
Suite 1500, 100 South 5th St.
Minneapolis, MN 55402

RECEIVED

OCT 11 1988

NORTHWEST DISTRICT
HEADQUARTERS

Dear Ms. Brand:

Re: Investigation of VOC and Metal Contamination, UMET Inc. Site,
Amery, Wisconsin

We have reviewed the Foth & Van Dyke correspondence of September 21, 1987 concerning on-site activities at the Electro-Craft facility in Amery, Wisconsin.

We intend to close the file on the subject investigation when the following tasks are completed and documented:

1. Abandonment of the underground storage tanks. A copy of DILHR form SBD-7427 (form enclosed) documenting the abandonment should be sent to me for inclusion in the file.
2. Abandonment of the groundwater monitoring wells. Upon abandonment, the attached forms must be completed and returned to me for inclusion in the file.

In addition, we request that UMET, Inc. notify this department of any changes in operating status of the facility (new owners, new occupants, new processes, different production lines, etc.). If future activities at the facility present the possibility of hazardous substances being spilled/released to the loading dock sumps, the Department may require an alternate surface runoff drainage system.

Upon completion of the aforementioned items, we will consider the subject investigation closed down. If you have any comments or questions concerning this letter, please direct them to me at 715-822-3590. Your cooperation, as always, is appreciated.

Sincerely,



Dave Hanson
Water Supply Specialist

DNH:dh

cc: Charles Dayton

Pepin, Dayton, Herman, Grahn & Getts, P.A.

930 Lumber Exchange

10 So. 5th St.

Minneapolis, MN 55402

Timothy P. Doran, P.E.

Foth & Van Dyke & Associates, Inc.

P.O. Box 19012

Green Bay, WI 54307-9012

Gary LeRoy - Spooner

Mark Giesfeldt - W3

Linda Wymore - L65

Further remediation/investigation needed
Site re-opened
Contact Project Manager for assistance