



ENVIRONMENTAL & REGULATORY SERVICES DIVISION
BUREAU OF PECFA
P.O. Box 8044
Madison, Wisconsin 53708-8044
TDD #: (608) 264-8777
Fax #: (608) 267-1381
<http://www.commerce.state.wi.us>
<http://www.wisconsin.gov>
Scott McCallum, Governor
Philip Edw. Albert, Secretary

November 19, 2002

Bruce West
West's Hayward Dairy
809 Johnson
PO Box 506
Hayward, WI 54843

RE: **Final Closure**

Commerce # 54843-9999-24 WDNR BRRTS # 02-58-000054
West Hayward Dairy, 124 W 2nd St., Hayward

Dear Mr. West:

The Wisconsin Department of Commerce (Commerce) has reviewed the request for case closure prepared by your consultant, No Consultant found, for the site referenced above. Commerce has determined that this site does not pose a significant threat to the environment and human health. No further investigation or remedial action is necessary.

This site is now listed as "closed" on the Commerce database. This letter serves as your written notice of "no further action". Timely filing of your final PECFA claim (if applicable) is encouraged. If your PECFA claim is not received within 120 days of the date of this letter, interest costs incurred after 60 days of the date of this letter will not be eligible for PECFA reimbursement.

It is in your best interest to keep all documentation related to the environmental activities at your site. If residual contamination is encountered in the future, appropriate measures must be implemented to assure that it is managed following all applicable regulations. If future site conditions indicate that any remaining contamination poses a threat, and subsequent information indicates a need to reopen this case, any original claim under the PECFA fund would also reopen and you may apply for assistance to the extent of remaining eligibility.

Thank you for your efforts to protect Wisconsin's environment. If you have any questions, please contact me in writing at the letterhead address or by telephone at (608) 261-7718.

Sincerely,


Will M. Myers
Geologist
Site Review Section

Will Meyers
201 W Washington
P.O. Box 8044
Madison, Wi. 53708

RECEIVED
NOV 14 2002
ERS DIVISION

Will Meyers,

The lot where my house is was completely removed and dug out and halled away and the well was Capped by a well digger ,a new well was drilled out side the house. And a new house built on the Same lot in the city .,



Bruce West



State of Wisconsin \
DEPARTMENT OF NATURAL RESOURCES

Tommy G. Thompson, Governor
George E. Meyer, Secretary
William H. Smith, District Director

Northwest District Headquarters
810 West Maple Street
Spooner, WI 54801
TELEPHONE 715-635-2101
FAX 715-635-4105
TDD 715-635-4001

July 17, 1996

BRUCE WEST
WESTS HAYWARD DAIRY
PO BOX 506
HAYWARD WI 54843

COPY

SUBJECT: Transfer of Your File for the West Hayward Dairy, DNR site ID# 02-58-000054 to the Department of Commerce

The 1995-97 state budget bill made significant changes in the way state government manages discharges to the environment from petroleum storage tank systems. As of July 1, 1996, the Department of Commerce is responsible for governmental oversight of environmental cleanup activities at properties contaminated by petroleum storage systems when contamination has not impacted groundwater above state preventative action levels.

This letter is to notify you that the Department of Natural Resources (DNR) has an open file regarding contamination at the above site, and this file is being transferred to the newly created Department of Commerce.

Information presented to the DNR to date shows that this site falls into the group of sites identified for transfer. Therefore, we are transferring your file to the Department of Commerce effective immediately. Commerce will provide all future oversight of your cleanup at this property, including determination of file closure.

All future contacts regarding this site should be directed to the Department of Commerce. You may contact Commerce at either (608) 266-2424 or (608) 267-3753. Correspondence should be addressed to:

PECFA Bureau
Environmental and Regulatory Services Division
Department of Commerce
P.O. Box 7969
Madison, WI 53707-7969

Please include both your PECFA claim number, if you have one, and your DNR site identification number in your correspondence. The PECFA program reimbursement staff have also been transferred to Commerce from the Department of Industry, Labor and Human Relations (DILHR), effective July 1, 1996.

You must notify your consultant of this change. Your efforts toward clean-up at this site are greatly appreciated.

Sincerely,

Tom Kendzierski
Environmental Repair Unit Supervisor


ATTN. _____	<input type="checkbox"/> PRETREATMENT WW/2	Date M M D D Y Y 1 26 89
<input type="checkbox"/> ENV. ENF. EE/5	<input type="checkbox"/> MUNIC. WASTEWATER SECTION WW/2	Time (24-Hour Clock) 9:40
<input checked="" type="checkbox"/> PRIV. WATER SECTION WS/2	<input type="checkbox"/> IND. WASTEWATER SECTION WW/2	Contact Method <input type="checkbox"/> In Person <input checked="" type="checkbox"/> Telephone
<input type="checkbox"/> PUBL. WATER SECTION WS/2	<input type="checkbox"/> _____ DISTRICT	

Facility Name Freemal Well + Pump Repair	Location (Address or 1/4-1/4) Hayward	County SALYER
Facility I.D. -----	WPDES Permit Number -----	District No. 8
Facility Representative Contacted Bob Freemal	Title or Position of Representative P.I.	
Activity Codes -----	Representative's Telephone Number (including area code) 634-2707	
DNR Person Making Contact N. Cable		

Bob called re: pt. well in a basement that is pumping fuel oil -
 - In Dec '88 Bruce West (West Dairy in Hayward) had his house
 burn down - He lives just beyond (2 houses) Hayward city H₂O
 on the rd to the cemetery - several other houses in the
 immediate area are on pt. wells
 - when house burned - 265 gal. fuel tank in basement broke up
 + all 265 gal leaked out - 1 1/4" well pt is in the basement
 + there is a 4" diam opening in the cement floor where the
 pt. well is - oil leaked down around well casing -
 its 7ft to H₂O & well pt. is 28ft deep -
 - Bob Freemal hooked up a pump to this well & pumped 5gal
 of water in a bucket - there is an oil film on the water
 & he could smell fuel oil
 - I told Bob not to cement the well up yet as we may want
 to pump it - I told Bob I would have DNR follow up on
 this as a spill (The property owner can be reached at
 West Dairy in Hayward), West would like follow up ASAP (both for concern
 for groundwater contamination and insurance purposes)
 - CC - Tom Hendzierski - Spooner

Check if Additional Sheets Attached

Bruce West 634-2244 (DAYS)



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Northwest District Headquarters
Box 309
Spooner, WI 54801

Carroll D. Besadny, Secretary
TELEFAX NO. 715-635-4105

September 15, 1989

File Ref: 4440

Mr. Bruce West
P.O. Box 506
Hayward, WI 54843

Dear Mr. West:

I hope I can clear up an apparent misunderstanding.

You had asked me to provide you with a letter stating that your property is "clean" of contamination. I must explain that the Department of Natural Resources is not in the business of providing environmental assessments or opinions of risk associated with properties. I have attached a brief list of firms who are in this business for your information.

The Department mandate from the legislature is to enforce laws protecting health, safety, and the environment. In your case, a spill occurred which violated Section 144.76, Wisconsin Statutes.


Because you incurred a hardship with your house burning down, I did not insist on professional assistance in performing the cleanup. I did recommend professional assistance in our telephone conversations, but you felt that was too costly. I am willing to accept the laboratory analysis of soils you provided and your word that contaminated soil was cleaned up properly.

The water sample is another story. You submitted a water sample analysis from the State Lab of Hygiene for coliform bacteria. Our concern was for fuel oil which may have gotten into the well. Why didn't you send a water sample along with the soil to Northern Lakes Service for a fuel oil analysis? Bacteria in the water was not our contaminant of concern, fuel oil was.

Mr. Froemel, the pump installer, did make an effort to purge the well of fuel oil. I will not insist on a water analysis for fuel oil if you can provide proof that the well was properly abandoned.

The Department does not intend to pursue further enforcement action at this time. We may require additional work if future problems come to our attention. Whether or not the property is "clean" is something you will have to convince prospective buyers and mortgage holders of at the time you sell the property.

Sincerely,


Tom Kendzierski
Hydrogeologist

TJK:mj

cc: Iris M. Moe, Office Manager, Governor's Northern Office
Box 787, Hayward, WI 54843

0989\HW8J0616.TJK

*LIST OF ENVIRONMENTAL CONSULTANTS
WORKING IN THE WDNR NORTHWEST DISTRICT*

These firms are qualified to do hydrogeologic investigations and remedial work. Most are within 2-3 hours drive and commonly work in the district. This is a partial list and does not imply a recommendation of these firms over similarly qualified firms not listed.

<i>Ayres Associates</i>	<i>1300 West Clairemont Avenue Eau Claire, WI 54702 715/834-3161</i>
<i>Bay West, Inc.</i>	<i>800 North Grotto Street St. Paul, MN 55104 612/488-1008</i>
<i>Braun Environmental</i>	<i>245 Roselawn Avenue East Maplewood, MN 55117 612/487-3245</i>
<i>Central Wisconsin Engineers</i>	<i>P.O. Box F Schofield, WI 54476 715/359-9400</i>
<i>Delta Environmental</i>	<i>1801 HWY 8, Suite 123 St. Paul, MN 55112 612/636-2427</i>
<i>Foth and Van Dyke</i>	<i>6474 City West Parkway Eden Prairie, MN 55344 612/942-0396</i>
<i>Nova Environmental</i>	<i>Suite 420, Hazeltine Gates 1107 Hazeltine Blvd Chaska, MN 55318 612/448-9393</i>
<i>RREM, Inc.</i>	<i>1301 North 3rd Street Superior, WI 54880 715/392-7222</i>
<i>STS Consultants</i>	<i>2405 North Annapolis Lane Plymouth, MN 55441 612/559-1900</i>
<i>Twin Cities Testing</i>	<i>P.O. Box 656 Wausau, WI 54401 612/645-3601</i>
<i>Warzyn Engineering</i>	<i>715 Florida Avenue South Golden Valley, MN 55426 612/593-5650</i>



TOMMY G. THOMPSON

**Governor
State of Wisconsin**

RECEIVED

SEP 14 1989

NORTHWEST DISTRICT
HEADQUARTERS

September 13, 1989

Tom Kendzerski
DNR District Office
P.O. Box 309
Spooner, Wisconsin 54001

Dear Tom:

This letter is a follow-up to our conversation of Sept. 12th regarding a request from Bruce West, Hayward, for a letter from the Department of Natural Resources stating the results of the soil and water tests taken from his property.

Mr. West would appreciate a letter confirming the test results and stating that the soil and water tested clear.

Please let me know if any further information is needed and I appreciate your assistance.

Sincerely,

A handwritten signature in cursive script, appearing to read 'Iris'.

Iris M. Moe
Office Manager
Governor's Northern Office

IMM/mmo
cc: Bruce West



West's Hayward Dairy

WISCONSIN GRADE A MILK, CREAM, CHEESE, BUTTER AND ICE CREAM
124 W. 2nd St. - HAYWARD, WIS. 54843 - Tele. 634-2244

Here is the water results of
my well. Please send me a letter
clearing my property of any
contamination from the Fuel
oil leak and Soil Pits.

Thank you
Bruce West,

RECEIVED

AUG 24 1989

NORTHWEST DISTRICT
HEADQUARTERS

First Water Quality Test For
WISCONSIN UNIQUE WELL NUMBER **CR 707**

Property Owner BRUCE WEST Telephone Number (757) 634-2505

Mailing Address 809 JOHNSON

City HAYWARD State WI Zip Code 54843

County of Well Location W Well Completion Date 8/11/88

Well Constructor (Business Name) Robert Froemel Registration # _____

Address Well & Pump Repair

City Hayward, WI 54843 Zip Code (757) 634-2505

*2-000d
S.M.*

STOP! DETACH SLIP AT TOP BEFORE COMPLETING UNSHADED AREAS

Date of Collection 07/11/89 Time 01:50 AM PM

Collected By: DAVID FROEMEL

Sample Location

Test Pump Air Lift
 Bailor Sampling Faucet
 Other _____

Pump Installer ROBERT FROEMEL
(If Known)

Permit No 4354

Please indicate tests desired.

Bacteriology (See explanation of tests on reverse side.)
 Nitrate

Microbrane Filter Test (MFCU) _____
 (1 to 1000)

CFR Tube (MER) Test (M-1005-10M) _____
 Fluorimetric 20 hrs. _____
 Fluorimetric 20 hrs. _____


Coliform Group 0

Bacteriological Interpretation LI - Safe

Lab Name _____ Lab No. _____

Date Received Jul 17 '89 No. 03755

Date Reported Jul 17 '89 6



file

State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Northwest District Headquarters
Box 309
Spooner, WI 54801

Carroll D. Besadny
Secretary

February 7, 1989

File Ref: 4400

Mr. Bruce West
P.O. Box 506
Hayward, WI 54843

Dear Mr. West:

Chapter 144.76, Stats., requires spills of hazardous substances to be cleaned up to the extent economically and technically feasible. A spill of fuel oil (a hazardous substance) during a fire on your property was reported to Nadene Cable of the Department of Natural Resources' Water Supply staff.

The fuel oil apparently contaminated concrete and soil in the basement of the structure and entered a driven point well. To prevent future environmental damage, you should document that the well has been purged of fuel oil. A laboratory analysis of the well water shall be submitted to the Department prior to abandonment. A well abandonment report shall be submitted to the Department after the well is properly abandoned.

Contaminated concrete can be steam-cleaned or removed along with any contaminated soil and taken to an approved landfill. The Town of Hayward landfill is closest, but you must have their permission. You have three choices if you wish to raze the remainder of the structure and foundation. Disposal in an approved landfill (Town of Hayward, with their permission), or obtain a one-time disposal permit for a location off the property. No permit is necessary if you dispose of demolition material on the property where it is generated. However, you must make sure the well is properly abandoned if you choose to use the existing basement excavation.

Contact Steve Palzkill in our Cumberland Area office (715/822-3590) if you need guidance toward obtaining a one-time disposal permit. Call me at 715/635-4057 if you have any questions.

Sincerely,

Thomas J. Kendzierski
Hydrogeologist

TJK:mj

cc: Steve Palzkill - Cumberland
Nadene Cable - Spooner

0389\HW8J0125.TJK

NORTHERN LAKE SERVICE, INC.
Analytical Laboratory and Environmental Consulting Service
400 N. Lake Avenue
Crandon, WI 54520

WIS. CERTIFICATION NO. 721026160

ANALYTICAL REPORT

05-11-89

SAMPLE NO: SEE BELOW
Page 1

Bruce West
Box 506
Hayward, WI 54843

SAMPLE DESCRIPTION: SEE BELOW

TAKEN RECEIVED
SEE BELOW 04-14-89 0915

91280	Sand - Before	12-12-88	
Solids, total on solids	95.8		% DWB
Tot. Petroleum Hydrocarbon	10000		mg/kg
91281	Sand - After	04-12-89	
Solids, total on solids	96.4		% DWB
Tot. Petroleum Hydrocarbon	<3.0		mg/kg

RECEIVED

JUN -6 1989

NORTHWEST DISTRICT
HEADQUARTERS

TOM HERMAN
LABORATORY DIRECTOR



ERP
54

12/12/89

PMN#: _____ FID#: _____
PROJECT MGR: TJK
SUPPORT PERSON: Nadene Cable
DISTRICT: NWD COUNTY: 58 HNDI: _____

SITE NAME: West Hayward Dairy
ADDRESS: 124 W 2nd str
Hayward CA TN CITY_VIL
LEGAL DESC: 1/4 1/4 SEC T R E/W

DATE OF INITIAL CONTACT: 11/26/89 (mo day yr)
DATE OF RP LETTER: 2/7/89 (mo day yr)
DATE SITE CLOSURE APPROVED: / / (mo day yr)

LUST TRUST ELIGIBLE: (X)
 1 = FEDERAL
 2 = NON-FEDERAL
STATUS: (X)
 1 = STATE LEAD
 2 = RP LEAD

PRIORITY SCREENING: (X)
 1 = HIGH SCORE: _____
 2 = MEDIUM
 3 = LOW
 4 = UNKNOWN
(see worksheet on back)

FUNDING SOURCE: (X)
 1 = RESPONSIBLE PARTY
 2 = LUST TRUST FUND
 3 = ENVIRONMENTAL RESPONSE FUND
 4 = SUPER FUND
 5 = NONE
 6 = OTHER _____

(X AS APPROPRIATE)	DATE INITIATED (MO DAY YR)	DATE COMPLETED (MO DAY YR)	COMMENTS:
<input type="checkbox"/> NO ACTION TAKEN	___/___/___	___/___/___	_____
<input type="checkbox"/> EMERGENCY	___/___/___	___/___/___	_____
<input type="checkbox"/> EMERGENCY RESPONSE	___/___/___	___/___/___	_____
<input type="checkbox"/> FIELD INVESTIGATION	___/___/___	___/___/___	_____
<input checked="" type="checkbox"/> REMEDIAL ACTION	<u>1/26/89</u>	___/___/___	<u>well in basement near leak was purged</u>
<input checked="" type="checkbox"/> LONG TERM MONITORING	<u>1/26/89</u>	___/___/___	_____

FIRM OR PERSON RESPONSIBLE: West's Hayward Dairy
CONTACT: Bruce West
ADDRESS: 809 Johnson PoBox 506
Hayward WI 54843
PHONE: 715 1634-2244
(list additional on separate list & attach)

CONSULTANT: _____
CONTACT: _____
ADDRESS: _____
PHONE: / /
AMOUNT COMMITTED: \$ _____ AMOUNT SPENT: \$ _____
(list additional on separate list & attach)

PECFA REVIEW REQUESTED: (X) YES NO

DATE PECFA REQUEST RECEIVED: (mo day yr) / /

	KNOWN IMPACTS: (X)	POTENTIAL IMPACTS: (X)
FIRE/EXPLOSION THREAT	___	___
CONTAMINATED PRIVATE WELL	<input checked="" type="checkbox"/>	___
CONTAMINATED PUBLIC WELL	___	___
GROUNDWATER CONTAMINATION	___	___
SOIL CONTAMINATION	<input checked="" type="checkbox"/>	___
OTHER: _____	___	___

SUBSTANCES: (X)	QUANTITY DISCHARGED: (gals)
<input type="checkbox"/> LEADED GAS	___
<input type="checkbox"/> UNLEADED GAS	___
<input type="checkbox"/> DIESEL	___
<input checked="" type="checkbox"/> FUEL OIL	<u>265</u>
<input type="checkbox"/> UNKNOWN HYDROCARBONS	___
<input type="checkbox"/> OTHER	___

ENFORCEMENT ACTION TAKEN
01=INF. CONTACT, RESP INITIATED 06=INSPECTION LETTER 14=NOTICE OF VIOLATION 23=REFERRAL TO DOJ
02=RP LETTER, RESP INITIATED 07=RESPONSE RECEIVED 18=ADMIN. ORDER FINAL 25=REFERRAL TO EPA
03=NTC OF NON COMPLIANCE 11=CLOSE OUT 20=ADMIN. ORDER CANCELLED 99=OTHER ACTION: _____

ACTION (code from above)	DATE (mo/day/yr)	COMMENT:
<u>2</u>	<u>2/7/89</u>	<u>Correspondence advising RP of spill stats & well abandonment</u>
<u>7</u>	<u>6/16/89</u>	<u>request from RP for statement from DNR clearing soil & water of contamination</u>
___	___/___/___	_____
___	___/___/___	_____

(for additional action codes see instructions/list additional on separate list and attach)

OVER ALL CASE COMMENT: _____

LUST CASE PRIORITY SCREENING WORKSHEET

HIGH FACTORS: (DEFINITION: Any case which presents an actual threat to human health, or has a high potential of causing a threat to human health and property; and/or any case which has caused or has a high potential of causing substantial impacts to the soil waters and air of the State of Wisconsin)

- | | |
|---|--|
| <input type="checkbox"/> Contaminated private or public well >NR140 enf. std. | <input type="checkbox"/> Floating product (medium if no receptors within 1 mile) |
| <input type="checkbox"/> Explosive or toxic vapors in structures | <input type="checkbox"/> Known gw contamination (private or public well <140 enf. std.) |
| <input type="checkbox"/> Threat of fire | <input type="checkbox"/> Impacted surface water--wetland, trout stream, etc. impacted saturated soil contamination |

MEDIUM FACTORS: (DEFINITION: Any case which does not appear to be an immediate threat to human health or vital natural resources but which shows levels of contamination that may cause substantial environmental impacts if left unaddressed.)

- Moderate soil contamination with moderate potential for impacting groundwater.
- Impacted surface water--no critical habitat threats.

LOW FACTORS: (DEFINITION: Any case where contamination has been documented, but which presents limited potential for any immediate threat to human health and vital natural resources.)

- Soil contamination which appears to have a limited potential for impacting groundwater.
- Initial remedial action has substantially reduced environmental threat.

UNKNOWN FACTOR: (DEFINITION: Any case where some indication of contamination is present, but due to incomplete or inaccurate information the level of threat to human health or the environment can not be assessed at this time.)

- Inadequate information to assign a high, medium, or low ranking.

OVERALL RANKING: The screening rank for the site along with the date of ranking. This may be updated when additional information is received. Special circumstances for a particular case may be taken into account in the comment section. The District LUST coordinator may independently set the ranking of a site based upon "special circumstances."

Circle one & date, indicate in priority screening box opposite side HIGH MEDIUM 11/30/88 (LOW) UNKNOWN

COMMENT: _____

NUMERICAL LUST SCORING WORKSHEET (complete for LUST cases ranked HIGH)

1. **GROUNDWATER & SOILS:** (circle one)

POINTS	Documented Petroleum Contamination:	POINTS	
20	Municipal well	8	Soil & gw within 1200' of a public well
18	>6 private wells	6	Soil & gw within 1200' of one or more private wells
16	4 - 6 private wells	4	GW contamination, no wells within 1200'
14	2 - 3 private wells	2	Soil contamination
12	1 private well		

2. **EXPLOSIVE OR TOXIC VAPORS:** (circle one)

POINTS	CONFIRMED	POTENTIAL	
20	10	10	Explosive levels in a residence or building
16	8	8	Explosive levels in a sewer or structure
12	6	6	Toxic levels in a residence or building

Note: Explosive levels determined to be >20% LEL as per an explosivity meter; toxicity levels are based on OSHA permissible exposure limits (PEL)

3. **HYDROGEOLOGIC SETTING:** (circle one)

POINTS	
12	Highly permeable sub-soils (gravel, well sorted sand, fractured bedrock or utilities capable of intercepting and directing flow) <u>and</u> groundwater within 25 feet of the ground surface.
10	Highly permeable sub-soils <u>and</u> groundwater more than 25 feet below ground surface.
8	Moderately permeable sub-soils (silty sands, silty gravel, clayey sands) <u>and</u> groundwater within 25 feet of ground surface
6	Moderately permeable sub-soils <u>and</u> groundwater greater than 25 feet below ground surface.
4	Low permeability sub-soils (silt, clayey silt, sand clays) <u>and</u> groundwater within 25 feet of ground surface.
2	Low permeability sub-soils <u>and</u> groundwater greater than 25 feet below ground surface.

4. **TYPE OF PRODUCT:** (circle one)

POINTS	NOTE: Add 4 points if free product is present. (score in parentheses)
8 (12)	Gasoline, mixture of gasoline and other products, other light petroleum products.
6 (10)	Diesel, fuel oil
2 (6)	Bunker oil, other heavy oils or crude fractions

_____ TOTAL SCORE (indicate score in priority screening box on opposite side)

LIST ADDITIONAL RESPONSIBLE PARTY NAMES HERE

FIRM OR PERSON RESPONSIBLE: _____ FIRM OR PERSON RESPONSIBLE: _____

CONTACT: _____

CONTACT: _____

ADDRESS: _____

ADDRESS: _____

PHONE: ____/____/_____

PHONE: ____/____/_____

LIST ADDITIONAL CONSULTANTS HERE:

CONSULTANT: _____

CONSULTANT: _____

CONTACT: _____

CONTACT: _____

ADDRESS: _____

ADDRESS: _____

PHONE: ____/____/_____

PHONE: ____/____/_____

AMOUNT COMMITTED: \$ ____ . ____ AMOUNT SPENT: \$ ____ . ____

AMOUNT COMMITTED: \$ ____ . ____ AMOUNT SPENT: \$ ____ . ____

LIST ADDITIONAL ENFORCEMENT ACTIONS HERE:

ACTION CODE

DATE
(mo/day/yr)

COMMENT:

ACTION CODE	DATE (mo/day/yr)	COMMENT:
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____
___	___/___/___	_____

ADDITIONAL CASE COMMENTS: _____

