

State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Jim Doyle, Governor
Scott Hassett, Secretary
Gloria L. McCutcheon, Regional Director

Plymouth Service Center
1155 Pilgrim Rd.
P.O. Box 408
Plymouth, Wisconsin 53073-0408
Telephone 920-892-8756
FAX 920-892-6638

April 22, 2005

Mike Gromacki
Cook Composites and Polymers
P.O. Box 419389
Kansas City, MO 64141-6000

Dear Mr. Gromacki:

Subject: Status of sites nearby Cook Composites and Polymers Co., Saukville, file reference FID #246004330 ERR-LUST.

Thank you for your inquiry regarding the status of sites nearby your facility. I am the contact person for all of the following cases and have the following summaries for you:

Saukville Feed Supply, BRRTS #0346174724

I gave this case a conditional closure in March of this year pending well abandonment. Eighteen petroleum tanks, mostly AST's were removed from the site in the 1980's. The site investigation consisted of 26 geoprobe borings, six monitoring wells, and a piezometer (the piezometer and one well are yours). The site underwent monitored natural attenuation. Monitoring wells on site had decreasing concentrations of BTEX concentrations until no Enforcement Standards were exceeded in the last rounds of monitoring. Soil sampling showed soil contamination was confined to this property. No chlorinated compounds showed up in groundwater samples run for full VOC analysis.

Logeman Brothers Ashpile/Incinerator Area, BRRTS #0246000762

I closed this case in 2001 after Georgia Gulf did source control by excavation followed by natural attenuation monitoring. Contaminants dropped below the enforcement standards.

Logeman Brothers Churchyard Area, no separate BRRTS #.

According to documents in our file RMT consultants wrote a remedial action report in 1996 for the remedial excavation that occurred on the church ball field. We do not have a copy in our Logeman files, but I will try to get one, and look into the status of this area.


Northern Signal BRRTS #0946535604

The US EPA did a site investigation there in 1988. For unknown reasons, action has not been taken at the site since that time, and the file was been lost until recently. I am planning to send the current owner, a family trust, a letter asking them to take action regarding the chlorinated solvent contamination that the EPA found on this property. Walt Ebersohl determined that I should handle this case.

↑
its in CA#16
FID#246004330

If you have any questions about any of these cases or others, please call me at 920-892-8756 extension 3023.

Sincerely,



John Feeney
Wisconsin Department of Natural Resources

Cc: SER File