Substance Release Notification Form Form 4400-91 (Rev. 12-01, e-form) Page 1 of 2 24-Hour Emergency Hotline Number: 1-800-943-0003

		mergency moun		
Date & Military Time Of Inciden	t: Date	& Military Time	Reported:	Spill File #
huknown		9/12/02	- mes sage	04-16-403133
Person Reporting:		Representing NR E	ng:	Phone # (218) 722 - 9554
Barry Power	<u> </u>			Fax # ()
Responsible Party (RP) / Spiller:			n Based On:	Phone # (715) 39 4-1413 Fax # ()
RP Address:	mpany	propers	yowner	City State Zip Code
2800 E. 21st St RP Contact Name & Title:				Phone # (715) 394-1410
RP Contact Name & Title:				Phone # (715) 394-1410 Fax # ()
Substance Involved:		Amount & Un	its Released:	Amount & Units Recovered:
Crude Oil		unkno	n w	
Solid Semisolid	Liquid	Gas	Color:	Odor:
Exact Location Of Incident: (incl	uding street nar	ne, bldg. #, mileag		Facility Name / Property Owner:
Superior Termina	1 - pipeli	inc entering	from Sw	Enbridge Energy
City Village Township	County		Latitud	e/Longitude
Superior	Done	las	4600	11,0309'N 92" 04.325'W Weather Conditions:
DNR Region:	SE 1/4 Alia	1/4 Sec 3 6 T 4	GN R/4 E	W Weather Conditions:
NOR	32 700			
Cause Of Incident:	7.2.7			
	-1.0 red	lace la Ga	. to . o . l	uring Terrace 3
Expansion	_	2016 21160	2014 -	
Spilled Substance Impact To:	Spill Cause/S	ite:		Action Taken By Spiller:
(check X all that apply)	Ag Coop/I			Cleanup Method:
Air Potential	Airport Fa	cility Railroad		Absorbent
Concrete/Asphalt Potential		on, Excavation, W		
Contained/Recovered		ce Station/Garage/	Auto Dealer/Repa	
Groundwater Potential Private Well Potential	Hydraulic Industrial	Facility Paper	Mill Chemical	
Sanitary Sewer Potential	Pipeline/T	erminal/Tank Farm	n/Oil Jobber/Who	lesaler Name:
Soil Potential		operty (home/farm		
Storm Sewer Potential		perty (city, state, o		
Surface Water Potential		ation Accident, Fu		No Action Needed
Name:		ation Accident, Lo		Waste Destination: 1; m bealine
Other:	Other:	. Tower denotating	g Transfer Facility	()ther:
Injuries? Yes No If yes how		Has An Evacu	ation Occurred?	L rail
Are There Any Resource Damage		No Potent		
Other Agencies Notified: (check	7			
Fire Department	Local D		EPA	meident communici.
Local Law Enforcement		nerg. Mgt.		r 800-442-8802
LEPC or Local Emer. Mgt.	Coast G		Chemtrec 800	
Level A/Level B Team		08-258-0099	Other:	Phone # ()
Prepared By: Norman Danbar		Phone # 15-365 -89	Date: 91/2	Rpt'd To DATCP? Yes No
Person Notified:		Phone #	Date;	Time:
Norman Ounbar		715-365-89		
Investigated By:	1	Sign: Journey Dun ba	Date:	Incident Closed? Yes No Date: 4/26/02
Spill Coordinator Signoff:	(1	Date:	Transferred T	1 2010
			DATCP D	
Norman Dun ban	1.1	20/02	Case #	To:
	1			See Additional Comments On Reverse
				Please, print page 2 of 2

November 12, 2002

Norm Dunbar Wisconsin Department of Natural Resources 107 Sutliff Avenue Rhinelander, WI 54501

RE: Enbridge Energy Partners

Discovery of Impacted Soil along the Terrace III Construction Route

September 11, 2002

Dear Mr. Dunbar,

This letter serves to document the environmental activities conducted in response to discovery of impacted soil from a historic release near Enbridge Energy Partners' (Enbridge's) Superior Terminal in Superior, Wisconsin (hereon referred to as "Site.") The location of the Site is shown on Figure 1. GPS coordinates for the area of the release are also included on Figure 1.

Setting:

Near surface geology at the Site consists of over 300 feet of red, plastic, fat clay with a USCS designator of CL. Surface drainage from the Site is to the east-southeast, ultimately discharging to the Nemadji River, a low energy river that flows north to Superior Bay. The slope across the Site is generally less than 0.5%, but steepens to over 15% along the Nemadji River valley. Depth to groundwater across the Site varies from a minimum of approximately 6 feet to over 15 feet below grade in response to topographic and piezometric relief across the Site. The Nemadji River located approximately ¼-mile east of the release location, is the closest surface water and groundwater receptor. There are no known drinking water supply wells located within 1,200 feet of the Site.

Remedial Actions:

While excavating a trench for Enbridge's Terrace III expansion project, impacted soil from a historic release was discovered. The crude oil stained soil was encountered from nearly one foot to three feet below grade. Seven soil samples for headspace screening were collected from the base and sidewalls of the trench (See Figure 2). Headspace concentrations are summarized on Table 1. The prefix SW- indicates a sample collected from the trench sidewall while the prefix B- indicates a sample collected from the base of the trench. Approximately 55 tons of impacted soil were

Natural Resources Engineering Company

Page 2 November 12, 2002

removed from the excavation and hauled off-site for disposal at Waste Management's Timberline Trail Landfill in Weyerhaeuser, Wisconsin on September 12th.

Fifteen hand-augured boreholes were subsequently advanced on the north and south sides of the trench to define the lateral extent of impacted soil. Samples for headspace screening were collected from the impacted soil in the boring, or in cases where impacted soil was not discovered, from the bottom of the boring. Headspace screening results for the hand auger borings are summarized in Table 2.

Following placement of the new pipeline and removal of the timber mat road, impacted soil on the north side of the trench was removed and hauled off-site for disposal. Soil was excavated based on the presence of visual staining. Approximately 33 tons of impacted soil were scraped from the area beneath the timber mat road to the south of the trench on October 7th and disposed of at Waste Management's Timberline Trail Landfill in Weyerhaeuser, Wisconsin. The disposal records are attached with this letter. Due to the presence of an existing pipeline to the north of the trench, impacted soil could not be excavated from that area.

Based on the extent of the impacted soil as defined by the hand-augured borings, the remedial actions taken, and the setting of the site, we do not believe the soil left in place poses a significant risk to human health of the environment and are requesting closure of the site. Please call me if you have any comments or questions – I can be reached at (218) 722-9554.

Sincerely,

David J. Hodek, P.E. Environmental Engineer

c: Mark Sitek – Enbridge Energy Company

Scott Lounsbury - Enbridge Energy Company

Barry Power - NRE

bc: Law


Enclosures

Table 1: Excavation Headspace Screening Results Enbridge Energy Company - Terrace III Expansion

			Headspace
Location	Date	Depth (feet)	(ppm)
SWN-1	11-Sep-02	2	184.3
SWN-2	11-Sep-02	3	139.6
SWS-1	11-Sep-02	1	60.4
SWS-2	11-Sep-02	2	67.0
SWS-3	11-Sep-02	3	12.4
B-1	11-Sep-02	6	< 5.0
B-2	11-Sep-02	6	< 5.0

Table 2: Hand-Augured Boring Headspace Screening Results Enbridge Energy Company - Terrace III Expansion

		Depth	Headspace
Location	Date	(feet)	(ppm)
HA-1	13-Sep-02	2	< 5.0
HA-2	13-Sep-02	1	60.3
HA-3	13-Sep-02	1.5	< 5.0
HA-4	13-Sep-02	1.5	25.1
HA-5	13-Sep-02	1	16.3
HA-6	13-Sep-02	1.5	37.8
HA-7	13-Sep-02	2	< 5.0
HA-8	13-Sep-02	1.5	< 5.0
HA-9	13-Sep-02	1.0	< 5.0
HA-10	13-Sep-02	2.5	< 5.0
HA-11	18-Sep-02	2	43.4
HA-12	18-Sep-02	2.5	< 5.0
HA-13	18-Sep-02	2	72.1
HA-14	18-Sep-02	2.5	< 5.0
HA-15	18-Sep-02	2.5	< 5.0








Figure 2: Site Map

20 30

DATE ISSUED: 11/6/2002

DATE REVISED: 11/06/2002

SCALE: 1:60

DRAWN BY: Alina K. Mustonen, E.I.T. gineering Co.

SERIES: Terrace III - Superior Terminal

40 ■ Feet

INVOICE

ACCOUNT NUMBER
300-0000346-2274-6
INVOICE NUMBER
0001729-2274-2
DATE
11/01/2002


LAKEHEAD PIPELINE-HANS

(Continued from previous page)

PAYMENT DUE UPON RECEIPT OF THIS INVOICE PLEASE CONTACT WASTE MANAGEMENT WITH ANY QUESTION

TICKET	DESCRIPTION	QUANTITY	RATE	AMOUNT
Ticket 753691	Description VEH#	Quantity	Rate	Extended
	WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total	16:38 TON 16:38 TON	15:00	245.70 307.13
753799	10/07/2002 VEH#: CONTAMINATED SOIL	12.39 TON	15.00	185.85
753800	10/07/2002 VEH#: CONTAMINATED SOIL	8.45 TON	15.00	126.75
753801	10/07/2002 VEH#: CONTAMINATED SOIL	11.73 TON	15.00	175.95
753829	10/07/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total	20.26 TON 20.26 TON	3.75 15.00	75.98 303.90 379.88
753842	10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total	20.96 TON 20.96 TON	15:75 15:00	78.60 314.40 393.00
753846	10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total	11:49 TON	15:75 15:00	43.09 172.35 215.44
753847	10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total	17:89 TON 17:89 TON	15:75 15:00	67.09 268.35 335.44
753848	Description 10/05/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 10/07/2002 VEH#: CONTAMINATED SOIL 10/07/2002 VEH#: CONTAMINATED SOIL 10/07/2002 VEH#: CONTAMINATED SOIL 10/07/2002 VEH#: CONTAMINATED SOIL 10/07/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE	10:33 TON 10:33 TON	15:75 15:00	38.74 154.95 193.69
753851	10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total	19:55 TON	3:75 15:00	73.31 293.25 366.56
753852	10/08/2002 VEH#: WISCONSIN GENERATOR TAX/FEE	10.15 TON	3.75	38.06

(Canti-... 1



INVOICE

ACCOUNT NUMBER 300-0000346-2274-6 INVOICE NUMBER 0001645-2274-0

> DATE 10/01/2002

PAYMENT DUE UPON RECEIPT OF THIS INVOICE PLEASE CONTACT WASTE MANAGEMENT WITH ANY QUESTIONS

TICKET	DESCRIPTION	QUANTITY	RATE	AMOUNT
Ticket 751982	Description	Quantity	Rate	Extended
751983	CONTAMINATED SOIL	18.58 TON	15.00	278.70
751984	CONTAMINATED SOIL	18.43 TON	15.00	276.45
752049	CONTAMINATED SOIL	18.29 TON	15.00	274.35
; 752049 ; 752051	Description 09/12/2002 VEH#: CONTAMINATED SOIL 09/12/2002 VEH#: CONTAMINATED SOIL 09/12/2002 VEH#: CONTAMINATED SOIL 09/13/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 09/13/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 09/13/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 09/13/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 09/13/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 09/16/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 09/16/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 09/16/2002 VEH#: WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total 09/16/2002 VEH#: WISCONSIN GENERATOR TAX/FEE Ticket Total 09/16/2002 VEH#: WISCONSIN GENERATOR TAX/FEE	17.57 TON 17.57 TON	3.75 15.00	65.89 263.55 329.44
752052	WÍŚCOŃŚIN GENERÄTOR TAX/FEE NON HAZ SOLID WASTE Ticket Total	20:18 TON 20:18 TON	15.00	75.68 302.70 378.38
752056	WISCONSIN GENERÄTOR TAX/FEE NON HAZ SOLID WASTE Ticket Total	17:83 TON	$\frac{3.75}{15.00}$	66.86 267.45 334.31
752117	WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total	23.00 TON 23:00 TON	3.75 15.00	86.25 345.00 431.25
752116	WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE TASKet Total	22.86 TON 22.86 TON	15.75 15.00	85.73 342.90 428.63
, 752197	WISCONSIN GENERATOR TAX/FEE WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE	19:11 TON	3.75 15.00	71.66 286.65 358.31
752198	WISCONSIN GENERATOR TAX/FEE NON HAZ SOLID WASTE Ticket Total	19:27 TON 19:27 TON	3.75 15.00	72.26 289.05 361.31
752201	WISCONSIN GENERATOR TAX/FEE	21.54 TON	3.75	80.78

(Continued on next page)

SE RETURN THIS PORTION WITH PAYMENT - DO NOT ATTACH CHECK TO STUB IF PAYING BY MASTERCARD, VISA OR AMERICAN EXPRESS, FILL OUT BELCA

CHECK CARD USING FOR PAYMENT