State of Wisconsin Department of Natural Resources PO Box 7921, Madison WI 53707-7921 dnr.wi.gov BRRTS ID No. 02-45-552083

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 11/13) Page 1 of 5

Page 1 of 5

Reviev	ver: Jennife	er Borski			Review Date: 08			3/19/2014		
Site Na	me:Tierne	ys Clean	ers		Region:NE					
				net.dnr.state.wi.us/ii	nt/aw/rr/gu	idance/RR52	42.pdf . Steps v	vith an *d	lenote DNR	
follow u	p;		•		_					
		erty ow	ner follow up.	If auditing a VPLE	site, use th	e applicable	LUST or ERP B	RRTS nu	ımber.	
File Rev		and DDD	TS, identify th	o fellowing:						
		allu DKK		ie following.	lo:h.			lotata l	710.0-4-	
Address					1 1	City State ZIP Cod				
	Wisconsi		Number (DINI)	TEID Mumb on	Appleto	Appleton WI 54914 Current Property Owner				
•		uncation	Number (PIN)	FID Number	, · · · ·					
315023'	/01 Responsib	lo Doroca			John & Janet Kennedy					
-	•									
John Jr	& Nancy A	Abraham								
Has the	property be	en trans	ferred since the	e restriction was reco	rded/condi	tion applied?	Yes	○ No		
How was	site selec	ted for au	ıdit? (AC = BRF	RTS Action Code)						
	r Mitigation		-	Green Space Grant	AC 605	ПΔ	ge of Remedy			
	with AC 5			AC 220, 222, 224, 22			complaint Receiv	hav		
_	cement Fo			Deed Restriction AC			Regional Priority	/cu		
Other		now-up	<u>.</u> .	beca restrotion Ao	02 01 000 1	(100)	cegional i nomy			
Oute of:				****						
Final	Closure		12/14	5/2009	Pemedial A	Action Plan Ap	proval			
	icate of Co	mplotion				ability Clarificat				
	n Space Gi	•				: Unit (LGU) Le				
	•		no applied (at a	ا الــا ase closure or RAP ap:		` '				
Select a	Action	Tobligatio	нь аррней (ат са	ase closule of MAF ap	proval of le	etter to LGO).				
Add to BRRTS	Code (AC) in BRRTS	AC	·		A	C Meaning				
	Bracio	51	Deed notice			• • • • • • • • • • • • • • • • • • • •				
		52	Deed restriction	on for soil						
		730	Groundwater ι	use restriction					·	
		95		ent conditions met (fo	or audits, u	se if deed resti	riction was upda	ted by filii	ng a deed	
		101	GIS Registry PDF modified - date DNR letter sent							
-		104	Site removed from GIS Registry - date DNR letter sent							
		696	Continuing obligation required of LGU to maintain liability exemption							
		605		Grant awarded (deed						
	X	56	1	oligation applied (use		<u> </u>				
		220	Soil at industri							
	X	222		ered containment sys	tem (pavei	ment, soil cove	er, etc.)			
		224		ediment (buildings or			(
		226	Vapor mitigatio			,				
		228		identify in comment fi	eld)					
		230		cted to take a protect				bar		
	X	232		contamination > RCL		(use with AC	222, 224)	***************************************		
		234		ll needs to be abando						
		236	Site closed wit	th groundwater conta	mination >	ES				

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 11/13) Page 2 of 5

Page 2 of 5

Add to BRRTS	Action Code (AC) in BRRTS	AC	AC Meaning
		238	Maintenance and inspection documentation required to be submitted
X	1	185	Closure Compliance Review completed
X		186	Closure Compliance Review - RP follow up needed
		187	Closure Compliance Review follow up completed
		99	use this code with comments, for actions not listed under AC 186
Describe	e anv site-s	pecific re	outrements that the site owner and/or responsible party needed to address:

BRRTS Number: 02-45-552083

Is the site on the GIS Registry? No - Add it to the GIS Registry*
Were neighboring properties affected? Yes No
If yes, are these properties listed on the GIS Registry and in BRRTS? Yes No - Update the GIS Registry/BRRTS, use form 4400-246*
Was a maintenance plan required at closure? Yes No NA
● Is it in the file ○ or PDF ○ or missing? If no maintenance plan was required, offer the property owner the template model with inspection log, and note in the follow up section of the audit that one was provided on the audit date
Was/were the appropriate restriction(s) recorded with the Register of Deeds?
Has a restriction been amended, or been nullified by DNR?
If yes, was BRRTS updated? (95) Yes O No*
Was the GIS Registry PDF updated?
Site Visit:
2. Contact the site owner for access.
3. Walk the site (ideally with the owner or responsible party) to review the site conditions against the conditions documented at closure/other to verify or change answers to questions in #1.
4. With the site owner/RP (if possible), answer the following for DNR RR records:
Did the site owner know about the continuing obligation(s)?
Have site conditions changed since closure that would affect either a deed restriction or other restrictions Yes or requirements associated with the site? If yes, explain:
Examples: 1)a building has been razed and investigation and remediation occurred. 2.)excavation or residential development has occurred in a restricted area.
Has a pavement (asphalt or concrete) cover, soil cover or other sort of cover, such as a building, been removed or is it in disrepair?
Should it be replaced or repaired? Yes No
If a performance standard was the final remedy, has it been altered? O Yes No If yes, explain:
If yes, was the DNR notified?

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 11/13) Page 3 of 5

Page 3 of 5

Have local zoning changes occurred since closure? Yes No/NA
If yes, does it appear to impact the effectiveness of the restriction? Yes No If yes, describe:
Is soil sampling needed to determine if the final remedy has been modified such that a direct contact threat exists? Yes No If yes, describe:
For example, an asphalt cover has been removed or is in disrepair, or a new contaminated site is present upgradient, etc.
Has additional monitoring or remediation been done since the site was closed? Yes No If yes, describe:
Does a new threat to public health or the environment exist (e.g. new sources or exposure routes)?
If yes, does sampling need to be performed?
Is the vapor mitigation system or sub-slab depressurization system (SSDS) operating as designed? (pressure gradient being maintained) If no, describe any follow up needed.
Have any of the exposure assumptions used for closure changed at this site? Yes No NA If yes, describe any follow up needed.
Has the land use at this site changed such that a vapor intrusion pathway may now exist? • Yes • No If yes, describe any follow up needed. Active dry cleaner (1109) has occupied residence (R) above it (1109-1/2). DC interconnected to occupied business (1107) with occupied R above it (1107-1/2) and residual soil contamination beneath the business. 1107/1109 interconnected with adjacent currently vacant building (1101) with occupied R above it (1101-1/2). No VI SI performed.
COMPLIANCE AND FOLLOW-UP: 5. Identify compliance and any follow up needed. Is the site in compliance with the continuing obligations/closure approval document? Yes No If no, describe what's not in compliance and the reasons for noncompliance: Property owner has not performed annual cap inspections since closure on 12/15/2009.

BRRTS Number: 02-45-552083

May depend on extent of non-compliance, non-maintenance of remedy or changed ownership or conditions. If case is out of compliance, it should be prioritized by the region, for new casework or enforcement, as needed.

Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 11/13) Page 4 of 5 BRRTS Number: 02-45-552083 Has the maintenance agreement required at closure been followed? () Yes No \bigcirc NA If no. describe: No annual inspections performed. 6. **Are additional actions by the RP property owner warranted at the site? The intent is to return Yes () No the site to compliance with continuing obligation. If further remedial action is needed, determine if the site meets the NR 726 reopening criteria.) If yes, describe any actions needed to return the site to compliance and identify who is responsible: Perform initial cap inspection and develop schedule for subsequent annual inspections. Add AC 186, use AC 99 for actions not listed under AC 186. 7. *Does the site require follow up by DNR?

Yes

No contact or enforcement to return site to compliance with continuing obligation updating the GIS Registry (adding or modifying a packet) reopen site (add ACs 186 and 13) other:

- 8. *Attach photographs of the site, documenting site conditions. Label the photos with the site name/BRRTS Activity number/date/view. If a follow-up letter is sent, include a copy with the audit. (audit/photos/follow-up letter)
- 9. *Save a copy of the audit using the following naming convention: BRRTS#_COAUDIT_Year.pdf (example: 0365001149_COAUDIT_2008.pdf).
- 10. Update applicable BRRTS action codes on the Table on page 1. Send a copy of the audit to your Regional EPA for updating ACs and uploading the PDF into BRRTS.
- 11. *Add a PDF copy of this audit to the case file. Send a copy electronically (PDF) to Central Office.

BRRTS Number: 02-45-552083

{Click to Add/Edit Image} Date added: 08/19/2014



Title: SE corner of active DC above residual soil contamination at 1109

Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 11/13)

Page 5 of 5

