

STATE OF WISCONSIN
DEPARTMENT OF NATURAL RESOURCESSTATE DIV. EMERGENCY GOVT. 608/266-3232
U.S. NAT'L. RESPONSE CENTER 800/424-8802
CHEMTREC/PESTICIDES/CHLORINE 800/424-9300TOXIC AND HAZARDOUS
INCIDENT REPORT
FORM 3200-49 REV. 7-79

DATE OF INCIDENT about 7/9/84	DAY OF WEEK ?	TIME OF INCIDENT ? ☐ AM ☐ PM	REPORTED BY (NAME) Jim Polzin	TELEPHONE NUMBER 414 1 887-8137
DATE REPORTED 8/6/84	DAY OF WEEK Monday	TIME REPORTED ? ☐ AM ☐ PM	AGENCY OR FIRM REPORTING Malleable Iron Range Co	REPORTED THRU DIV. EMERGEN. GOVT. ☐ YES ☒ NO
SUBSTANCE INVOLVED PCB oil	QUANTITY 55 gals	UNITS barrel	PERSON OR FIRM RESPONSIBLE Jim Polzin/Malleable Iron Range Co	
SUBSTANCE INVOLVED IOC oil	QUANTITY few gals	UNITS barrel	CONTACT NAME Jim Polzin	TELEPHONE NUMBER 414/887-8137
PHYSICAL CHARACTERISTICS ☐ SOLID ☒ LIQUID COLOR <u>unk</u> ☐ SEMISOLID ☐ GAS ODOR <u>unk</u>			ADDRESS - STREET OR ROUTE 715 N Spring St	
CAUSE OF INCIDENT Moving barrel caused interruption			CITY, STATE, ZIP CODE Beaver Dam, WI 53916	
☐ TRANSP. RELATED ☒ FACILITY RELATED ☐ SPCC PLAN ☐ YES ☐ NO ☐ NA			ACTION TAKEN BY SPILLER ☐ NO ACTION ☐ NO NOTIFICATION ☒ DELAYED NOTIFICATION ☒ TAKEN ☐ CONTAINMENT; TYPE <u>tarp</u> ☒ CLEANUP; METHOD <u>remove soil</u> ☒ DISPOSAL; LOCATION <u>approved PCB disposal site</u> ☒ FIRE DEPARTMENT ACTION <u>NONE</u> ☐ CONTRACTOR HIRED; NAME ☐ OTHER ACTION	
EXACT LOCATION DESCRIPTION (INTERSECTION, MILEAGE, ETC.) SE corner of Jackson & Prairie St - BD				
COUNTY LOCATION Dodge	1/4, 1/4, SECTION, TOWN, RANGE 33 T 12 N, R 14 E			
DNR DISTRICT SD	DNR AREA Horicon	SURFACE WATERS AFFECTED ☐ YES ☐ NO ☒ POT	DRAIN. BASIN Beaver Dam	
NAME OF SURFACE WATER Beaver Dam Lake	NEAREST SURF. WATER 1200 FT.	NEAREST STORM SEWER 50 FT.	WEATHER CONDITIONS	
GROUNDWATERS AFFECTED ☐ YES ☐ NO ☒ POT	NEAREST WELL ☒ PRIV. ☐ MUNIC. <u>on-site well</u> FT.	TEMPERATURE <u>85</u> °F		
DATE DISTRICT NOTIFIED 8/6/84	DAY OF WEEK Monday	TIME DISTRICT NOTIFIED ? ☐ AM ☐ PM	WIND SPEED _____ MPH DIRECTION OF WIND _____	
DATE INVESTIGATED 8/7/84	DAY OF WEEK Tuesday	TIME INVESTIGATED 12:00 ☐ AM ☒ PM	PRECIPITATION: ☒ YES <u>Tues PM</u> ☐ NO	
ACTION TAKEN BY DNR ☐ NO ACTION ☒ INVESTIGATION ☐ 29.29 ENFORCEMENT ☐ TAKEN ☐ CONTAINMENT; TYPE ☐ CLEANUP; METHOD ☐ SUPERVISE CLEANUP (PERSON) ☐ DISPOSAL; LOCATION ☒ SPILLER REQUIRED TO TAKE ACTION; TYPE <u>remove soil (tarp area to secure)</u> ☐ CONTRACTOR HIRED BY DNR; NAME ☐ DNR SPILL EXPENSE SENT TO MADISON CENTRAL OFFICE. ☐ EVIDENCE COLLECTED: ☐ PHOTOGRAPHS ☒ STATEMENTS OF WITNESSES ☐ SAMPLES ☐ OTHER			DIRECTION OF SPILL MOVEMENT _____	
OTHER AGENCIES ON SCENE			DISTRICT PERSON NOTIFIED Wendell Wojner	
LOCAL _____			TELEPHONE NUMBER 608/267-9427	
STATE _____			PERSON INVESTIGATING David Edwards	
FEDERAL _____			TELEPHONE NUMBER 414/485-4434	
ADDITIONAL COMMENTS: Malleable Iron Range Co collected samples after spill to determine if it contained PCB's. District Notified Horicon Area on 8/7/84. John Christian & myself interviewed Jim Polzin & inspected spill site same day. Soil will be analyzed as it is removed.			LIST HUMAN HAZARDS OR CASUALTIES ☐ REAL ☐ POTENTIAL ☒ NONE	
			ENVIRONMENTAL HAZARD/DAMAGE ☐ REAL ☒ POTENTIAL ☐ VEGETATION ☐ FISH ☐ WILDLIFE ☐ BIRDS ☐ OTHER <u>groundwater - surface water</u> ☐ NONE	
			COMMENTS: <u>closed 8-8-84</u>	
			PERSON FILING THIS REPORT (PRINT NAME) David S. Edwards	
			SIGNATURE <u>David S. Edwards</u> DATE SIGNED <u>8/8/84</u>	