

**State of Wisconsin - Department of Natural Resources
Substance Release Notification Report (SERTS)
Report created on 09/08/2009**

SPILL ID# 20090903NO16-1

Incident Date & Time: 09/03/2009 14:26	Reported Date & Time: 09/03/2009 16:20	BRRTS No: 04-16-554108	Spill ID: 20090903NO16-1
DATCP Reported? No DATCP Transferred? No	NFA Letter Sent? No	ERP Transferred? No	Incident Closed? Yes : 09/08/2009

Location			
Region: NO	County: Douglas	Municipality: SUPERIOR, CITY OF	
Facility/Property Name and Street Address: PLANT 2402 STINSON AVE, SUPERIOR		Description:	
Facility Type: Industrial Facility (Foundry/Factory/Plating/Manufacturing)			
Lat/Long:	PLSS:	WTM:	
Weather Conditions: Sunny, Hot			

Responsible Parties			
Name/Address (1): MURPHY OIL 2407 STINSON AVE SUPERIOR, WI 54880- (715) 398-8453 x Primary (218) 525-5848 x Secondary	Contact: MARK DARBY ENVIRONMENTAL ENGINEER (715) 398-8453 x primary (218) 525-5848 x secondary	Other Contact:	Spill Packet:

Cause
SHUTDOWN IN SULFUR RECOVERY PLANT, RELEASED FROM FLAIR

Cause Type: Equipment Failure

Substances						
Name	Other / Comments	Amt Released	Amt Recovered	Type	Color	Odor
Other	SULFUR DIOXIDE	1500.0 lb	0.0 lb	GAS		

Environmental Impacts / Damages			
Environmental Impacts: AIR	Resource Damages: No	Injuries: No	Evacuation: No

Cleanup Actions	
Method	Description

Cleanup Action Comments
NONE

Contractors Hired	
Name	Description

Waste Destinations	
Location	Description

Agencies Notified / On Scene		
Agency	Notified	On Scene
DNR	X	

Additional Comments

**State of Wisconsin - Department of Natural Resources
 Substance Release Notification Report (SERTS)
 Report created on 09/08/2009**

SPILL ID# 20090903NO16-1

WINDS WSW @ 5-10 MPH SAGER REFERRED TO THE WDNR AIR PROGRAM FOR FOLLOWUP.

Enforcement Action/Citation

Enforcement Action/Citation? No

Case Activity Reports:

Person Reporting

Name	Representing / Address	Primary Phone	Secondary Phone
MARK DARBY	MURPHY OIL	(715) 398-8453 x	(218) 525-5848 x

Contractors Hired

Name / Address	Zone Contractor Hired by DNR?
	No

Contacts

Role	Name	Office Phone	Date	Time
Prepared By:	JOHN SAGER	(715) 365-8959 x	09/03/2009	
Person Notified:	JOHN SAGER		09/03/2009	
Investigated By:			09/03/2009	
Incident Commander:				
Spill Coordinator:	JOHN SAGER, NO Region	(715) 365-8959 x	09/08/2009	

Electronic Attachments (list)

Name	Type

Sager, John E - DNR

From: Sager, John E - DNR
Sent: Friday, September 04, 2009 8:20 AM
To: Baudhuin, Neal E - DNR
Subject: Murphy Oil air release yesterday

Neal,

Murphy Oil had an air release yesterday. Below are the details. I will note in the spills database that I transferred this to the air program and close the spill.

-----Original Message-----

From: SERTS_SYSTEM@dnr.state.wi.us [mailto:SERTS_SYSTEM@dnr.state.wi.us]
Sent: Thursday, September 03, 2009 8:25 PM
To: Sager, John E - DNR
Subject: WI SPILL #4599 SERTS ID 20090903NO16-1 - OTHER : SULFUR DIOXIDE

The following Substance Release Notification was submitted through the Wisconsin DNR Spill Electronic Reporting and Tracking System (SERTS) web form:

SERTS Spill ID:
20090903NO16-1

Date/Time Reported:
09/03/2009 16:20

Person Reporting (PR):
MARK DARBY
MURPHY OIL
mark.darby@murphyoilcorp.com
(715) 398-8453
(218) 525-5848

Date/Time Occurred:
09/03/2009 14:26

Location:
NO REGION
DOUGLAS COUNTY
CITY OF SUPERIOR
PLANT
2402 STINSON AVE, SUPERIOR
INTO THE AIR

Responsible Party (RP):
MURPHY OIL
2407 STINSON AVE
SUPERIOR
WI
54880
(715) 398-8453
(218) 525-5848

RP Contact:
MARK DARBY
MURPHY OIL
ENVIRONMENTAL ENGINEER
(715) 398-8453
(218) 525-5848
mark.darby@murphyoilcorp.com

Substance:
OTHER

SULFUR DIOXIDE
Released Amt: 1500
Recovered Amt: 0
UOM: LB

Spill Cause:
SHUTDOWN IN SULFUR RECOVERY PLANT, RELEASED FROM FLAIR

Environmental Impact:
TO AIR

Weather:
HOT
SUNNY

Contractor Hired:
NONE ENTERED

Cleanup Method:
NONE

Additional Comments:
WINDS WSW @ 5-10 MPH

Notified JOHN SAGER at 16:35 by

This Email Also Sent To:
john.sager@wisconsin.gov

Form Completed by:
DENNIS GAWRONSKI
(608) 267-7450
dennis.gawronski@wisconsin.gov

The Immediate Responder should document their response by updating SERTS record 20090903NO16-1 with additional information.