## State of Wisconsin - Department of Natural Resources Substance Release Notification Report (SERTS) Report created on 03/04/2013

 	BRRTS No: 04-38-560147	Spill ID: 20130211NE38-1
 NFA Letter Sent? No		Incident Closed? Yes: 03/04/2013

DATCP Transferr		No No		No	isierreu :		Yes : 03/04/2	
				11:	·			
				ation			·	
Region: NE	County: Marinette		Municipa MARINE	ality: ETTE, CIT	Y OF			
Facility/Property	Name and Street Addres	s:	1	Descripti	on:			
	RINE SHIPYARD			DOCKSI				
Facility Type:	Industrial Facility (Fou	ndry/Factory/Platir	ng/Manufa	acturing)				
Lat/Long:		PLSS:				WTM: X 707718	3 Y 516744	
Weather Conditio	ns: Rain, Windy (	add to SDE	- U/A	load ole Partie	does-	MGS-	12-m	uch-2013
N (A d-l (4)		1	esponsi	Jie Fai lie			Cuill Dools	-4-
Name/Address (1) PRECISION ICE		Contact:	ARD .		Other Contac TOM ST. PE		Spill Pack	et:
801 MAPLE ST	DEAGI	DIR OF ENVIRO			FOREMAN	I LIX		
PESHTIGO, WI	54157-	HEALTH & SAFE		-	(715) 504-90	31 x primary		
(906) 864-2421 >		(906) 864-2421 x		arv	( , , , , , , , , , , , , , , , , , , ,			
(855) 423-2527 >			•					
			Car	use				
OIL BUILT UP IN	TROUG BELOW GE	VERATOR COMPI	RESSOR	PLUGE	ALLED AND O	II OVERELO	WED INTO	STORM DRAIN
	GED TO THE MENON			,	,			
*								
Causa Turas EAU	ED DDAIN DLUC ON	CENEDATOD	·	-				
Cause Type. FAII	LED DRAIN PLUG ON	GENERATUR	0.4-4					·
N		045		ances Released	Amt Recovered	Toma	Calan	0.4
	ime	Other / Comments				Type	Color	Odor
Engine Oil					0.0 Gal	LIQUID		
		Environr		ipacts / E				
Environmental Im			I .	e Damage	s:	Injuries:	· · ·	vacuation:
STORM SEWER			No			No	N	0
	ER - Name : MENOMI							
	TO OIL FELL INTO THE SIMOSTLY CONTAINE							
KIVEK BUT WA	S MOSTET CONTAINE	-U.,						
	Method		Cleanup	Actions		Description		
Boom	Method		MA	TS AND S	SOCKS	Description	•	
	y, sand, sawdust)	-						
Absorbent (on di	y, sanu, sawuust)	Class	A -45	Canan	van'r			
				on Comm				
	TROUGH BELOW GI							
	GES TO MENOMINEE							
WAKINETTEMA	RINE AND PLACED C	VIT ADOUGEN!	VIA 13, 3(	JUNO, AN	ID OIL DRY AT	DISCHARG	E LOCATIO	٧.
		•			•			
	<u> </u>		Continue	ove liber				<b></b>
			Contract	ors Hired				
	Name					Description		

04-38-560147

## State of Wisconsin - Department of Natural Resources Substance Release Notification Report (SERTS) Report created on 03/04/2013

***	Wast	e Destinations						
Location			Description					
HERITAGE-CRYSTAL CLEAN, LLC WASTE DISOPOSAL FACILITY								
		Notified / On Scene						
	Agency		Notifie	d	On Scene			
COAST GUARD			Х					
DNR			Х					
		onal Comments						
SUBMITTED VIA SERTS WEI	3 FORM REF # 6989.							
·					•			
,								
		•						
						•		
	Enforcem	ent Action/Citation						
Enforcement Action/Citation?	No							
•								
					•			
÷								
				* .				
Case Activity Reports:			,					
Case Activity Reports.	Pare	on Reporting	*					
Name	Representing / Address				econdary Phone			
SCOTT OKHUYSEN	MARINETTE MARNINE	·	(715) 735-9341 x 6069					
	CORPORATION	(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	( , , , , , , , , , , , , , , , , , , ,			(715) 587-8027 x		
	Cont	ractors Hired						
	Name / Address			Zone	Contractor Hire	ed by		
				No	DIAK			
		Contacts		INO				
Role	Name		Office F	hone	Date	Time		
Prepared By:	DAKOTA BERG		(608) 267	-0844 x	02/11/2013			
	I		` '					
reison Notified:	JASON LOWERY		(608) 267	-7570 x	02/11/2013			
Person Notified:	JASON LOWERY		(608) 267	-7570 x	02/11/2013			
Investigated By:	JASON LOWERY		(608) 267	-7570 x	02/11/2013			
	JASON LOWERY  ROXANNE CHRON, NE Regio		(608) 267 ERT (920)		<u> </u>			

Name

Туре

I spoke on the phone w/ Tom St. Peter from Precision Ice Blast at 11:30 on 3/4/13. He was the foreman that responded to the engine oil spill on 2/11/13. He said the spill occurred on land but the oil drained into a storm sewer which discharges to the Menominee River. The spill occurred because there was a buildup of oil and water in a trough below the air compressor. Then the plug that held the oil and water in place failed.

They borrowed oil socks, mats, and oil dry from Marinette Marine and placed them at the location where the storm drain discharges to the Menominee River. He said that the absorbent material was given back to Marinette Marine, who put it in a 55-gallon drum and disposed of it.

Since then they've built a secondary containment for the generator, replaced the drain plug, and moved the generator at least 10' away from the storm drain. They open the plug approximately 4x/day to make sure that oil/water doesn't build up.

I then called Scott Okhuysen from Marinette Marine. He said that there were 9 drums of absorbent material that were disposed of. He sent me the manifest.

Scott Okhuysen
EHS Coordinator
MARINETTE MARINE CORPORATION
a fincantieri company
Scott.Okhuysen@us.fincantieri.com

Phone: 715-735-9341 Ext. 6069


Cell: 715-587-8027 Fax: 715-735-0294

Jason B. Lowery
Spills Response Team Leader / Hydrogeologist
Remediation and Redevelopment Program
Wisconsin Department of Natural Resources
101 South Webster St., P.O. Box 7921
Madison, WI 53707-7921

phone: (608) 267-7570 e-mail: jason.lowery@wisconsin.gov

Spills Home Page: http://dnr.wi.gov/topic/spills/

## 20130211NE38-1 Precision Ice Blast



3000 ft.

Legend

County Boundary

ير Railroads County Roads (WDOT)

County Trunk Highway
State and U.S. Highways (WDOT)

State Trunk Highway

**US Highway** 

Interstate Highways (WDOT)

Interstate Highway

Local Roads (WDOT)

**Civil Towns** 

**Civil Town** 

24K Open Water

24K Rivers and Shorelines Municipalities

Map created on Mar 4, 2013

Note: Not all RR Sites have been geo-located yet.

This map is a user generated static output from an Internet mapping site and is for general reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable. THIS MAP IS NOT TO BE USED FOR NAVIGATION.

2000

1000

Notes: Spill Date: 2/11/13 Substance: Engine Oil Amount: 1 gallon



Scale: 1:10,614

HERITAGE-CRYSTAL CLEAN - BILL OF I AD	MAC	0) 2 CY6			•	
HCC Use Loc: GREEN BAY Doc #: 1879387	07-125-01	AY - ROUTE 1	NO #:		Page 1 (	
Shipper's Name And Mailing Address MARINETTE MARINE CORPORATION 1600 ELY STREET MARINETTE, WI 54143		u ti i printaningul ndendena. Vydilipu jiše obritim oblika ocu yen	कर्तानमञ्जूषात् स्वरंतः कृषण्यः स्वरंतः कृषण्यः स	Shipp WID(	per EPA 006135 per Stat	<u> 10</u> 5388
Generator Phone: (715)735-9341  Transporter 1 Company Name  HERITAGE-CRYSTAL CLEAN, LLC  Transporter 2 Company Name  LOCA / C  Transporter 3 Company Name	Transp 1 EPA Id I LR000130062 Transp 2 EPA Id ALDOLT/POST/ Transp 3 EPA Id	Transp 1 Stat  Transp 2 Stat  Transp 3 Stat	e Id	(647 Trans	5p 1 Pho )836-5 5p 2 Pho 5p 3 Pho	5570 one
Receiving Facility HERITAGE-CRYSTAL CLEAN, LLC. 1560 WEST RAYMOND ST INDIANAPOLIS, IN 46221	Facility EPA Id I L R 0 0 0 1 3 0 0 6 2 24Hr Emergency Phor 800-424-9300, "1"	Facility State	Id		ity Phor ) 489-5	
Shipping Description				ainer Type	Totai Qty	Unit Wt/vo
A UN3090, LITHIUM BATTERY, 9, PG II, (UNIVE	RSAL WASTE-BATTERII	ES) ERG# 138		1		
B NON-DOT/RCRA REGULATED, (FIRESEXTING	SWISHING AGENT) (8-1	n I solleds)	Ĺ	(F		4
( Non-Dot/Rich Regulated, (Non-	Haz Absorbent/Prb.	L1,44	9	pn	495	6
P Nun- Pot/ RERA Regulated, CALL	colina batterias)		3	DF	48	G
Special Handling Instructions, Additional Information  A) CC: 111522-10-12 TSD: 10-12 (1066) 5  B) CC: 111522-10 TSD: 01-036-05 (1014A)  B) LUS 22-3 12-015-04 LOL4  C) LUS 22-3 12-015-04 LOL4  GENERATOR'S This is to carrily that the above name of the control of	501 ) H141 (*3PFB), D.) W	1522-10-5			LOG (	ad ore in
Touber Deprendt	Kendon Bakes Signature	el.	<u></u>	19 Date	- 13	discontinuos discontinuos
Transporter 1 Asknowledgement of Reciept Materials  Printed/Typed Name	Mo CL L Signature	o construction of a construction of the constr	et in the second	44 Date	- 13	
Transporter 2 Acknowledgement of Reciept Materials  This has he will be the content of the conte	<u> Desartation</u>				-16.	117.
Printed/Typed Name  Transporter 3 Acknowledgement of Reciept Materials	Signature			Date		
Printed/Typed Name	Signature	. NOV on the desired printed grows in the self-state flowing flow in the self-state flowing grows and and self-state flowing grows and an extension of the self-state flowing grows and the self-state fl	e et en	Date	**************************************	voggjalikensifisessyl
Additional Description / Discrepancies  GENERATOR REQUESTS RETURN COPY	n an makambalajarphija dishi din dagari si ilin shapa na mahija man dishininsin di pasakan dagari sa Mahili	kana yanakan ana ata ma'i manadan mada kanina ka kanina ka kanina ka kanina ka kanina ka kanina ka kanina kani	de Alle Particular de Particular de Alle Particular de Alle Particular de Alle Particular de Alle Particular d	ektika.ikuga kilitaka yi <del>layo inin</del> anga g	. We want to the boson makes a constant	EZPERIORES PRO - OR - SAÇALANIA
Receiving Facility: Cartification of sereopt of waste mate	erials covered by this bill of lading			-2,	ko/1	<i>y</i>
Printed/Typed Name	Signature			Date		CONTRACTOR OF THE PROPERTY OF
				li M		