

**From:** [Alex Smith](#)  
**To:** [Sager, John E - DNR](#); [Endsley, Erin A - DNR](#)  
**Cc:** [Karl Beaster](#)  
**Subject:** RE: Superior Terminal release - Field Booster 25  
**Date:** Monday, September 15, 2014 11:54:51

---

John and Erin,

A brief update on the Field Booster 25 release at the Superior Terminal. Also residual product in the soil was been excavated. Ditches have been restored and riprap will be placed throughout to further reduce stormwater velocities. This should happen in the next week or so, since a project is coming through the same area. There is still a faint bathtub ring around the first containment pond that did not remove with either pressure or steam washing. I believe Operations is planning on excavating the stained sod. All contaminated soil and water has been disposed of at approved facilities. Finally, I will submit a technical memo along with a closure request shortly. Please let me know if you have any questions in the meantime.

Thanks,

**Alex Smith**

Environmental Analyst, LP US Environment Operations

**ENBRIDGE**

TEL: 715-398-4795 | FAX: 832-325-5511

1320 Grand Avenue, Superior, WI 54880

[www.enbridgeUS.com](http://www.enbridgeUS.com)

**Integrity. Safety. Respect.**

---

**From:** Sager, John E - DNR [<mailto:John.Sager@wisconsin.gov>]  
**Sent:** Monday, August 25, 2014 10:32 AM  
**To:** Karl Beaster  
**Subject:** RE: Superior Terminal release - Field Booster 25

Thank you Karl. Erin filled me in on the details from her visit. Please call me when you get a chance. No rush.

**We are committed to service excellence.**

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

**John Sager**

Phone: (715) 392-7822

[John.sager@wisconsin.gov](mailto:John.sager@wisconsin.gov)

---

**From:** Karl Beaster [<mailto:Karl.Beaster@enbridge.com>]  
**Sent:** Monday, August 18, 2014 11:35  
**To:** Sager, John E - DNR  
**Cc:** Endsley, Erin A - DNR  
**Subject:** Superior Terminal release - Field Booster 25

John,

If you haven't heard already, Enbridge experienced a release of crude oil at the Superior Terminal this morning. Current volume out reported is 105 gallons from Field Booster 25. I've attached a site map for your reference. We have implemented response actions and External Notification to the NRC has been completed #1092634. The oil migrated due to the heavy rains to a nearby containment pond. Sheen made it past the first pond to a secondary containment pond. Boom has been deployed on the Nemadji River as a precautionary measure but no trace of sheen has been observed on the river.

I'll give you a call to fill you in on the details.

Thanks,

Karl

**Karl F. Beaster, PG**

Sr. Environmental Analyst, LP Environment

**ENBRIDGE**

TEL: 715-398-4754 | CELL: 715-718-1040

1320 Grand Ave, Superior, WI 54880

[www.enbridgeUS.com](http://www.enbridgeUS.com)

Integrity. Safety. Respect.

---

\*\*\*\*\* IMPORTANT NOTICE\*\*\*\*\*

Unless otherwise indicated or obvious from the nature of the transmittal, the information contained in this email message is CONFIDENTIAL information intended for the use of the individual or entity named herein. If the reader of this message is not the intended recipient, or the employee or agent responsible to deliver it to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify the sender using the above contact information or by return email and delete this message and any copies from your computer system. Thank you.

---

\*\*\*\*\* IMPORTANT NOTICE\*\*\*\*\*

Unless otherwise indicated or obvious from the nature of the transmittal, the information contained in this email message is CONFIDENTIAL information intended for the use of the individual or entity named herein. If the reader of this message is not the intended recipient, or the employee or agent responsible to deliver it to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify the sender using the above contact information or by return email and delete this message and any copies from your computer system. Thank you.