

**State of Wisconsin - Department of Natural Resources
Substance Release Notification Report (SERTS)**

Incident Date & Time 08/20/2016 11:00		Reported Date & Time 08/20/2016 12:35		Activity Type Spill		BRRTS No. 04-42-578296		SPILL ID 20160820WC42-1	
Reported to DATCP? No		Transferred to DATCP? No		NFA Letter Sent? No		Transferred to ERP? No		Status Closed	
Location									
DNR Region WC		Mgmt Region WC		County Monroe		Municipality FORT MCCOY, UNINCORPORAT		Parcel No.	
Location Name TTB WARRENS DROP ZONE					Address TTB WARRENS DROP ZONE				
Location Description								Facility ID	
LocationType Military Installation (Base/Fort/Post)						PLSS Description			
WTM 469821 X 408460 Y			Latitude/Longitude 0 ' " 0 ' "						
Responsible Parties									

FORT MCCOY 608-388-5915/5705
2171 S 8TH AVE
FORT MCCOY WI 54656-513

Cause

Type
Equipment Failure
Other Cause

Cause Description
F24 FUEL

Substances

Substance	Quantity Released	Quantity Recovered	UOM	Physical Characteristic	Color	Odor	Substance Other
Jet Fuel [Petroleum]	8.00	8.00	Gallon	LIQUID			F-24

Environmental Impacts

Impact to	Other Desc	Surface Water Name
Soil Contamination		

Weather Conditions

CLOUDY

Resource Damages? **Resource Damage Type**
No

Resource Damage Comment
Injuries? **Injury Count** **Injury Comment**
No 0

Evacuation? **Evacuation Count** **Evacuation Comment**
No 0

Response

Enforcement Action? **Enforcement Type**

SPILL ID: 20160820WC42-1 BRRTS No: 04-42-578296

SPILL ID: 20160820WC42-1 BRRTS No: 04-42-578296

State of Wisconsin - Department of Natural Resources
Substance Release Notification Report (SERTS)

No

Enforcement Comment

Investigated by

TOM KENDZIERSKI

Date

Incident Commander

Date

Cleanup Actions

Excavation

Cleanup Comments

USED MACHINERY TO REMOVE THE CONTAMINATED SOIL. SEE THE REPORT IN THE SPILL FILE. - TK WCR RSC

Waste Destination

Other

ON-BASE SOIL STORAGE BUILDING

Person Reporting

Anonymous Violation RP Contact

SUSAN HERZOG-BLUMER

FORT MCCOY

CHIEF ENVIRONMENTAL COMPLIANCE

susan.r.herzogblummer.civ@mail.mil

(608) 388-7990

Comments

F24 FUEL

Closure

Regional Spill Coordinator	Docs Received On	Date Closed
Tom Kendzierski (715) 410-8842	08/25/2016	10/31/2016

Kendzierski, Thomas J - DNR

From: Williams, Jimmie B Jr CIV USARMY IMCOM CENTRAL (US)
<jimmie.b.williams2.civ@mail.mil>
Sent: Thursday, August 25, 2016 8:12 AM
To: Kendzierski, Thomas J - DNR
Cc: Herzog Blumer, Susan R CIV USARMY IMCOM (US); Bartholomew, Craig O CIV USARMY IMCOM CENTRAL (US); Hessil, James R CIV USARMY IMCOM CENTRAL (US)
Subject: Spill Report 623301 (UNCLASSIFIED)
Attachments: 623301 Report (Final).pdf

CLASSIFICATION: UNCLASSIFIED

Good morning,

Attached you will find the full spill report from a spill that occurred on August 20th, 2016. Please let me know if there are any questions, comments or concerns regarding this report and I will get back to you as soon as I can.

Thank you.

V/R

Jimmie B Williams Jr
Environmental Protection Assistant
Fort McCoy, Wisconsin 54656-5136
Office DSN: 280-5915/5705
Office Commercial: 608-388-5915/5705
[Jimmie.b.williams2.civ@mail.mil](mailto:jimmie.b.williams2.civ@mail.mil)

"Improvise, Adapt, Overcome"

CLASSIFICATION: UNCLASSIFIED

ENVIRONMENTAL COMPLIANCE BRANCH
2171 South 8th Avenue
Fort McCoy, WI 54656-5136

HAZARDOUS MATERIALS SPILL FORM

SUBJECT: F-24 Release

LOCATION: TTB Warrens Drop Zone

DATE of Release: 8/20/2016

X: 469821 Y: 408460

DATE of Reporting: 8/20/2016

INCIDENT #: 623301

HAZARDOUS MATERIALS: F-24

GALLONS RELEASED: Approx.: 7-10 Gallons

TIME OF INCIDENT: 0930

TIME OF REPORTING: 1030

CAUSE OF SPILL: HUMAN ERROR (TYPE OF ERROR):

EQUIPMENT FAILURE : (WHAT PART FAILED)

Seal Broke on fuel separator

VEHICLE SOURCE: (ECS, MATES, IMMA, TMP, OFF-POST, POV, ETC.) ECS

MOB-RELATED, AT, OR OTHER. _____

UNIT INVOLVED (IF APPLICABLE): 334th QM Company

SUPPLIES USED: Hand Shovels / Absorbent material

HOME ADDRESS: 20610 Arsenal Elwood, IL 60421

DODDAC #: N/A

TOTAL MAN-HOURS: 1

BRIEF DESCRIPTION OF INCIDENT:

On Saturday, 8/20/2016, fueling unit from the 334th QM Company were conducting fueling operations when a seal from the fuel separator broke off due to a mechanical failure. Approx. 7-10 Gallons of F-24 were released from the fuel tanker, unit initiated spill response procedures and notified range control of the spill. On Monday, 8/22/2016, environmental compliance personnel inspected the area of the F-24 release and recommended more excavating is required. Roads & Grounds excavated 20.9 tons (42,420 LBS) of contaminated soil and placed the soil in the licensed soil storage building. Photos, weight tickets and map indicating the location of the release are attached for review. Wisconsin DNR Emergency Spill Hotline was notified and briefed on this reportable spill.

(Use back if needed)

REPRESENTATIVE PERSON: Bernard Williams

TITLE: SSG

SIGNATURE: _____

RESPONSE PERSON: Jimmie Williams




Figure 1: Facing South




Figure 2: Hole getting back-filled

**SPILL LOCATION
20 AUGUST 2016
FORT MCCOY
623301**



0 0.1 0.2
Miles

SPILL
LOCATION



TTTLER TOLEDO

MFL

AUTHORIZED SIGNATURE

*Hazmat @ Warrens
Drop Zone*

FMT 1

5.15cy

FORM #083025020

FORT MC-COY
SPARTA WI. 54656
PHONE # 608-388-2726
PHONE # 608-388-3715

:04

08 23 16

34122

OSS

41320 1b

26720

14000

TTTLER TOLEDO

MFL

AUTHORIZED SIGNATURE

*Hazmat @ Warrens
Drop Zone*

FMT 3

FORM #083025020

FORT MC-COY
SPARTA WI. 54656
PHONE # 608-388-2726
PHONE # 608-388-3715

:48

08 23 16

34120

OSS

52400 1b

24580

27820

981 cu