Note: In order to fill and save this form electronically, it must be opened using Adobe Reader or Acrobat software. Save a copy of the file, open Adobe Reader, select File > Open and browse for the file you saved.

State of Wisconsin Department of Natural Resources PO Box 7921, Madison WI 53707-7921

BRRTS ID No. 02-13-583171

Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 07/22) Page 1 of 6

Reviewer:	Koepke			Regi	on: <u>SCR</u>	Review Date:	09/08/2023	
Site Name	e: Best Wa	ay Clean	ers					
follow up number. I	; ** denote Use the N	e RP/pro	s <u>http://intranet.dnr.s</u> perty owner follow u ea in each section to	p. If auditing a VI	PLE site, use the	applicable LUST or E		
File Revie								
	•	and the	file if needed, to ident	tify the File Revie				
Site Address					City ZIP Code			
5914 Highway 51					McFarland 53558			
County Parcel Identification Number (PIN)					FID Number			
154/0610-032-4510-1 Original Responsible Person								
ŭ	•				. D 1			
			Farland, Inc.; Steve Pe			- 0		
<u> </u>			erred since the continu	ing obligation was	recorded/applied	? ONo Yes		
	urrent Pro							
			vestments, Inc.; Moha		Registered Ager	nt		
Р	hone Num			Email				
0 1 1 1				oitstopm@yahoo.				
		obligatio	ns applied (at case clos	ure or RAP approv	al or letter to LGU):		
Add to BRRTS	AC in BRRTS	AC		Actio	on Code (AC) Me	aning		
		51	Deed notice					
		52	Deed restriction for soil					
		730	Groundwater use restric	ction				
		95	Deed instrument conditions met (for audits, use if deed restriction was updated by filing a deed notice)				ng a deed notice)	
		101	GIS Registry PDF modified - date DNR letter sent					
		104	Site removed from GIS Registry - date DNR letter sent					
	Ц	696	Continuing obligation required of LGU to maintain liability exemption					
		605	Green Space Grant awarded (deed restriction)					
		56	Continuing Obligation applied (use with codes 220-238)					
		46	Impacted Right-of-Way					
		220	Soil at industrial use level					
		222	Cover/engineered containment system (pavement, soil cover, etc.)					
	$oxed{\boxtimes}$	224 226	Structural impediment (buildings or other structures)					
		228	Vapor mitigation/response Site specific (identify in comment field)					
	$ \vdash$	230	Site-specific (identify in comment field) LGU was directed to take a protective action					
	\boxtimes	232	Residual soil contamination > RCLs/SS RCLs (use with AC 220, 222, 224)					
		234	Monitoring well needs to		(,,,		
		236	Site closed with ground		n > ES			
		238		Maintenance and inspection documentation required to be submitted				
		185	Closure Compliance Review completed					
\boxtimes		186	Closure Compliance Review - RP follow up needed					
	187 Closure Compliance Review follow up completed							
		99	Use this code with com	ments, for actions i	not listed under AC	186 (i.e. submittal of in	spection reports)	

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 07/22) Page 2 of 6 BRRTS Number: 02-13-583171

Page 2 of 6

Но	w was site selected for audit? (AC = BRRTS	Action Code)				
	☑ Vapor Mitigation AC 226	Green Space G	rant AC 605	☐ Age of Rem	Age of Remedy	
	☐ VPLE with AC 56 ☐ A	AC 220, 222, 22	24, 228, or 230	Complaint R	leceived	
	Enforcement Follow-up	Deed Restriction	n AC 52 or 696 (I	LGU) 🔲 Regional Pri	ority	
	Other:					
Da	te of:					
		2021	Remedial A	ction Plan Approval		
	Certificate of Completion		General Lial	bility Clarification Letter		
	Green Space Grant		Local Gov't	Unit (LGU) Letter		
De	scribe any site-specific requirements (AC 22	28) that the site	owner and/or res	sponsible party needed to	o address:	
No	t applicable					
ls t	he site on BRRTS as having residual contar	mination and co	entinuina obligatio	nns?		
	ine one on Brace as having residual contain	Yes	_		le action codes (56, etc.)*	
We	ere neighboring properties affected?	O Yes	No	o brave o doing applicable	10 4011011 00400 (00, 010.)	
	If yes, are these properties listed in BRRTS	S with AC 66?	○ Yes ○ N	0		
Wa	as a maintenance plan required at closure?	○ NA ○ No	● Yes – It is:	○ in the file ● PDF	○ missing	
	If no maintenance plan was required, offer up section of the audit that one was provide			e model with inspection lo	og, and note in the follow	
Wa	as/were the appropriate restriction(s) recorde	ed with the Reg	ister of Deeds?	○ Yes ○ No	● NA	
	Has a restriction been amended, or been n	ullified by DNR	? () No			
			◯ Yes: Was	BRRTS updated? (95)	○ Yes ○ No*	
			_	the CO PDF updated?	○ Yes ○ No*	
No	tes:			,	0 111 0 111	
	operty managed by Madison Property Man	nagement, Ton	y Xiong, tony@	madisonproperty.com		
То	ny met me onsite for the walk-through.					
Sit	e Visit:					
	Contact the site owner for access. Provi conducted for a CO which would now re plan was required at closure, for the pro-	equire a mainte	enance plan, pro	ovide a template versio		
3.	Walk the site (ideally with the owner or a documented at closure/other to verify or template.					
4.	With the site owner/RP (if possible), ans	wer the follow	ing for DNR RR	records:		
Dic	I the site owner know about the continuing o	bligation(s)?	○ Yes •	No		
	ve site conditions changed since closure tha	it would affect e	•		ns or requirements	
ass	sociated with the site?					
	No					
	○ Yes - Explain:					

Examples: 1) a building has been razed and investigation and remediation occurred. 2) excavation or residential development has occurred in a restricted area. BRRTS Number: 02-13-583171

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 07/22) Page 3 of 6

Has a pavement (asphalt or concrete) cover, soil cover or other sort of cover, such as a building, been removed or is it in disrepair? No/NA	
Yes – Should it be replaced or repaired? Yes ^{**} No	
If a performance standard was the final remedy, has it been altered? No Yes - Explain:	
Was the DNR notified? Yes No Have local zoning changes occurred since closure? No/NA Yes – Does it appear to impact the effectiveness of the restriction? No Yes – Describe:	
Is soil sampling needed to determine if the final remedy has been modified such that a direct contact threat exists? No Yes - Describe:	
For example, an asphalt cover has been removed or is in disrepair, or a new contaminated site is present upgradient, etc.	
Has additional monitoring or remediation been done since the site was closed? No Yes – Describe:	
Does a new threat to public health or the environment exist (e.g. new sources or exposure routes)? No 	
○ Yes – Does sampling need to be performed?	
 No Yes** – Describe what should be done to address the problem, and by whom: 	
Is the vapor mitigation system or sub-slab depressurization system (SSDS) operating as designed? (pressure gradient being maintained) O Yes NA	3
 No** - Describe any follow up needed: Needs repair. Manometer is level, indicating leakage in the system, although we could hear the fan. 	
Have any of the exposure assumptions used for closure changed at this site? NA	
NoYes – Describe any follow up needed:	
Has the land use at this site changed such that a vapor intrusion pathway may now exist? No Yes – Describe any follow up needed:	

BRRTS Number: 02-13-583171

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 07/22) Page 4 of 6

Page 4 of 6

Has the land use changed such that there are either health or safety issues? • No
Yes – Describe any follow up needed:
Notes:
I will email owner and property manager copies of the closure letter (which has the maintenance plans attached) and the inspection forms.
COMPLIANCE AND FOLLOW-UP SUMMARY:
5. Identify compliance and any follow up needed.
Is the site in compliance with the continuing obligations/closure approval document?
○ Yes
No – Describe what's not in compliance and the reasons for noncompliance: No – Describe what's not in compliance and the reasons for noncompliance:
vapor mitigation system needs repair
(May depend on extent of non-compliance, non-maintenance of remedy or changed ownership or conditions. If case is out of compliance, it should be prioritized by the region, for new casework or enforcement, as needed.)
Has the maintenance agreement required at closure been followed?
○ Yes
NA
○ No – Describe:
Was the property owner reminded to complete and document the (yearly) inspections?
Yes
○ NA○ No – Why not?
O No Willy libe:
Was a maintenance plan or template provided to the property owner at the site visit?
Yes
○ NA
No – If no, why not?
I will be sending PDFs in email.
6.** Are additional actions by the RP property owner warranted at the site? The intent is to return the site to compliance with continuing obligation. If a significant land use change has occurred, and/or further remedial action is needed, determine if the site meets the NR 726 reopening criteria.)
○ No
 Yes – Summarize the actions needed to return the site to compliance and identify who is responsible:
Repair vapor mitigation system

BRRTS Number: 02-13-583171 **Continuing Obligation Review** Form 4400-232 (R 07/22) Page 5 of 6

Notes:

Add AC 186 for RP/property owner follow-up required. Use AC 99 if a reminder was provided to the property owner to complete and document inspections.

7. * Does the s	ite require follow up by DNR?
○ No	
Yes:	contact or enforcement to return site to compliance with continuing obligation
	updating BRRTS for the CO PDF (adding or modifying a packet)
	reopen site (add ACs 186, 12 and 13)
∇	other: review documentation of VMS renair and undate DNR database

- 8. * Attach photographs of the site, documenting site conditions. Label the photos with the site name/BRRTS Activity number/date/view. If a follow-up letter is sent, include a copy with the audit. (audit/photos/follow-up letter)
- 9. * Save a copy of the audit using the following naming convention: YYYYMMDD_185_CO_Audit.pdf. For follow-up documentation use YYYYMMDD_186_Follow_Up_Needed.pdf.
- 10. Update applicable BRRTS action codes on the Table on page 1. Use the regional tracking sheet, and have your Regional EPA update the ACs and upload the audit PDF into BRRTS.
- 11. Notify Central Office when the audit has been completed and loaded into BRRTS.

{Click to add an image file (*.bmp, *.jpg, *.gif, *.png, *.tif) For best results, insert a photo with horizontal orientation. Crop vertical photos to a horizontal orientation, if needed.} Date added: 09/08/2023



Title: Front view of subject property (current tenant is a vape & cigar shop)


Date added: 09/08/2023

Page 6 of 6

BRRTS Number: 02-13-583171

Form 4400-232 (R 07/22)

{Click to add an image file (*.bmp, *.jpg, *.gif, *.png, *.tif) For best results, insert a photo Date added: 09/08/2023 with horizontal orientation. Crop vertical photos to a horizontal orientation, if needed.}



Title: Manometer fluid is level, indicating leakage in the vapor mitigation system

{Click to add an image file (*.bmp, *.jpg, *.gif, *.png, *.tif) For best results, insert a photo with horizontal orientation. Crop vertical photos to a horizontal orientation, if needed.}



Title: Back of subject unit