

Notice: Hazardous substance discharges must be reported immediately according to Wis. Stat. § 292.11. Non-emergency hazardous substance discharges may be reported by submitting this online form, calling the Department or visiting an office in person. Under Wis. Stat. § 292.99, the penalty for violating the reporting requirement of Wis. Stat. ch. 292 shall be no less than \$10 nor more than \$5,000 for each violation. Each day of continued violation is a separate offense. It is not the Department's intention to use any personally identifiable information from this form for any purpose other than program administration. However, information submitted on this form may also be made available to requesters under Wisconsin's Open Records Law (Wis. Stat. § 19.31 - 19.39). Submitting the notification as part of a Phase 1 or Phase 2 environment assessment report is not considered immediate notification under Wis. Stat. ch. 292.

Reporter Information:

Name: Lynette Carney Company: Barr Engineering
Address: 325 S Lake Ave, Duluth, MN, 55802 Phone: 2185297141
Email: lcarney@barr.com

Site Information:

Site Name: Superior Refining Company LLC (SRC)
Address: 2407 Stinson Ave, Superior, WI, 54880
Address Description: NW1/4, NW1/4, Sec 36, T49N, R14W

Coordinates, County and municipality where contamination was found on the property

Coordinates: WTM 361691 692814 Lat/Long 46.69015 -92.07039

What does the coordinate location represent? Contamination source (preferred)

County: Douglas Municipality: Superior



Responsible Party (RP):

Company Name	Full Name	Address	Email	Phone Number
Superior Refining Company LLC (SRC)		2407 Stinson Ave, Superior, WI, 54880	joseph.pearson@cenovus.com	7153983533

Contact Person:

Representing the Responsible Party, Business or Property Owner

Contact Person Information: None of the above

Company Name	Full Name	Address	Email	Phone Number
Superior Refining Company LLC (SRC)	Joseph Pearson	2407 Stinson Ave, Superior, WI, 54880	joseph.pearson@cenovus.com	7632189982

Hazardous Substance Information

Type of Discharge:

Other - Describe

historical release in refinery process unit (Platformer)

Contamination was discovered as a result of:

Other Assessment - 12/6/2022

Other Assessment Comments - Historical petroleum spill identified during removal of concrete in the Platformer Unit

Hazardous Substance Discharged:

Unknown Type

Impacts to the Environment

Impacts to the Environment Information:

Soil Contamination

Lab Results and other Info

Lab results or Report: No lab results or report are available

Lab comments: Samples will be collected as access allows. Laboratory results will be provided in a future report

Additional documentation: None of the above

Payment type: Not Applicable

Payment Amount: 0

Additional Comments: Historical impacts to soil were discovered during a concrete replacement project in the Platformer. Soil removed as part of this work will be managed separately. Representative soil samples will be collected from the excavation prior to concrete replacement. Concrete replacement work may happen in multiple phases.

If you have questions please contact:

KATHLEEN SHAFEL

kathleen.shafel@wisconsin.gov

(715) 527-0116