

Hustisford
Dodge County
February 9, 1978

The City of Hustisford has a two cell lagoon system located south of town. The first lagoon is an aerated lagoon and the second is a polishing pond. The discharge enters a channel and travels a short distance before it enters the Rock River. It is an existing channel and primarily carries only effluent.


Recommendations

From the Hustisford outfall to the juncture of the Rock River the classification should be noncontinuous marginal. The Rock River at this point is continuous fish and aquatic life.

The above recommendations represent a concurrence of opinion of the stream classification team who are as follows:

Jim Congdon - Area Fish Manager
Tom Bainbridge - District Biologist
Roger Schlessner - Environmental Specialist

Roger Schlessner
Roger Schlessner
Environmental Specialist




(WATERTOWN) 3270 II
 WATERTOWN 8.1 MI.
 SCALE 1:62500

R. 16 E.

371 35' INTERIOR—GEOLOGICAL SURVEY, WASHINGTON, D. C. 1971

ASHIPPUN 1.8 MI.
 OCONOMOWOC 9.8 MI.

3700



ROAD CLASSIFICATION

Heavy duty ——— Light duty ———
 Medium-duty ———

