



Photo 14. Stockbridge Tributary looking upstream from location photo 13 was taken (June 19, 2000).



Photo 15. Stockbridge Tributary looking downstream from HWY 55 (June 19, 2000)




Photo 16. Stockbridge Tributary looking upstream from HWY 55 (June 19, 2000).



Photo 17. Farm pond located immediately above Site 1A. Looking west down HWY E. The Stockbridge Tributary flows down the roadside ditch from the foreground fence downditch (June 19, 2000).



Photo 18. Stockbridge Tributary looking downstream from HWY E east of the Village of Stockbridge. Site 1A was located immediately below the HWY (June 19, 2000).



Photo 19. Mud Creek at Site 5 looking downstream from the upstream end (June 19, 2000).



Photo 21. Close-up of the upstream end of Site 5 on Mud Creek. Note the heavy moss and filamentous algae growth in the Creek (June 19, 2000).



Photo 22. Mud Creek at Site 6 looking upstream from Hickory Hills Road (June 19, 2000).



Photo 23. Mud Creek looking downstream from Hickory Hills Road immediately across the Road from Site 6 (June 19, 2000).



Photo 24. The underground flow of the Stockbridge Tributary is claimed to emerge at the location of this rock pile within the east side of the Village of Stockbridge (June 19, 2000-looking east).