Method B: Zebra Mussel Monitoring Report

rerecter	Dala			•		
Name:	Wisconsin Valley Improvement Company					
Address:	2301 N. Third Street		·			
City:	Wausau	State: WI	Zip: 54403			
Phone:	715-848-2976		•			
Monitori	ng Location			-		
Date: _	See attached table	rime: See attached	table	,		
County: _	Oneida	City:				
Body of V	Willow Reservo	ir				
Nearest I	andmark (town, highway, bo	oat ramp, bridge):				
	Willow Dam					
	lity Parameters sperature: See attached to	able Secchi Depth:				
Sampler I	information	•		•		
Total Wat	er Depth: See attached ta	ble Depth of Sampler: _	2.0m	_		
Number of	Days Sampler was in place	: :	·.			
Monitorin	g Results		•			
Number of	mussels found: # on Top s	side of Plates:		,		
	# on Bottom s	side of Plates:				
Size of t	he largest mussel:	Total:				
Size of t	he smallest mussel:					
 .						

If greater than 20 mussels are found measure 20 mussels chosen randomly from the sample. If less than 20 mussels are found measure all mussels found. Report results in table given at the end of this manual.

WILLOW RESERVOIR - ZEBRA MUSSEL MONITORING SUMMARY:

DATE	TIME	TOTAL DEPTH (m)	TEMPERATURE	REMARKS
07-MAY-01	0845	6.0	55.8	Two samplers installed
30-MAY-01	810	6.5	59.0	One sampler checked – negative
19-JUN-01	935	6.8	66.0	One sampler checked – negative
23-JUL-01	1420	6.3	80.6	One sampler checked negative
28-AUG-01	1235	5.4	71.8	One sampler checked – negative
27-SEP-01	1145	5.2	57.2	One sampler checked – negative
31-OCT-01	1200	5.2	41.4	Both samplers removed and checked – negative