

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name LEHNER CREEK		Waterbody ID Code 24400	Sample ID (YYYYMMDD-CY-FD) 20191010-67-07
Sampling Location US Lily Rd			Database Key 220742847
SWIMS Station ID 10008831		SWIMS Station Name UN CR (LEHNER CREEK) STATION #1 25 M UP FROM LILY ROAD	
Latitude 43.3266	Longitude 88.2087	Lat/Long Determination Method (circle) SWIMS SWDV <u>GPS</u>	Datum Used if using GPS <u>WGS84</u> or NAD83
Basin (WMU) MILWAUKEE RIVER		Watershed Name CEDAR CREEK	County WASHINGTON

Sample and Site Descriptors

Sample Collector (Last Name, First) CRAIG HELKER	Project Name MILWAUKEE RIVER BASIN AQUATIC MACROINVERTEBRATE
--	--

Sampling Device

☒ D-Frame Kick Net	☐ Surber Sampler	☐ Eckman
☐ Ponar	☐ Artificial Substrate	☐ Hess Sampler ☐ Other: _____

Habitat Sampled

☒ Riffle	☐ Run	☐ Pool
☐ Other	☐ Shoreline Composite	☐ Proportionally-Sampled Habitat
☐ Littoral Zone	☐ Profundal Zone	☐ Wetland

Total Sampling Time (min) 1	Estimated Area Sampled (m²) 1	Number of Samples in Composite	Replicate No. _____ of _____
---------------------------------------	--	---------------------------------------	-------------------------------------

Reason For Sampling

☐ Least Impacted Reference	☐ Baseline	☐ Impact / Treatment Site
☐ Control Site	☐ Trend	☒ Other: _____

Water Temp. (C) 15.83	D.O. (mg/l) 10.21	D.O. (% sat.) 105.2	pH (su)	Conductivity (umhos/cm) 869.6	Transparency (cm) +120
---------------------------------	-----------------------------	-------------------------------	----------------	---	----------------------------------

Water Color ☒ Clear ☐ Turbid ☐ Stained	Estimated Stream Velocity (m/s) ☐ Slow (< 0.15 m/s) ☒ Moderate (0.15 m/s - 0.5 m/s) ☐ Fast (> 0.5 m/s)
--	--

Measured Velocity 1.01 circle units m/s or f/s	Average Stream Depth of reach (m) .3	Average Stream Width of reach (m) 3
--	--	---

Composition of Substrate Sampled (Percent):

Bedrock: _____	Boulders (basketball or larger): _____	Rubble (tennisball to basketball): 70	Gravel (ladybug to tennisball): 20
Sand: 10	Clay: _____	Silt/Muck: _____	Overhanging Vegetation: _____
Aquatic Macrophytes: _____	Leaf Snags: _____	Coarse Woody Debris: _____	Other (_____): _____

Embeddedness of Substrate at Sample Site (%) 10	Canopy Cover at Sample Site (%) 30
--	---

Stream and Watershed Descriptors

N = Not a problem
U = Uncertain

PL = Present, Low Impact
PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological			Chemical				
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Bank Erosion				Runoff: - Barnyard			
Channelization: - Upstream				- Construction			
- Downstream				- Cropland			
Hydraulic Scour / Channel Incision				- Urban			
Impoundment: - Upstream				Septic Systems			
- Downstream				Tile Drainage - Organic Soils			
Low Flow				- Mineral Soils			
Sedimentation				Springs			
Sludge				Tributary(s)			
Thermal				Wetland			
Turbidity				Other - Specify:			
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only

Sample Sorter <i>Eric Naas</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>13%</i>
Date Processed <i>6/3/2020</i>	Specimens Saved <i>Subsample archived in HSL label Aug 2023</i>	

B3 AI
W2 75 = 137

Taxonomist: Dimick, Jeffrey

Page 1 of 1

[illegible]