

## Wisconsin Department of Natural Resources

## Notification of Petroleum Contamination from Underground Storage Tank System

Please complete this form and FAX it to Mike Farley, LUST Program Assistant, Southeast District, Milwaukee, immediately upon discovery of a release from an UST system.

**TO: WDNR, Attn: Mike Farley**  
**FAX #: 414-229-0810**

**1. Name, company, mailing address and phone number of person reporting the discharge:**

Gregory S. Walsh  
Assured Environmental Associates, Inc.  
14120 W. Glendale Ave.  
Brookfield, WI 53003  
(414) 781-4646

**2. Site Information**

Name of site at which discharge occurred (local name of site/business - not responsible party name, unless a residence):

D&M Motors

Location (actual street address, not PO box; if no street address, describe as precisely as possible, i.e., 1/4 mile NW of CTHs 60 & 123 on E side of CTH 60):

5923 West Linclon Ave.

Municipality (city, village, township in which the site is located - not mailing address):

West Allis

County:

Milwaukee

Legal Description: \_\_\_ 1/4, \_\_\_ 1/4, Section \_\_\_, Tn \_\_\_, Range \_\_\_ E/W

**3. Responsible Party (RP) and/or RP Representative Information**

Company Name:

Contact Person:

George Tsitsos

Mailing Address (with zip code):

5881 South Howell Ave.  
Milwaukee 53207

Telephone Number:

(414) 747-1142

4. Identify tank size(s) and contents (list all that apply):

_____ unknown size _____	Unleaded gasoline	_____ Fuel Oil
_____ possible unknow size _____	Leaded gasoline	_____ Waste Oil
_____ Diesel		_____ Other _____

gasoline USTs

5. Impacts to the environment:

_____ Fire/explosion threat	_____ <input checked="" type="checkbox"/> Soil contamination
_____ Contaminated private wells (# of wells _____)	_____ Surface water impacts
_____ Contaminated public wells	_____ Floating product
_____ Groundwater contamination	_____ Other _____

6. Contamination was discovered as a result of:

\_\_\_\_\_ Tank closure assessment     Site assessment    \_\_\_\_\_ (Other) \_\_\_\_\_ Tank Removal \_\_\_\_\_

7. Immediate actions being taken and the name of the contractor or other person performing the actions:

Sampling completed by Assured environmental Associates, Inc.

8. Source, speed of movement, and destination or probable destination of the discharged hazardous substance.

None identified.

9. Local soil type and topography in the area of the discharge, depth to groundwater, and distance to surface water:

Soil: clay to sandy clay; relatively flat topography; unknown depth to groundwater; unknown distance to surface water. Groundwater or surface water were not observed to be threatened.

10. Weather conditions existing at the scene, including presence of precipitation, and wind direction and velocity:

Calm, no precip, T = 25 F

11. Soil contaminant concentration of laboratory analytical samples (if known):

Elevated GRO concentration obtained from geoprobe sample (1)

Additional Comments: