Spill Notification for WRR Environmental Services Co., Inc.

EPA ID# WID990829475 FID# 618026530 Spill ID# 19644

ID 20230917WC18-1- Other: Flammable Hazardous Material

Per Condition 86 of WRR Environmental Services' current Feasibility and Plan of Operations Report (FPOR), WRR is making the following spill report to the Department's designated Hazardous Waste Inspector assigned to WRR, to the Department's designated Hazardous Waste plan review staff person assigned to WRR and to the Department's designated Spills Coordinator.

This notification, required by Condition 86 of the WRR FPOR and NR 706.05(1), contains the following information to the extent practicable or applicable:

1. Name, address, and telephone number of the person reporting the discharge.

Becky Anderson – Director of Compliance WRR Environmental Services Co., Inc. 5200 Ryder Road Eau Claire WI 54701 715-577-7755 (Cell)

2. Name, address, and telephone number of the discharger, or owner and operator of the UST system and any other potentially responsible persons.

WRR Environmental Services 5200 Ryder Road Eau Claire WI 54701 715-834-9624

3. Date, time, and duration of the discharge.

September 17, 2023 at 8:45 pm. Time to clean up the release was 1.50 hours.

Location of the discharge including street address, county, town, city or village

WRR Environmental Services Co., Inc. 5200 Ryder Road Eau Claire WI 54701

Town of Washington

4. Identity, physical state, and quantity of the material discharged.

~4 gallons total of Solvent Recovery Residue from a Paint Related Material run was released from a top manway on a tanker.

Spill Notification for WRR Environmental Services Co – Reclamation Residue 09172023

5. Physical, chemical, hazardous, and toxicological characteristics of the substance.

The release was a paint residue consisting mainly of paint solids and flammable solvents. The main hazard associated with this material is its flammability

6. Cause of the discharge.

The release occurred as a production worker running a solvent recovery operation with product going to an above ground tank and the residue going to a tanker. The fill pipe to the residue tanker was not secured correctly. This allowed the fill pipe to jump out of the tanker when pressure built up in the line. Material was released from the top of the tanker.

7. Immediate actions being taken and the name of the contractor or other person performing the action.

A supervisor saw the release and shut valves to prevent a greater release. The supervisor shut down the solvent recovery equipment to stop more residue from entering the tanker. The supervisor contacted the operator and spill control activities were started.

All cleanup activities were conducted by WRR personnel.

8. Source, speed of movement, and destination or probable destination of the discharged hazardous substance.

The release was contained the concrete and blacktop. No material drained to the onsite reservoir or grassy areas.

Included with this report is a facility map with the release location marked with a red arrow.

9. Actual or potential impacts to human health or the environment, including actual or potential impacts to drinking water supplies.

WRR personnel were wearing personal protective equipment during cleanup operations. No injuries were reported.


No drinking water supplies were impacted by the spill.

This waste contained to the concrete and blacktop.

10. Weather conditions existing at the scene, including presence of precipitation and wind direction and velocity.

The night was clear and 50F with no breeze.

11.Other agencies on–scene during the discharge incident.	
No agencies were on-site during the discharge or clean-up.	
The agentices were on site during the discharge of olean up.	



WRR Environmental Services Co Inc. 5200 Ryder Road
Eau Claire WI 54701
FID ID# 618026530
EPA ID# WID990829475

Condition 86 – DNR Spill Hotline Report

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision according to a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

James L Hager President/CEO

10/2/2023

Date