



August 23, 2018

Vicki Mottram

P.O. Box 4

Grand View, Wisconsin 54839



Subject:

Water Well Sample Results – 54665 Cudworth Avenue
Kelly's Spur
Grand View, Wisconsin

Dear Ms. Mottram:

On July 17, 2018, REI Engineering, Inc. (REI) collected a water sample from the water well located on your property at 54665 Cudworth Avenue. The sample was collected as part of the on-going monitoring of the Kelly's Spur petroleum release at 22230 U.S. Highway 63. The results indicate that your well is not impacted by the parameters associated with the release. We have included the following items for your reference:

- A copy of a map depicting the location of Kelly's Spur in relation to your property
- A table depicting the previous and current results
- A copy of the laboratory analytical report for your well sample

If you have any questions or concerns, please feel free to contact me at (715) 675-9784 or via email at dlarsen@reiengineering.com.

Sincerely,
REI Engineering, Inc.

Julie Linn, PG, RG for
Dave Larsen, PG
Senior Hydrogeologist/Professional Geologist

Enclosures



RESPONSIVE. EFFICIENT. INNOVATIVE.

4080 N. 20th Avenue Wausau, WI 54401

715-675-9784 REIengineering.com



August 23, 2018

Great Divide Christian Center
30770 Hager Road
Mason, Wisconsin 54856



Subject:

Water Well Sample Results – 54655 Raymond Avenue
Kelly's Spur
Grand View, Wisconsin

Dear To Whom it May Concern:

On July 17, 2018, REI Engineering, Inc. (REI) collected a water sample from the water well located on your property at 54655 Raymond Avenue. The sample was collected as part of the on-going monitoring of the Kelly's Spur petroleum release at 22230 U.S. Highway 63. The results indicate that your well is not impacted by the parameters associated with the release. We have included the following items for your reference:

- A copy of a map depicting the location of Kelly's Spur in relation to your property
- A table depicting the previous and current results
- A copy of the laboratory analytical report for your well sample

If you have any questions or concerns, please feel free to contact me at (715) 675-9784 or via email at dlarsen@reiengineering.com.

Sincerely,
REI Engineering, Inc.

Julie Linn, PG, RG for
Dave Larsen, PG
Senior Hydrogeologist/Professional Geologist



RESPONSIVE. EFFICIENT. INNOVATIVE.

4080 N. 20th Avenue Wausau, WI 54401
715-675-9784 REIengineering.com



August 23, 2018

Grand View United Methodist Church

P.O. Box 124

Grand View, Wisconsin 54839



Subject:

Water Well Sample Results – 54630 Cudworth Avenue
Kelly's Spur
Grand View, Wisconsin

To Whom it May Concern:

On July 17, 2018, REI Engineering, Inc. (REI) collected a water sample from the water well located at 54630 Cudworth Avenue; which provides water to your facility at 22180 U.S. Highway 63. The sample was collected as part of the on-going monitoring of the Kelly's Spur petroleum release at 22230 U.S. Highway 63. The results indicate that your well is not impacted by the parameters associated with the release. We have included the following items for your reference:

- A copy of a map depicting the location of Kelly's Spur in relation to your property
- A table depicting the current results
- A copy of the laboratory analytical report for your well sample

If you have any questions or concerns, please feel free to contact me at (715) 675-9784 or via email at dlarsen@reiengineering.com.

Sincerely,
REI Engineering, Inc.

Julie Linn, PG, RG for
Dave Larsen, PG
Senior Hydrogeologist/Professional Geologist

Enclosures



RESPONSIVE. EFFICIENT. INNOVATIVE.

4080 N. 20th Avenue Wausau, WI 54401
715-675-9784 REIengineering.com



August 23, 2018

Korlis Wallin
54635 Cudworth Avenue
Grand View, Wisconsin 54839



Subject:

Water Well Sample Results – 54635 Cudworth Avenue
Kelly's Spur
Grand View, Wisconsin

Dear Korlis:

On July 17, 2018, REI Engineering, Inc. (REI) collected a water sample from the water well located on your property at 54635 Cudworth Avenue. The sample was collected as part of the on-going monitoring of the Kelly's Spur petroleum release at 22230 U.S. Highway 63. The results indicate that your well is not impacted by the parameters associated with the release. We have included the following items for your reference:

- A copy of a map depicting the location of Kelly's Spur in relation to your property
- A table depicting the previous and current results
- A copy of the laboratory analytical report for your well sample

If you have any questions or concerns, please feel free to contact me at (715) 675-9784 or via email at dlarsen@reiengineering.com.

Sincerely,
REI Engineering, Inc.

Julie Linn, PG, RG for
Dave Larsen, PG
Senior Hydrogeologist/Professional Geologist

Enclosures



RESPONSIVE. EFFICIENT. INNOVATIVE.

4080 N. 20th Avenue Wausau, WI 54401
715-675-9784 REIengineering.com



August 23, 2018

Andrew and Rochelle Leding
54630 Cudworth Avenue
Grand View, Wisconsin 54839



Subject:

Water Well Sample Results – 54630 Cudworth Avenue
Kelly's Spur
Grand View, Wisconsin

Dear Mr. and Mrs. Leding:

On July 17, 2018, REI Engineering, Inc. (REI) collected a water sample from the water well located at your property. The sample was collected as part of the on-going monitoring of the Kelly's Spur petroleum release at 22230 U.S. Highway 63. The results indicate that your well is not impacted by the parameters associated with the release. We have included the following items for your reference:

- A copy of a map depicting the location of Kelly's Spur in relation to your property
- A table depicting the previous and current results
- A copy of the laboratory analytical report for your well sample

If you have any questions or concerns, please feel free to contact me at (715) 675-9784 or via email at dlarsen@reiengineering.com.

Sincerely,
REI Engineering, Inc.

Julie Linn, PG, RG for
Dave Larsen, PG
Senior Hydrogeologist/Professional Geologist

Enclosures



RESPONSIVE. EFFICIENT. INNOVATIVE.

4080 N. 20th Avenue Wausau, WI 54401
715-675-9784 REIengineering.com