

24-Hour Emergency Hotline Number: 1-800-943-0003

04-38-255500

Form 4400-91 Rev. 11-95

04-38-255500

Date and Mil. Time of Incident 08-19-99 @ 0600	Date and Mil. Time Reported 08-19-99 @ 1105
--	---

Person Reporting GEORGE ROGERS	Telephone # (715) 735-7411
--------------------------------	----------------------------

Representing Agency, Firm or Citizen SPECIALITY CHEMICAL <i>Nasul</i>
--

Responsible Party SUPERIOR ENVIROMENTAL SERVICES
--

Contact Name DAN GRUNEWALD	Telephone # (715) 732-0484
----------------------------	---------------------------------------

Address 100 W. LARSON DR.	City, State, Zip Code FOND DU LAC, WI. 54937
---------------------------	---

Substance Involved HYDRAULIC FLUID-BIODEGRAD	Amount & Units Released 10-15 GALLONS	Amount Recovered 14 GALLONS	Is this a 304 (11004 42 USC) <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown
---	--	--------------------------------	---

<input type="checkbox"/> Solid <input type="checkbox"/> Semisolid <input type="checkbox"/> Liquid	Gas Color _____	Odor _____
---	-----------------	------------

Exact Location (inc. address, facility name, mileage, bldg. #, etc.) WATERS OF THE MENOMINEE RIVER W/IN ARSENIC CONTAINMENT AREA OFF 8 TH ST., CITY OF MARINETTE <i>Nasul - 1 Stanton Street</i> <i>Eight Street Slip</i>

City MARINETTE	County MARINETTE	Lat/long
----------------	------------------	----------

DNR Region <u>NER</u>	<u>1/4</u> <u>1/4</u> sec <u>NR</u> (E/W)	Weather Cond. WIND - CALM, COOL TEMPS
-----------------------	---	---------------------------------------

Cause of Incident HEAVY EQUIPMENT FROM R.P. INVOLVED WITH CLEANUP OF ARSENIC CONTAMINATED AREA IDENTIFIED BY EPA, ON BED OF MENOMINEE RIVER, DEVELOPED LEAK FORM HOSES ON UNIT RESULTING IN DISCHARGE. FLUID IS BIO-DEGRADABLE

Spilled Substance Impact To: Check (✓) all that apply: <input type="checkbox"/> Air <input type="checkbox"/> Potential <input type="checkbox"/> Soil <input type="checkbox"/> Potential <input type="checkbox"/> Groundwater <input type="checkbox"/> Potential <input checked="" type="checkbox"/> Surface Water <input type="checkbox"/> Potential Name: MENOMINEE RIVER <input type="checkbox"/> Storm Sewer <input type="checkbox"/> Potential <input type="checkbox"/> Sanitary Sewer <input type="checkbox"/> Potential <input type="checkbox"/> Concrete/Asphalt <input type="checkbox"/> Potential <input type="checkbox"/> Private Well <input type="checkbox"/> Potential <input checked="" type="checkbox"/> Contained/Recovered <input type="checkbox"/> Other: _____	Spill Source: <input type="checkbox"/> Transportation Accident, Fuel Tank Spill <input type="checkbox"/> Transportation Accident, Load Spill <input type="checkbox"/> Industrial Facility <input type="checkbox"/> Paper Mill <input type="checkbox"/> Chemical Company <input type="checkbox"/> Ag Coop/Facility/ Food Factory/Facility <input type="checkbox"/> Gas/Service Station/Garage/Auto Dealer <input type="checkbox"/> Pipeline, Terminal, Tank Farm, etc. <input type="checkbox"/> Public Property (city, state, school, etc.) <input type="checkbox"/> Utility Co, Power Generating Facility <input type="checkbox"/> Private Property (home/farm) <input checked="" type="checkbox"/> Construction, Excavation, Mine, etc. <input type="checkbox"/> Airport Facility <input type="checkbox"/> Railroad Facility <input type="checkbox"/> Other: _____	Action Taken By Spiller: <input checked="" type="checkbox"/> No Action Taken <input type="checkbox"/> No Action Needed <input type="checkbox"/> Monitor <input checked="" type="checkbox"/> Cleanup Method: BOOMS <i>1 Pad</i> <input checked="" type="checkbox"/> Waste Destination: PORT WASHINGTON SITE <input type="checkbox"/> Containment <i>2-55 gal drums</i> <input checked="" type="checkbox"/> Contractor Hired Name: SUPERIOR ENVIR. <input type="checkbox"/> Other: _____
---	--	---

Injuries? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, how many? _____	Has an evacuation occurred? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Potential? <input type="checkbox"/> Yes <input type="checkbox"/> No
---	---

Are there any resource damages? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Potential What kinds? _____

Other Agencies Notified (✓ first column if notified); Check (✓) both columns if on scene <input type="checkbox"/> Fire Department/Hazmat <input checked="" type="checkbox"/> Local DNR <input type="checkbox"/> EPA <input type="checkbox"/> Local Law Enforcement <input type="checkbox"/> Div. Emer. Gov. <input type="checkbox"/> Nat'l Resp. Ctr. 800-442-8802 <input type="checkbox"/> LEPC or Local Emer. Gov. <input type="checkbox"/> DATCP 608-224-4500 <input type="checkbox"/> Chemtrec 800-424-9300 <input type="checkbox"/> Regional Response Team <input type="checkbox"/> DHSS 608-266-2830 <input type="checkbox"/> Other _____	Incident Commander, if known: _____ Phone: _____
---	---

Prepared By: (Print) STEVEN DAYE (Sign) <i>[Signature]</i> Date: 08-19-99	Rpt'd to DATCP? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---

Person Notified: STAN NOGALSKI Region Notified: NO Time: N/A	Da
--	----

Investigated By: (Print) STEVEN DAYE (Sign) <i>[Signature]</i> Date: 08-19-99	Site Closed? <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <i>6-23-00</i>
---	--

Spill Coordinator Signoff: <i>[Signature]</i> Date: <i>6-23-00</i>	NFA Letter Sent? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
--	--

INCIDENT RESPONSE REPORT

PREPARED FOR

WISCONSIN DEPARTMENT OF NATURAL RESOURCES

**ROXANNE NELEZEN CHRONERT
SPILLS COORDINATOR**

PREPARED BY

Daniel J Grunewald-PROJECT MANAGER

SUPERIOR SPECIAL SERVICES, INC.

P.O. BOX 1323

FOND DU LAC, WI 54936-1323

SUPERIOR JOB # GCL4286

Response Date: August 19, 1999

INCIDENT SUMMARY

NOTIFICATION DATE: August 19, 1999

TIME NOTIFIED: 10:15 AM

NOTIFIED BY: Super Special Services, Inc. - Randy Peterson

INCIDENT LOCATION: 1 North Stratton Street, Marinette, WI 54143
(Eight Street Slip)

Contact: Roxanne Nelezen Chronert

INCIDENT TYPE: Cleanup Biodegradable Hydraulic Oil Contamination

SUBSTANCE: Biodegradable Oil, Pads, and Boom

SOURCE: Broken Hydraulic Line from Hydraulic Dredge

STATUS: a broken hydraulic hose caused Contamination from the cutter head of our hydraulic dredge. The spill happen at the eight street slip, which the waters were contained by PZ 27 sheet piling. Superior Special Services responded to the call the clean up the oil.

WASTE GENERATED: 2 55-Gallon Metal Drums of Boom and Pads

INCIDENT NARRATIVE

At 10:15 on August 19, 1999 Super Special Services, Inc. was hydraulically dredging contaminated sediment from a sheet wall containment at the Eighth street slip in Marinette, Wisconsin when a hydraulic line broke off on our dredge. The dredging stopped immediately and the spill kit on site that contained soft boom and pads was deployed. Superior personnel surround the dredge with soft boom and stopped the material from exiting between the pontoons of the dredge. At the time that the site superintendent called the office to report the spill, the Superior crew began padding up the biodegradable oil and placing the pads into the 55-gallon drums. After the biodegradable oil was removed from the surface of the water, the crew then wiped down the pontoons of the dredge to remove any residual that might have attached itself to the dredge. Superior recovered 2 55-gallon metal drums of soft boom and pads. The drums were loaded that day onto a Superior transportation vehicle and disposed of at our TSDF location in Port Washington, Wisconsin.

All information has been submitted with good intent and is accurate to the best of my knowledge.

REPORT COMPLETED BY: Al Hoepner-Project Manager

SIGNATURE: _____ DATE: _____

TABLE OF CONTENTS

I. INCIDENT SUMMARY

II. INCIDENT NARRATIVE

III. ATTACHMENTS

Appendix A...MSDS Of Biodegradable Oil

Precautions To Be Taken in Handling and Storage: Keep containers closed when not in use. Wash thoroughly after handling.

Special Comments: No special storage precautions are required.

Although the information and recommendations set forth herein (hereafter referred to as information) are presented in good faith and believed to be accurate and factual as of the date hereof, Schaeffer Mfg. Company makes no representation as to the completeness or accuracy thereof. Information is supplied upon the condition that the person receiving the same will make their own determination as to its safety and suitability for their purposes prior to use. In no event will Schaeffer Mfg. Company be responsible for damages of any natures whatsoever resulting from the use or reliance upon information. **No representation or warranty, either expressed or implied, of merchantability or fitness for a particular purpose is made with respect to information of the product to which the information refers.**

Spill Packet Sent? Yes No

X Additional Comments on Reverse

PLEASE PRINT

State of Wisconsin Substance Release Report (Con't)

Form 4401-91 Rev. 11-95

Date and Military Time of Incident 08-19-99 @ 0600

Responsible Party SUPERIOR ENVIROMENTAL SERVICES

Additional Comments:

SUPERIOR IS THE CLEANUP CONTRACTOR FOR THIS PROJECT. A PIECE OF THE HEAVY EQUIPMENT USED IN THIS CLEANUP PROJECT DEVELOPED A LEAK OVER NIGHT AND 10-15 GALLONS OF HYRAULIC FLUID SPILLED INTO WATER WHICH IS CONTAINED BY SHEET METAL PILING WHICH IDENTIFIES THE AREA. BOOMS USED TO ABSORB MATERIAL FROM THE WATER. DAYE LEARNED THIS BY WAY OF TELEPHONE CONTACT AND LEARNED FLUID IS BIODEGRAD-ABLE. REASON GIVEN FOR NOT REPORTING WAS HE FORGOT DUE TO BUSY WORKLOAD. HE DID HANDLE ANOTHER SPILL WITH WARDEN KITT AT SHOPKO IN MARINETTE NIGHT BEFORE.