

Spill ID Number

04-16-045246 closed  
Y Y M M D D 0-99

Date of Incident 11-14-90	Day of Week Wed.	Time of Incident 10:20	<input checked="" type="checkbox"/> A.M. <input type="checkbox"/> P.M.	Reported By (Name) Bruce Jardine	Telephone Number ( 715 ) 398-3533
Date Reported 11-14-90	Day of Week Wed.	Time Reported 10:40	<input checked="" type="checkbox"/> A.M. <input type="checkbox"/> P.M.	Agency or Firm Reporting Murphy Oil Refinery	Reported thru Div. Emergen. Gov't. <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Substance Involved sulfur		Quantity 50	Units gallons	Person or Firm Responsible Murphy Oil Refinery	
Substance Involved		Quantity	Units	Contact Name Bruce Jardine	Telephone Number ( 715 ) 398-3533
Physical Characteristics <input checked="" type="checkbox"/> Solid <input type="checkbox"/> Semisolid <input checked="" type="checkbox"/> Liquid <input type="checkbox"/> Gas Color <u>yellow</u> Odor <u>sulfur</u>				Address - Street or Route P.O. Box 2066 City, State, Zip Code Superior, WI 54880	
Cause of Incident overload tank car				Action Taken By Spiller <input type="checkbox"/> No Action Taken <input type="checkbox"/> No Notification <input type="checkbox"/> Investigate <input type="checkbox"/> Containment; Type _____ <input checked="" type="checkbox"/> Cleanup; Method <u>shovel &amp; front-end loader</u> <input checked="" type="checkbox"/> Amount Recovered <u>100%</u> <input type="checkbox"/> Monitor _____ <input type="checkbox"/> Contractor Hired; Name _____ <input type="checkbox"/> Other Action _____	
Exact Location Description (intersection, mileage, etc.) rail on Stinson loading platform				Spill Location <input type="checkbox"/> Industrial Facility/Paper Mill/Chem. Co. <input type="checkbox"/> Gas/Service Station/Garage, Auto Dealer, Repair Shop <input type="checkbox"/> Ag Coop/Facility/Cheese Factory/Creamery <input type="checkbox"/> Other Small Business (bank, grocery, insurance co., etc.) <input type="checkbox"/> Public Property (city, county, state, church, school, etc.) <input type="checkbox"/> Utility Co., Power Generating/Transfer Facility <input type="checkbox"/> Private Property (home/farm) <input type="checkbox"/> Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler <input type="checkbox"/> Transportation Accident, Fuel Supply Tank Spill <input type="checkbox"/> Transportation Accident, Load Spill <input type="checkbox"/> Construction, Excavation, Wrecking, Quarry, Mine <input checked="" type="checkbox"/> Other <u>oil refinery</u>	
County Location Douglas		¼¼, ¼, Section, Town, Range _____, _____, _____, T _____ N, R _____		Spilled Substance-Destination <input type="checkbox"/> Air <input type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Storm Sewer <input type="checkbox"/> Sanitary Sewer <input checked="" type="checkbox"/> Contained/Recovered <input type="checkbox"/> Other _____	
DNR Dist NW	DNR Area Brule	Groundwaters Affected <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Potential		Person Filing This Report (print name) Joe Davidowski	
Surface Waters Affected <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Potential		Name of Surface Water		Signature	
Date District Notified 11-14-90	Day of Week Wed.	Time District Notified 10:45	<input checked="" type="checkbox"/> A.M. <input type="checkbox"/> P.M.	Date Signed 11-14-90	
District Person Notified John Plenke		Telephone Number ( 715 ) 635-4151			
Date Investigated 11-14-90	Day of Week Wed.	Time Investigated 10:55	<input checked="" type="checkbox"/> A.M. <input type="checkbox"/> P.M.		
Person Investigating Joe Davidowski		Telephone Number ( 715 ) 392-7988			
Action Taken By DNR <input type="checkbox"/> No Action Taken <input checked="" type="checkbox"/> Investigation <input type="checkbox"/> Supervise/Conduct Cleanup <input type="checkbox"/> Spiller Required To Take Action; Type _____ <input type="checkbox"/> Contractor Hired By DNR; Name _____ <input type="checkbox"/> Amount Recovered _____ <input type="checkbox"/> 29.29 Enforcement					
Other Agencies on Scene Local <u>none</u> State <u>DNR</u> Federal <u>none</u>					

## Additional Comments:

Murphy was loading a rail tank car and it overloaded and spilled about 50 gallons of

sulfur. Sulfur became solid and was all picked up by three men and shovels and put into