## Vitale, Matthew J - DNR

From: Vitale, Matthew J - DNR

Sent: Tuesday, February 05, 2019 11:03 AM

To: 'Ken Shimko'

**Subject:** Re: Julson Store Progress report, BRRTS # 03-06-001296

Ken,

I have reviewed the January 23, 2019 Progress report you sent. I have it classified in BRRTS as a Remedial Action Documentation Report. I agree with the report's recommendations to install 5 additional monitoring wells/piezometers to fully define the extent of the groundwater plume. The only change I suggest to the proposed well locations from the report's Figure 8 is to move the eastern well nest further east another 10-20 ft to be sure it defines the eastern edge of the groundwater plume.

Please submit a PECFA U&C Cost request for installing the wells and for one additional groundwater monitoring round of all wells.

-Matt

## We are committed to service excellence.

Visit our survey at <a href="http://dnr.wi.gov/customersurvey">http://dnr.wi.gov/customersurvey</a> to evaluate how I did.

## Matthew Vitale

Hydrogeologist Remediation and Redevelopment Program Wisconsin Department of Natural Resources Eau Claire Regional Office 1300 W. Clairemont Ave. Eau Claire, WI 54701 Phone: (715) 839-3760

Fax: (715) 839-6076 Matthew.Vitale@wisconsin.gov

