## State of Wisconsin - Department of Natural Resources Substance Release Notification Report (SERTS) Report created on 10/01/2008

	2:00	Reported Date & Tir 09/05/2008 11:50		BRRTS No: 04-71-552387 ERP Transferred? No		Spill ID: 20080905NE71-1				
DATCP Report DATCP Transfe		NFA Letter Sent? No	2010			Incident Closed? Yes: 09/30/2008				
			Location							
Region: NE	County: Winnebago		Municipality: OSHKOSH, CIT	Y OF						
Facility/Propert OSHKOSH CO 333 W 29TH A		ress:	Descrip IN THE	tion: SOUTH PLAN	Γ PARKING L	.OT				
Facility Type:	Industrial Facility (fo	oundry, factory, platter,	etc)			V				
_at/Long:		PLSS:	WTM:							
Weather Condi	tions:	THE BOOK AND								
412 527			sponsible Parti			The bad =				
Name/Address (1): OSHKOSH CORP 2307 OREGON ST OSHKOSH, WI 54902-		Contact: SUE MURAWSKI SR PROJECT ENG (920) 233-9582 x p (920) 410-6851 x s	orimary	Other Contact: BRYAN OLSON ENVIRONMENTAL ENGINEER y (920) 233-9464 x p		Spill Packet:				
			Cause							
Cause Type: F/	AULTY FUEL TANK V/	AVLE	Substances							
Cause Type: F/	AULTY FUEL TANK V	AVLE Other / Comments	Substances Amt Released	Amt Recovered	Туре	Color	Odor			
1				Amt Recovered 50.0 Gal	Type LIQUID	Color	Odor			
1		Other / Comments	Amt Released	50.0 Gal		Color	Odor			
Diesel Environmental	Name	Other / Comments  Environme	Amt Released 50.0 Gal ental Impacts / Resource Damage	50.0 Gal Damages	LIQUID Injuries:	E	vacuation:			
Diesel Environmental	Name	Other / Comments  Environme	Amt Released 50.0 Gal ental Impacts / Resource Damage	50.0 Gal Damages es:	LIQUID	E				
Diesel Environmental	Name	Other / Comments  Environme	Amt Released 50.0 Gal ental Impacts / Resource Damage	50.0 Gal Damages es:	LIQUID Injuries:	E	vacuation:			
Diesel Environmental SOIL	Name Impacts:	Other / Comments  Environme	Amt Released 50.0 Gal ental Impacts / Resource Damage No Ieanup Actions	50.0 Gal Damages es:	LIQUID Injuries:	E	vacuation:			
Diesel Environmental   SOIL  Excavation	Impacts:	Environme R N Cleanu	Amt Released 50.0 Gal ental Impacts / Resource Damage lo Ieanup Actions 30 YARDS E	50.0 Gal  Damages es:  EXCAVATED ments	Injuries: No Description	E	vacuation: No			
Diesel Environmental SOIL Excavation EXCAVATION GRA	Impacts:  Method	Other / Comments  Environme R N C C Cleanu EXCAVATED THE IMP	Amt Released 50.0 Gal ental Impacts / Resource Damage lo leanup Actions 30 YARDS E p Action Common	50.0 Gal  Damages es:  EXCAVATED ments ACE (A 20 FT X	Injuries: No Description	E	vacuation: No			
Diesel Environmental SOIL Excavation ENUL ON GRA	Impacts:  Method	Environme R N Cleanu	Amt Released 50.0 Gal ental Impacts / Resource Damage lo leanup Actions 30 YARDS E p Action Common	50.0 Gal  Damages es:  EXCAVATED ments ACE (A 20 FT X	Injuries: No Description	E	vacuation: No			
Diesel Environmental SOIL Excavation ENUL ON GRA	Impacts:  Method	Other / Comments  Environme R N C C Cleanu EXCAVATED THE IMP	Amt Released 50.0 Gal ental Impacts / Resource Damage lo leanup Actions 30 YARDS E p Action Common	50.0 Gal  Damages es:  EXCAVATED ments ACE (A 20 FT X	Injuries: No Description	E	vacuation: No			
Diesel Environmental SOIL Excavation ENUL ON GRA	Impacts:  Method	Other / Comments  Environme R N C C Cleanu EXCAVATED THE IMP	Amt Released 50.0 Gal ental Impacts / Resource Damage lo leanup Actions 30 YARDS E p Action Common	50.0 Gal  Damages es:  EXCAVATED ments ACE (A 20 FT X	Injuries: No Description	E	vacuation: No			
Diesel Environmental SOIL Excavation ENUL ON GRA	Impacts:  Method	Other / Comments  Environme R N C C Cleanu EXCAVATED THE IMP	Amt Released 50.0 Gal ental Impacts / Resource Damage lo leanup Actions 30 YARDS E p Action Common	50.0 Gal  Damages es:  EXCAVATED ments ACE (A 20 FT X	Injuries: No Description	E	vacuation: No			
Diesel  Environmental SOIL  Excavation  SPILL ON GRA	Impacts:  Method	Cleanu EXCAVATED THE IMP	Amt Released 50.0 Gal ental Impacts / Resource Damage lo leanup Actions 30 YARDS E p Action Common	50.0 Gal  Damages es:  EXCAVATED ments ACE (A 20 FT X MANAGEMEN	Injuries: No Description	E	vacuation: No			
Diesel  Environmental   SOIL  Excavation  SPILL ON GRA	Impacts:  Method	Cleanu EXCAVATED THE IMP	Amt Released 50.0 Gal ental Impacts / Resource Damage lo leanup Actions 30 YARDS E ACTED SURFA SAL BY WASTE	50.0 Gal  Damages es:  EXCAVATED ments ACE (A 20 FT X MANAGEMEN	Injuries: No Description	E	vacuation: No			
Diesel  Environmental   SOIL  Excavation  SPILL ON GRAGRAVEL WAS	Impacts:  Method  AVEL PARKING LOT. I	Cleanu EXCAVATED THE IMP	Amt Released 50.0 Gal ental Impacts / Resource Damage lo Ieanup Actions 30 YARDS E PACTED SURFA SAL BY WASTE	50.0 Gal  Damages es:  EXCAVATED ments ACE (A 20 FT X MANAGEMEN	Injuries: No  Description  40 FT AREA T.	E	vacuation: No			
Diesel  Environmental   SOIL  Excavation  SPILL ON GRAGRAVEL WAS	Impacts:  Method  AVEL PARKING LOT. I	Cleanu EXCAVATED THE IMP	Amt Released 50.0 Gal ental Impacts / Resource Damage lo Ieanup Actions 30 YARDS E PACTED SURFA SAL BY WASTE	50.0 Gal  Damages es:  EXCAVATED ments ACE (A 20 FT X MANAGEMEN'	Injuries: No  Description  40 FT AREA T.	E	vacuation: No			
Diesel  Environmental SOIL  Excavation  SPILL ON GRAGRAVEL WAS	Impacts:  Method  AVEL PARKING LOT. I	Cleanu EXCAVATED THE IMPTAINERS FOR DISPOS	Amt Released 50.0 Gal ental Impacts / Resource Damage leanup Actions 30 YARDS E ACTED SURFA SAL BY WASTE  EXCAVATIO ste Destination	50.0 Gal  Damages es:  EXCAVATED ments ACE (A 20 FT X MANAGEMEN'	Injuries: No  Description  40 FT AREA T.  Description  Description	). THE CON	vacuation: No			

## State of Wisconsin - Department of Natural Resources Substance Release Notification Report (SERTS) Report created on 10/01/2008

		Notified / On Scene	N 416			
DVD	Agency		Notified		On Scene	9
DNR			Х			
00 26 09 MOELLED DECEN	Addition // Addition // // // // // // // // // // // // //	onal Comments				
109-26-08, MOELLER RECEIV	VED CLEAN UP REPORT FROM	105HKUSH CURP.				
	Enforce	amout Actions				
Enforcement action? No	Enforc	ement Actions				
Emorcement action? No						
				-		
Case Activity Report Numbers:				V		
		on Reporting				
Name SUE MURAWSKI	Representing / Address OSHKOSH CORP	(920) 233-9582 x	Primary Phone		condary Phone	-
SUE WURAWSKI		ractors Hired				
		Zone Contractor Hired by				
		DNR?				
				No		
Role	Name / Add	Contacts	Office Phone		Date	Time
Prepared By:	bauer Name / Add	(608) 266-5214 x		09/05/2008	Time	
Person Notified:	JASON HIGGINS				09/05/2008	
Investigated By:	JASON MOELLER		09/05/2008			
Incident Commander:	JAJON WOLLER		<del>)</del>		03/03/2006	
The state of the s	NE MOELLED IACONIDAGO	0.662.5402	Call M		00/20/0000	
Spill Coordinator:	NE - MOELLER, JASON [P] 92	O-662-5492  Attachments (list)	mld Tlock		09/30/2008	
N:	ame	Attacillients (list)	Туре			
No	anie		Туре			

ISO 9001 CERTIFIED

2307 OREGON STREET
POST OFFICE BOX 2566
OSHKOSH, WISCONSIN 54903-2566
920-235-9151



Certified Mail, Return Receipt Requested

October 8, 2008

Jason Moeller Wisconsin Department of Natural Resources Northeast Regional Office 2984 Shawano Ave., P.O. Box 10448 Green Bay, WI 54307-0448

Subject: Diesel Fuel Spill, September 5, 2008

Dear Jason,

On September 25, 2008, Oshkosh Corporation submitted a letter requesting closure of a fuel spill incident that took place September 5, 2008 at the South Plant located at 333 W. 29<sup>th</sup> Ave, Oshkosh, WI, 54902. In the letter, it was noted that the certificates of disposal of the contaminated soil would be submitted separately.

Attached to this submittal are copies of the original letter and the certificates of disposal from Waste Management's Valley Trail Landfill. If you have any questions or concerns, please contact me at (920) 233-9464. Thank you.

Bryan Olson

Environmental Engineer

cc. Don Draxler

Attachments

ISO 9001 CERTIFIED

2307 OREGON STREET
POST OFFICE BOX 2566
OSHKOSH, WISCONSIN 54903-2566
920-235-9151



Certified Mail, Return Receipt Requested

September 25, 2008

Jason Moeller Wisconsin Department of Natural Resources Northeast Regional Office 2984 Shawano Ave., P.O. Box 10448 Green Bay, WI 54307-0448

Subject: Diesel Fuel Spill, September 5, 2008

Dear Jason,

On September 5, 2008 at approximately 10:00 am, Oshkosh Corporation reported a release of diesel fuel to the DNR 24-hour Spill Hotline. The fuel was released on a gravel portion of the South Plant yard located at 333 W. 29<sup>th</sup> Ave, Oshkosh WI, 54902 due to an equipment malfunction. The spill was completely contained within the property, in an area approximately 20 feet by 40 feet.

On the same day, the impacted soil/gravel was excavated by an outside contractor and loaded into containers supplied by Waste Management. The area was excavated until no visual or olfactory evidence of fuel remained and was backfilled with clean gravel. Approximately 30 yards of soil was bio-piled at Valley Trail Landfill. The certificate of disposal from the Valley Trail Landfill will be sent as a separate submittal.

Oshkosh Corporation is respectfully requesting full closure of this spill incident. If you have any questions or concerns, please contact me at (920) 233-9464. Thank you.

Bryan Olson

Environmental Engineer

cc. Don Draxler



## **WASTE MANAGEMENT**

W132 N10487 Grant Drive Germantown, Wisconsin 53022

**September 15, 2008** 

Waste Management

Oshkosh Truck 2307 Oregon Street Oshkosh, WI 54902

Valley Trail Reference Number: 957981

To Whom It May Concern:

Valley Trail RDF received 9.92 tons of material for disposal. This material was delivered to our site on 9/15/2008. All material disposed of at Valley Trail RDF is for disposal.

Sincerely,

Jennifer Goss Technical Service Representative



## **WASTE MANAGEMENT**

W132 N10487 Grant Drive Germantown, Wisconsin 53022

10-07-2008

**September 15, 2008** 

Oshkosh Truck 2307 Oregon Street Oshkosh, WI 54902

Valley Trail Reference Number: 958003

To Whom It May Concern:

Valley Trail RDF received 10.74 tons of material for disposal. This material was delivered to our site on 9/15/2008. All material disposed of at Valley Trail RDF is for disposal.

Sincerely,

Jennifer Goss **Technical Service Representative**