



Stantec Consulting Services Inc.
12075 Corporate Parkway, Suite 200
Mequon, WI 53092
Tel: (262) 241-4466
Fax: (262) 241-4901

**BRRTS
Duplicate**

November 13, 2019
Stantec No.: 755624

Mr. Riley Neumann
Remediation & Redevelopment Program
Wisconsin Department of Natural Resources
2300 North Dr. Martin Luther King, Jr. Drive
Milwaukee, Wisconsin 53212-3128

**Reference: Workplan and Cost Estimate – Vapor Intrusion Assessment
Capitol Cleaners, 2101 East Capitol Drive, Shorewood, Wisconsin
WDNR BRRTS #02-41-282945**

Dear Mr. Neumann:

Stantec Consulting Services Inc. (Stantec) prepared this workplan and cost estimate to complete a vapor intrusion assessment of a tetrachloroethene (PCE) release at Capitol Cleaners, 2101 East Capitol Drive, Shorewood, Wisconsin (herein referred to as "the Site"). To ensure the additional investigation is eligible for reimbursement under the Drycleaner Environmental Response Fund, estimated costs are summarized on the attached Wisconsin Department of Natural Resources (WDNR) Form 4400-214D.

BACKGROUND INFORMATION

A single-story building covers the majority of the Site which is served by a public water supply and sewer system. The Site has operated as a dry cleaner since at least the early 1990's.

PCE was detected in soil and groundwater during a petroleum release investigation of the adjoining property to the east. An off-site exemption request was filed on September 28, 2001, and a potential responsible party (PRP) letter was sent to Capitol Cleaners on November 7, 2001. During August 2008, Northern Environmental Technologies, Incorporated (Northern Environmental) completed four soil boreholes at the Site to assess if drycleaning activities resulted in a PCE release. PCE concentrations as high as 2,590 milligrams per kilogram were detected in subsurface soil samples adjacent to an existing dry cleaner machine. Northern Environmental summarized the findings in an August 29, 2008 report. Northern Environmental also submitted the Dry Cleaner Environmental Response Program Potential Claim Notification Form 4400-210 for the Site to the WDNR during August 2008. On September 3, 2008, the WDNR provided the Site owner a letter that required investigation of the PCE detected at the Site.

Since that time, the Site owner has received Notice of Noncompliance letters (dated September 30, 2011, May 16, 2014, and May 10, 2015) from the WDNR highlighting your responsibility to investigate the degree and extent of contamination at the Site. On August 5, 2019, the WDNR sent the Site owner a "Notice of Intent to Incur Expenses" letter related to the immediate need to complete a vapor intrusion assessment at the Site and adjacent properties. On October 30, 2019, on behalf of the Site owner, Stantec contacted the WDNR and requested guidance regarding the scope of the required vapor intrusion assessment. The vapor intrusion assessment workplan outlined below is based on WDNR site-specific requests.

WORKPLAN

The additional investigation includes outdoor air, indoor air and sub-slab air sample collection at the Site and the following addresses:

- 2107 East Capitol Drive, Shorewood, WI
- 2121 East Capitol Drive, Shorewood, WI
- 3936 North Frederick Avenue, Shorewood, WI
- 3940 North Frederick Avenue, Shorewood, WI

Reference: **Workplan and Cost Estimate – Additional Investigation
Capitol Cleaners, 2101 East Capitol Drive, Shorewood, Wisconsin**

The additional investigation will be divided into the following three tasks.

- Task 1: Vapor Intrusion Assessment – Residential Properties
- Task 2: Vapor Intrusion Assessment – Commercial Properties
- Task 3: Prepare Summary Letter Report

Task 1: Vapor Intrusion Assessment – Residential Properties

The vapor intrusion assessment will include collection of indoor air samples and sub-slab vapor samples as described below.

Subtask 1.1 - Obtain Access Agreements

Stantec will assist Capitol Cleaners in obtaining access agreements to sample inside the residential properties located at 2121 East Capitol Drive, 3936 North Frederick Avenue, and 3940 North Frederick Avenue (2 total homes and 1 apartment building). Access agreements will be drafted for the property owners' review and approval.

Subtask 1.2 - Indoor Air Sampling

Stantec will collect indoor air samples from one apartment building and two homes. Stantec will collect two indoor air samples at each location, one located in the basement and one located on the ground floor. Each indoor air sample collection device (6-liter Summa canister with 24-hour flow controller) will be positioned at a height considered to represent the normal breathing zone (approximately 3 to 5 feet above the lowest floor of the house [assumed to be the basement]). Summa canisters may be placed on a desk, table, shelf, cabinet, etc. so that the sampling location is at the correct height. Collection of indoor air samples near windows or sources of outdoor air leakage will be avoided. Stantec will use a placard labeled "Do Not Disturb – Active Air Sampling". Stantec assumes home occupants will not tamper with the Summa canisters during the 24-hour sample collection time, as Stantec personnel will not be continuously monitoring each canister. After approximately 24 hours, the canisters will be sealed and collected for shipment to the project laboratory. The project laboratory will be instructed to analyze the air samples for PCE, trichloroethylene (TCE), cis-1,2-Dichloroethene, trans-1,2-Dichloroethene, and vinyl chloride using EPA Method TO-15.

Subtask 1.3 - Sub-Slab Vapor Sampling

The vapor assessment will also include the collection of sub-slab soil vapor samples from one apartment building and two homes. The samples will be collected from a sub-slab vapor point constructed using a 5/8-inch diameter VaporPin® kit. A 1.5-inch diameter drill bit will be used to allow placement of a flush mounted cover over the VaporPin® in the upper 4-inches of concrete. A 5/8-inch diameter drill bit is then used to fully penetrate the concrete floor and allow VaporPin® installation. The VaporPin® is fitted with a stainless-steel sealable hose barb to allow for sample collection.

After vapor point construction, leak testing consisting of a "shut-in test" that measures airtightness of the fittings between the sample probe and the sample container and a "helium shroud test" to measure if the vapor point seal leaks will be performed. The helium shroud test consists of using a shroud filled with helium and placed over the vapor point. Air purged from the vapor point is then tested for helium. If helium is detected, the sampling point will be resealed and retested for helium. After successful shut-in and helium shroud tests, the vapor point will be purged of one well volume at a flow rate near or less than 200 milliliters per minute. Following purging, "grab" samples will be collected at a flow rate near or less than 200 milliliters per minute using a laboratory provided 6-liter Summa canister. The project laboratory will be instructed to analyze the sub-slab air samples for PCE, TCE, cis-1,2-Dichloroethene, trans-1,2-Dichloroethene, and vinyl chloride using EPA Method TO-15.

Subtask 1.4 – Outdoor (background) Air Sampling

Stantec will also collect an outdoor ambient air sample. The outdoor air sample will be collected at an upwind location from the Site. The sample will be collected using a 6-liter Summa canister with 24-hour flow controller. If possible, the canister will be placed in a concealed location to minimize the chance of tampering. After

Reference: **Workplan and Cost Estimate – Additional Investigation**
Capitol Cleaners, 2101 East Capitol Drive, Shorewood, Wisconsin

approximately 24 hours, the canister will be sealed and collected for shipment to the project laboratory. Meteorological data will be obtained from the nearest National Weather Service station. Data will be collected for the time period corresponding to the sampling period. Data collected will include minimum and maximum temperature, barometric pressure, precipitation, and a summary of hourly wind speed and direction.

Task 2: Vapor Intrusion Assessment – Commercial Property

The vapor intrusion assessment will include collection of indoor air samples and sub-slab vapor samples from the commercial business building described below.

Subtask 2.1 - Obtain Access Agreements

Stantec will assist Capitol Cleaners in obtaining an access agreement to the samples inside the commercial building located adjacent to the east of the Site at 2107 East Capitol Drive. The access agreement will be drafted for the property owner's review and approval.

Subtask 2.2 - Indoor Air Sampling

Stantec will collect two indoor air samples at the commercial building, one located in the basement and one located on the ground floor. Indoor air sample collection will be conducted using the methods previously described in Subtask 1.2. The project laboratory will be instructed to analyze the indoor air samples for PCE, TCE, cis-1,2-Dichloroethene, trans-1,2-Dichloroethene, and vinyl chloride using EPA Method TO-15.

Subtask 2.3 - Sub-Slab Vapor Sampling

The vapor assessment will consist of collection of sub-slab soil vapor samples at two locations in the building. The sub-slab vapor point will be constructed and sampled using the methods previously described in Subtask 1.3. The project laboratory will be instructed to analyze the sub-slab air samples for PCE, TCE, cis-1,2-Dichloroethene, trans-1,2-Dichloroethene, and vinyl chloride using EPA Method TO-15.

Task 3: Prepare Summary Letter Report

Vapor analysis results will be tabulated, and the site figures will be updated to reflect the additional investigation completed. The results will be summarized in a letter report that will be submitted to the WDNR.

PROBABLE SCHEDULE AND COST

The scope of work outlined above will be completed in phases. Task 1 and 2 will be initiated immediately after approval of this workplan and cost estimate by the WDNR. The schedule for collection of air samples inside the homes and business buildings will be dependent upon off-site access approval and may vary. If air samples indicate a health risk to home/building occupants, Task 3 will be delayed and a workplan and cost estimate would be prepared to install a mitigation system in the affected building(s). If indoor air sampling does not indicate a health risk to any homes/buildings Tasks 3 would then be completed.

The cost presented below is based on the quantities listed in the workplan. For budgeting purposes, the proposed work will be divided into cost categories consistent with the WDNR Linking Spreadsheet with off-site access coordination, data tabulation, and reporting incorporated into the various cost categories. A summary of probable costs are included on the enclosed WDNR Form 4400-214D. The probable costs are presented below.

WDNR Linking Spreadsheet Cost Category E – Air/Vapor Investigation

Consulting Services

Associate Geologist	1 hour @ \$191/hr	\$ 191.00
Senior Geologist/Project Manager	16 hours @ \$158/hr	\$ 2,528.00
Registered Geologist	2 hours @ \$127/hr	\$ 254.00
Staff Geologist	52 hours @ \$122/hr	\$ 6,344.00
GIS/CAD Technician	4 hours @ \$115/hr	\$ 460.00

Reference: **Workplan and Cost Estimate – Additional Investigation
Capitol Cleaners, 2101 East Capitol Drive, Shorewood, Wisconsin**

Geologist I	2 hours @ \$111/hr	\$ 222.00
Administrative Aid	6 hours @ \$103/hr	<u>\$ 618.00</u>
	Subtotal	\$10,617.00

Vapor Point Construction Supplies

Vapor Pin	5 each @ \$50/each	\$ 250.00
Helium Detector Rental	2 days @ 100/day	\$ 200.00
Coring Drill Rental	3 days @ \$45/day	<u>\$ 135.00</u>
	Subtotal	\$585.00
	Cost Category E Total	\$11,202.00

WDNR Linking Spreadsheet Costs Category G - Laboratory Analysis

<u>Air VOCs</u>	14 samples @ \$190/each	<u>\$ 2,660.00</u>
	Subtotal	\$2,660.00
	Cost Category G Total	\$ 2,660.00

TOTAL COSTS CATEGORIES E AND G **\$13,862.00**



November 13, 2019
Page 5 of 5

Reference: **Workplan and Cost Estimate – Additional Investigation
Capitol Cleaners, 2101 East Capitol Drive, Shorewood, Wisconsin**

Please contact us if you have any questions or comments.

Regards,

STANTEC CONSULTING SERVICES INC.

Chris Hatfield
Senior Geologist
Phone: (262) 643-9171
Fax: (262) 241-8222
Chris.Hatfield@stantec.com

Attachments

Client Approval

I, Juan Han, approve the scope and probable costs presented above.

Grantlan Couner
Signature – Title

11/21/19
Date

Enclosures

c: Gene Han, Capitol Cleaners

Site Name: Capitol Cleaners
 BRRTS #: 02-41-282945
 Type of Action: Vapor Intrusion Assessment

Dry Cleaner Environmental Response Program
 Reimbursement Cost Detail Linking Spreadsheet Form 4400-214D (R 08/12)

TASKS	BUDGET			INVOICES					DERF COST BREAKOUT (this claim)								Budget Remaining Use (-) to indicate cost over-run	% Task Complete, Remarks		
	Bid / Budgeted Amount	INSERT	Total Approved Budget	Previous Claims (if applicable)	Provider Name, Invoice #, Billing Date	Provider Name, Invoice #, Billing Date	Provider Name, Invoice #, Billing Date	Provider Name, Invoice #, Billing Date	INSERT	Total Invoiced Costs	A Soil Investigation	B Soil Remediation	C Groundwater Investigation	D Groundwater Remediation	E Air/Vapor Investigation	F Air/Vapor Remediation			G Lab & Other Analysis	H Miscellaneous Costs
Consultant Costs																				
Task			\$ -						\$ -										\$ -	Task % Complete
Air/Vapor Sampling	\$ 11,202.00		\$ 11,202.00						\$ -						\$ 11,202.00				\$ 11,202.00	
			\$ -						\$ -										\$ -	
			\$ -						\$ -										\$ -	
			\$ -						\$ -										\$ -	
			\$ -						\$ -										\$ -	
			\$ -						\$ -										\$ -	
Consultant Cost Total	\$ 11,202.00	\$ -	\$ 11,202.00	\$ -					\$ -										\$ 11,202.00	
Sub-Contractor Costs																				
Laboratory	\$ 2,660.00		\$ 2,660.00						\$ -								\$ 2,660.00		\$ 2,660.00	
			\$ -						\$ -										\$ -	
			\$ -						\$ -										\$ -	
			\$ -						\$ -										\$ -	
			\$ -						\$ -										\$ -	
Sub-Contractor Cost Total	\$ 2,660.00	\$ -	\$ 2,660.00	\$ -					\$ -										\$ 2,660.00	
DERF ELIGIBLE SUB-TOTALS	\$ 13,862.00	\$ -	\$ 13,862.00	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 11,202.00	\$ -	\$ 2,660.00	\$ -	\$ 13,862.00	
Non-DERF Eligible Expenses									\$ -											
									\$ -											
Non-DERF Cost Total			\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -										\$ -	
INVOICE GRAND TOTAL			\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -										\$ -	

Total DERF Eligible Costs This Claim \$ 13,862.00