

ATTN. <u>Don Miller - S.W.</u>	<input type="checkbox"/> PRETREATMENT WW/2	Date <u>12 10 92</u> M M D D Y Y
<input type="checkbox"/> ENV. ENF. EE/5	<input type="checkbox"/> MUNIC. WASTEWATER SECTION WW/2	Time (24-Hour Clock) <u>21:00</u>
<input type="checkbox"/> PRIV. WATER SECTION WS/2	<input type="checkbox"/> IND. WASTEWATER SECTION WW/2	Contact Method <input checked="" type="checkbox"/> In Person <input type="checkbox"/> Telephone
<input type="checkbox"/> PUBL. WATER SECTION WS/2	<input type="checkbox"/> _____ DISTRICT	

Facility Name <u>C.M. Christensen Co.</u>	Location (Address or 1/4-1/4) <u>Phelps WI</u>	County <u>Uilas</u>
Facility I.D. Or Wis. Unique Well Number _____	WPDES Permit Number _____	District No. <u>7</u>
Facility Representative Contacted <u>None</u>	Title or Position of Representative _____	DNR Person Making Contact <u>Guy Hansen</u> <u>715-369-8939</u>
Activity Codes <u>OW</u>	Representative's Telephone Number (including area code) <u>cc - Don Miller - S.W.</u> <u>Kenby Falstad - LF</u> <u>Bill Jerge - WRM</u> <u>Chuck Fitzgerald - W.S.</u>	

Complaint voiced by 3-4 Phelps residents after a public meeting re upgrading the waste water treatment plant. This company, mailing address - 1 Lake St, Phelps, is now owned/run by Phil (P.C.) Christensen. It is not ~~the~~ active now but once was a saw mill, a "treating plant" - where they treated poles in creosote/penta and a "chemical plant" - where they made charcoal and wood alcohol.

Residents are concerned that contaminated G.W. from this site will contaminate the lake (it was located on the N.E. end of N. Twin Lake).

The company buildings are torn down or removed there may be no reference points to I.D. potential contaminated soil sites ^{also} ~~add~~ spills/damage may occur. eg - the dip tank (where poles were placed in vertically) was removed last summer - was DNR aware/there?

Possible contacts in Phelps: - they discovered the sanitary sewer had not been connected to the sanitary sewer system - but was a straight pipe to the Creek - was DNR aware? Check if Additional Sheets Attached (no)
Tom Rick - S.D. Bd. Sec.
Bud Petrick - WSP p.
E.S. Obenlerner - former S.D. Bd. Pres.
Now what?

ACTIVITY CODES

Wastewater

Assistance

AL Laboratory Assistance
AO O & M Assistance
SA Sludge Assistance
PT Pretreatment Assistance
PA Planning Assistance
PR Confer with Officials on Permit Req.
CM Compliance Maintenance

Enforcement

VI Violation Identified by Inspector
VM Minor Violation follow-up
VS Significant Violation Follow-up
CP Compliance Schedule Progress Check

Wastewater - General

OW Other Wastewater

Evaluation

LE Laboratory Evaluation
AG Agricultural Waste Investigation
SD Sludge Disposal Site Inspection
OE Operator Evaluation
CI Facility Complaint Investigation
SP Spills/Plant Upsets

Compliance Monitoring

CC Compliance Check
CE Compliance Evaluation Inspection
CS Compliance Sampling Inspection
PI Performance Audit Inspection
GW Groundwater Monitoring System Inspection
PC Pretreatment Compliance Monitoring
LD Land Disposal System Inspection
CG Construction Grant Inspection

Water Supply

GC G.W. Contamination Investigation Follow-up
WO Waterworks Operator Evaluation
WC WD/PI Contact
CT Compliance Contact including Noncompliance/
Violation Follow-up
RC Plan Review Contact
CI Complaint Investigation
SS Sanitary Survey

AI Annual Inspection - Municipal
PP Public Presentation
OT O & M Technical Assistance
EC Enforcement Conferences/Contact
EE Environmental Emergencies/Spill
OR Other

District Number Codes

1 Southern
2 Southeast
4 Lake Michigan
6 Western
7 North Central
8 Northwest

Special Instructions

Time - when unknown code: 00:00

Facility Contact - when facility representative not available code: NONE (i.e., during site visit no one at facility)

1 OCT 92R02

9/28/92



Military CR. Sed. sampling site #2 looking up stream below foot bridge site A below stream

2 OCT 92R02

9/28/92



Military CR. sediment sampling site #2. Looking down stream toward site A above Hwy N.

3 OCT 92R02

9/28/92



Military creek sed. samp. site #3 looking Down stream (Below Hwy N)

4 OCT 92R02

9/28/92



Military creek sed. samp. site #3 Looking upstream (Below Hwy N)

5 OCT 92R02



9/28/92 Military creek. Taken from "N" S.W. Direction

6 OCT 92R02



9/28/92. Military CR taken at conf. with N. Twin Lake shot taken upstream (site #4)

7 OCT 92R02



9/28/92 - Military CR. conf. with N. Twin Lake - Sed. Sampling

8 OCT 92R02

shot taken N.W. direction



9/28/92. Sed. samp. Mil. Creek Christensen Prop. Looking west. Mil. creek flows adjacent to Bldg

9 OCT 92R02

Shoot Looking N-creek runs E to W.



9/28/92 - sed. sampling military CR Christensen pole 70

Not a electron

Field Field

parts per mill

Field 1.4
Field 2.4
Field 3.4
Field 4.4

126,000 parts per mill
13,700 parts per mill



1 – Military creek sediment sampling site # 2 looking upstream below foot bridge. Site above N below pole drying area.



2 – Military Creek sediment sampling site # 2 looking downstream toward N. Site above Hwy N.



3 - Military Creek sediment sampling site # 3 looking downstream. Below Hwy N.



4 – Military Creek sediment sampling site # 3 looking upstream. Below Hwy N.



5 – Military Creek taken from N, SW direction.



6 – Military Creek taken at conference with North Twin Lake. Shot taken upstream site # 4.



7 – Military Creek conference with North Twin Lake – sediment sampling.



8 – Shot in Northwest direction. Sediment sampling Military Creek Christiansen property looking West. Military Creek flows adjacent to building.



9 – Shot looking North, creek runs East to West. Sediment sampling Military Creek Christianson Pole yard.