



Soil & Plant Analysis Laboratory, 806 South Park Street, Madison, Wisconsin 53715; 608-262-4364

DEPARTMENT OF SOIL SCIENCE

August 18, 1981
Acct. 900
Lab No. 8E0020

RECEIVED

AUG 18 1981

Northwest District
Headquarters

MEMORANDUM

TO: Barry O'Flanagan
DNR, Box 309
Spooner, WI 54801

FROM: Soil/Plant Analysis Lab

RE: Results of analyses performed on 5 soil samples submitted Aug. 3.

Sample No.	pH	Cl ⁻	NO ₃ ⁻ -N
		-----ppm-----	
✓ 2	3.5	8.5	5.0
✓ 4	5.6	4.0	75.5
✓ 5	4.1	10.0	2.5
✓ 6	7.0	7.0	-0.5
✓ 8	7.2	7.0	1.5

"-" values = less than.

If you have any questions concerning these analyses, please feel free to contact us.

Encl.

/sf

Du Pont Rockdale works

Sample Analysis: 8/3/81

4 water samples analyzed
remaining liquid discarded

5 soil samples:

6 to be analyzed for exotics
by RAL Tech. - not all exotics
only what they have standard for.

4 to be analyzed for TMX by
RAL TECH if they have procedure
and standards

5 samples taken to university soils
lab for pH, NO_3^- and Cl^-

8 to be analyzed for Pb, Cd,
& Cr by LOH.