

Aniwa Arsenic Site Visit
September 2, 2014
Tauren Beggs, DNR & Kathy Halbur, EPA



Gated entrance, Gate was unlocked, facing north



No Trespassing Sign & Woodpost/Wire Fence, Fencing was minimal, Trail by fence



Entering property looking north at former shed and buried drum areas



Well B-19 location, facing north




Well B-10 location, facing west-northwest



Well B-18, facing northwest



May 1984 Buried Drum Excavation Area, Trail running through this area, facing south



Well B-13a on left, Well B-13 on right, Used Geoprobe sample tubes next to B-13a, facing northwest



Well B-12, facing southeast



Well B-10 location, Wetland in background, facing north



Wetland, facing north



Well B-21 in Marsh Road ROW, facing northwest towards site



Well B-21 on left, Marsh Road, facing east