

Saliars, Gwen N - DNR

From: Saliars, Gwen N - DNR
Sent: Tuesday, February 22, 2022 9:49 AM
To: Andy Delforge
Cc: Tammy Resch
Subject: Closure Packet Revision for Aniwa Arsenic Site, BRRTS #02-59-000198

Andy,

My coworkers noticed another small revision that is needed to the cap maintenance plan (D.1). One of the revisions was to combine Figures D.2.a and D.2.b into Figure D.2, and then change the reference under the Description of Cap section. You did complete this revision but it was noticed that under the Annual Inspection section along with list of attachments at the end of D.1 it still lists the original figures instead of just Figure D.2. I apologize for not pointing out the other spots the change was needed when I sent the original list of revisions to you.

Can you make those changes and resubmit the revised D.1 via email? I included screen shots of the spots that need fixing.

Annual Inspection


The clay cap overlying the soil and as depicted in **Figure D.2.a** will be inspected once a year, normally in the spring after all snow and ice is gone, for deterioration, cracks and other potential problems that can cause additional infiltration into and exposure to underlying soils. The inspections will be performed by the property owner or their designated representative. The inspections will be performed to evaluate damage due to settling, exposure to the weather, erosion, and other factors. Any area where soils have become or are likely to become exposed and where infiltration from the surface will not be effectively minimized will be documented.

A log of the inspections and any repairs will be maintained by the property owner and is included as D.4, Form 4400-305, Continuing Obligations Inspection and Maintenance Log. The log will include recommendations for necessary repair of any areas where underlying soils are exposed and where infiltration from the surface will not be effectively minimized. Once repairs are completed, they will be documented in the inspection log. A copy of the maintenance plan and inspection log will be kept at the Town of Aniwa hall and available for submittal or inspection by Wisconsin Department of Natural Resources (DNR) representatives upon their request.

Contact Information

October 2021

Site Owner and Operator: Town of Aniwa – Dan Lex, Chairman
N10485 Cherry Road
Aniwa, WI 54414
(715) 449-2114

Signature: 

Consultant: REI Engineering, Inc – Andrew Delforge Project Manager
4080 North 20th Avenue
Wausau, WI 54401
(715) 675-9784

DNR: Gwen Saliaries
625 East County Road Y, Suite 700
Oshkosh, WI 54901
(920) 510-4343

- D.2 Location Maps
 - D.2.a – Residual Soil Contamination and Clay Cap to be Maintained
 - D.2.b – Residual Groundwater Contamination
- D.3 Photographs of Cover/Barrier
- D.4 Continuing Obligations Inspection and Maintenance Log

Reach out with any questions. Thank you for your continued work on the closure request.

We are committed to service excellence.

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

Gwen Saliaries

Hydrogeologist

Remediation and Redevelopment Program

Wisconsin Department of Natural Resources

625 E County Rd Y, STE. 700

Oshkosh, WI 54901

Phone: (920) 510-4343

gwen.saliaries@wisconsin.gov



dnr.wi.gov

