

Attachment 1. Barrier Inspection and Maintenance Log, 3M Parking Lot, Wausau, Wisconsin.

Date	Inspector	Condition of Cap (Excellent, Good, Fair, Poor)	Recommendations	Required Repairs	Has recommended maintenance from the previous inspection been implemented?
4-24-15	MARK MEURETTE	GOOD	NONE	NONE	NA

