

Field & Technical Services

200 Third Avenue • Carnegie, PA 15106 • Phone: 412-429-2694 • Fax: 412-279-4512

December 6, 2021

Mr. John Sager Wisconsin Department of Natural Resources 1701 N 4th Street Superior, WI 54880

Re: Summary of 2021 Sign Inspection Activities Koppers Inc. Facility Superior, Wisconsin

Dear Mr. Sager:

On behalf of Beazer East, Inc. (Beazer), Field & Technical Services, LLC (FTS) is pleased to submit this letter summarizing the results of the October 2021 inspection of warning signs posted along the tributary to Crawford Creek (formerly referred to as Outfall 001 drainage ditch) and select areas within the Crawford Creek floodplain located near the Koppers Inc. (KI) facility in Superior, Wisconsin.

In the fall of 2001, at the request of the Wisconsin Department of Natural Resources (WDNR), Beazer posted warning signs along the tributary to Crawford Creek and a portion of the Crawford Creek floodplain located near the KI facility in Superior, Wisconsin. In September 2005, 68 new signs reflecting updated contact information for the WDNR and Douglas County Department of Health and Human Services were posted, and all of the old signs were removed. In general, signs are posted at approximately 250-feet intervals along both sides of the tributary to Crawford Creek from the KI property boundary downstream to the confluence with the Crawford Creek floodplain, and along both sides of the Crawford Creek floodplain from Hammond Avenue downstream to the railroad crossing. Additional signs are posted at potential access areas, such as near roads, hunting stands, bridges, and railroad tracks.

Since the warning signs were initially posted in 2001, periodic inspections have been made to identify damaged, disoriented, and/or missing signs. The most recent sign inspection was conducted on October 5, 2021. During the inspection, a total of 3 warning signs were reattached. A total of 7 warning signs were reported missing. New signs were ordered and shall be replaced during the next inspection event anticipated to occur in April 2022. The remaining 61 warning signs were observed to be in good condition.

Page 2

The construction fencing installed around the tributary to Crawford Creek from Hammond Avenue to the railroad crossing in September 2005 was inspected on October 5, 2021. During the October 5, 2021 inspection, the construction fencing was found in general good condition. Construction fencing was re-secured to existing posts where necessary during the inspection.

Please feel free to contact Jane Patarcity of Beazer at (412) 208-8813 or the undersigned at (412) 428-9397 if you have any questions or comments regarding the sign inspection activities summarized above.

Sincerely,

Field & Technical Services, LLC

Hank Pappert Project Manager

cc: Henry Nehls-Lowe - WDHFS Jane Patarcity-Beazer Ray Stevenson-ARCADIS David Bessingpas-ARCADIS

