



MEMO

To: File
From: Liz Victor
Site Name/BRRTS: Kewaunee Marsh Arsenic Spill (02-31-000508)
Re: Field Activities Report for **August 20, 2018**

Who: Liz Victor, DNR RR NER

Purpose of Field Visit: Read Staff Gage

Special Equipment: DNR's Canon Powershot SX 210 IS

Scope of Work for Field Visit:

- Measure both staff gages for comparison of elevations.

Work Performed: see above

Comments:

- Accessed site via public access from east end of trail.
- There were ripples on the surface of the water so several photos were taken and the photo used for elevations represented "average" conditions.

Data Collected: The collected data is attached.

Attachments:

- Photo of staff gage with notes.

Readings from
8/20/18




Water level = ~~582.78~~
581.33

West Staff Gage

Difference in
elevations =
582.18
- 581.33

85'



↓ E. Staff Gage:

Water
level =
582.18

4.84