From:	Michalets, Linda M - DNR
Sent:	Thursday, March 23, 2023 3:28 PM
То:	donald.dgallolaw@gmail.com
Cc:	James Drought (James.Drought@gza.com)
Subject:	Milwaukee Plating site, BRRTS #02-41-000826 Status Request

Hello Don,

Could you please provide me a with status update for the investigation of the TCE contamination at Milwaukee Plating? At this time, the contamination from the TCE degreaser source needs to be defined in soil and groundwater. In addition, the vapor pathway needs to be investigated, as the utilities within the alley adjacent to Milwaukee Plating extend to the south and appear to have entry into the 1422 building to the south.

The vapors from above ground at the degreaser also must be mitigated such that they do not pose a threat as fugitive emissions that enter the 1422 building to the south. I understand that degreaser repairs were being made earlier this year. Please provide an update to that as well.

Your prompt attention to this matter is appreciated.

Regards, Linda

## We are committed to service excellence.

Visit our survey at <u>http://dnr.wi.gov/customersurvey</u> to evaluate how I did.

Linda Michalets she/her/hers Hydrogeologist – Remediation and Redevelopment Program Wisconsin Department of Natural Resources 1027 W. St. Paul Ave. Milwaukee, WI 53233 Phone: 414-435-8010 <u>linda.michalets@wisconsin.gov</u>

