

**From:** [Vater, Katherine](#)  
**To:** [Koepke, Cynthia L - DNR](#)  
**Cc:** [Perkins, Thomas](#); [Braga, Wesley](#)  
**Subject:** RHL - MW Freeze Protection Inspection - December  
**Date:** Wednesday, December 23, 2020 12:29:52 PM  
**Attachments:** [image001.png](#)

---

Cindy –

Tom completed the inspection of the RHL monitoring wells with packers on Friday 12/18 and today (Wednesday 12/23). He inspected to wells for any sign of water/ice above the packer. Here is a summary of the inspection:

P-8BR – Freeze protection is working and the well is not flowing.  
P-9D – Freeze protection is working and the well is not flowing.  
P-31IA – Freeze protection is working and the well is not flowing.  
P-31IB – Freeze protection is working and the well is not flowing.  
P-31D – Freeze protection is working and the well is not flowing.  
P-33D – Freeze protection is working and the well is not flowing.  
P-24D – Freeze protection is working and the well is not flowing.  
P-24E – Freeze protection is working and the well is not flowing.  
P-36S – Freeze protection is working and the well is not flowing.  
P-36D – Freeze protection is working and the well is not flowing.

We will inspect the wells again in January.

Please let me know if you have any questions.

Thanks,  
Kat

**Katherine Vater, PE (WI)**  
Project Manager



708 Heartland Trail, Suite 3000, Madison, WI 53717  
T 608-826-3663 | C 608-807-8968 | [kvater@trccompanies.com](mailto:kvater@trccompanies.com)  
[LinkedIn](#) | [Twitter](#) | [Blog](#) | [TRCcompanies.com](http://TRCcompanies.com)

**From:** [Vater, Katherine](#)  
**To:** [Koepke, Cynthia L - DNR](#)  
**Cc:** [Perkins, Thomas](#); [Braga, Wesley](#)  
**Subject:** RHL - MW Freeze Protection Inspection - January  
**Date:** Thursday, January 21, 2021 2:04:54 PM  
**Attachments:** [image001.png](#)

---

Cindy –

Tom completed the inspection of the RHL monitoring wells with packers on Tuesday 1/19 and Wednesday 1/20. He inspected to wells for any sign of water/ice above the packer. Here is a summary of the inspection:

P-8BR – Freeze protection is working and the well is not flowing.  
P-9D – Freeze protection is working and the well is not flowing.  
P-31IA – Freeze protection is working and the well is not flowing.  
P-31IB – Freeze protection is working and the well is not flowing.  
P-31D – Freeze protection is working and the well is not flowing.  
P-33D – Freeze protection is working and the well is not flowing.  
P-24D – Freeze protection is working and the well is not flowing.  
P-24E – Freeze protection is working and the well is not flowing.  
P-36S – Freeze protection is working and the well is not flowing.  
P-36D – Freeze protection is working and the well is not flowing.

We will inspect the wells again in February.

Please let me know if you have any questions.

Thanks,  
Kat

**Katherine Vater, PE (WI)**  
Project Manager



708 Heartland Trail, Suite 3000, Madison, WI 53717  
T 608-826-3663 | C 608-807-8968 | [kvater@trccompanies.com](mailto:kvater@trccompanies.com)  
[LinkedIn](#) | [Twitter](#) | [Blog](#) | [TRCcompanies.com](http://TRCcompanies.com)

**From:** [Vater, Katherine](#)  
**To:** [Koepke, Cynthia L - DNR](#)  
**Cc:** [Perkins, Thomas](#); [Braga, Wesley](#)  
**Subject:** RHL - MW Freeze Protection Inspection - February  
**Date:** Thursday, February 25, 2021 8:54:00 AM  
**Attachments:** [image001.png](#)

---

Cindy –

Tom completed the inspection of the RHL monitoring wells with packers on Wednesday 2/24. He inspected to wells for any sign of water/ice above the packer. Here is a summary of the inspection:

P-8BR –Freeze protection is working and the well is not flowing.  
P-9D – Freeze protection is working and the well is not flowing.  
P-31IA –Freeze protection is working and the well is not flowing.  
P-31IB – Freeze protection is working and the well is not flowing.  
P-31D – Freeze protection is working and the well is not flowing.  
P-33D – Freeze protection is working and the well is not flowing.  
P-24D – Freeze protection is working and the well is not flowing.  
P-24E – Freeze protection is working and the well is not flowing.  
P-36S – Freeze protection is working and the well is not flowing.  
P-36D – Freeze protection is working and the well is not flowing.

We will inspect the wells again in March for the last time this winter.

Please let me know if you have any questions.

Thanks,  
Kat

**Katherine Vater, PE (WI)**  
Project Manager



708 Heartland Trail, Suite 3000, Madison, WI 53717  
T 608-826-3663 | C 608-807-8968 | [kvater@trccompanies.com](mailto:kvater@trccompanies.com)  
[LinkedIn](#) | [Twitter](#) | [Blog](#) | [TRCcompanies.com](http://TRCcompanies.com)

**From:** [Vater, Katherine](#)  
**To:** [Koepke, Cynthia L - DNR](#)  
**Cc:** [Perkins, Thomas](#); [Braga, Wesley](#)  
**Subject:** RHL - MW Freeze Protection Inspection - March  
**Date:** Wednesday, March 17, 2021 9:17:23 AM  
**Attachments:** [image001.png](#)

---

Cindy –

Tom completed the inspection of the RHL monitoring wells with packers on Monday 3/15. He inspected to wells for any sign of water/ice above the packer. Here is a summary of the inspection:

P-8BR –Freeze protection is working and the well is not flowing.  
P-9D – Freeze protection is working and the well is not flowing.  
P-31IA –Freeze protection is working and the well is not flowing.  
P-31IB – Freeze protection is working and the well is not flowing.  
P-31D – Freeze protection is working and the well is not flowing.  
P-33D – Freeze protection is working and the well is not flowing.  
P-24D – Freeze protection is working and the well is not flowing.  
P-24E – Freeze protection is working and the well is not flowing.  
P-36S – Freeze protection is working and the well is not flowing.  
P-36D – Freeze protection is working and the well is not flowing.

This completes our inspections for winter 2020-2021. We will resume the inspections in December 2021.

Please let me know if you have any questions.

Thanks,  
Kat

**Katherine Vater, PE (WI)**  
Project Manager



708 Heartland Trail, Suite 3000, Madison, WI 53717  
T 608-826-3663 | C 608-807-8968 | [kvater@trccompanies.com](mailto:kvater@trccompanies.com)  
[LinkedIn](#) | [Twitter](#) | [Blog](#) | [TRCcompanies.com](http://TRCcompanies.com)