

04-36-039873

STATE DIV. EMERGENCY GOVT. 608/266-3232
U.S. NAT'L. RESPONSE CENTER 800/424-8802
CHEMTREC/PESTICIDES/CHLORINE 800/424-9300

04-36-039873

DATE OF INCIDENT 8-6-84	DAY OF WEEK MON	TIME OF INCIDENT 7.15 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	REPORTED BY (NAME) Tom Santy	TELEPHONE NUMBER 414 1793-1161
----------------------------	--------------------	---	---------------------------------	-----------------------------------

DATE REPORTED 8-6-84	DAY OF WEEK MON	TIME REPORTED 8.00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	AGENCY OR FIRM REPORTING Paragon Electric	REPORTED THRU DIV. EMERGEN. GOVT. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
-------------------------	--------------------	--	--	--

SUBSTANCE INVOLVED Trichloroethylene	QUANTITY 30	UNITS gal	PERSON OR FIRM RESPONSIBLE Paragon Electric
SUBSTANCE INVOLVED	QUANTITY	UNITS	CONTACT NAME Tom Santy
			TELEPHONE NUMBER 1

PHYSICAL CHARACTERISTICS
 SOLID LIQUID COLOR _____
 SEMISOLID GAS ODOR _____

ADDRESS - STREET OR ROUTE
606 Park Way Blvd

CITY, STATE, ZIP CODE
Two Rivers WI.

CAUSE OF INCIDENT
pumping hose failure

ACTION TAKEN BY SPILLER
NO ACTION NO NOTIFICATION DELAYED NOTIFICATION
 TAKEN CONTAINMENT; TYPE _____
 CLEANUP; METHOD _____
 DISPOSAL; LOCATION _____
 FIRE DEPARTMENT ACTION _____
 CONTRACTOR HIRED; NAME _____
 OTHER ACTION _____

EXACT LOCATION DESCRIPTION (INTERSECTION, MILEAGE, ETC.)
606 Parkway plant

COUNTY LOCATION
Manitowish

1/4, 1/4, SECTION, TOWN, RANGE
_____, _____, _____, T _____ N, R _____

DNR DISTRICT
LND

DNR AREA
GB

SURFACE WATERS AFFECTED
 YES NO POT

DRAIN BASIN

NAME OF SURFACE WATER

NEAREST SURF. WATER _____ FT.

NEAREST STORM SEWER _____ FT.

WEATHER CONDITIONS

TEMPERATURE _____ °F

WIND SPEED _____ MPH

DIRECTION OF WIND _____

PRECIPITATION: YES NO

DIRECTION OF SPILL MOVEMENT _____

DATE DISTRICT NOTIFIED 8-6-84	DAY OF WEEK	TIME DISTRICT NOTIFIED <input type="checkbox"/> AM <input type="checkbox"/> PM	DISTRICT PERSON NOTIFIED Jim Reburn	TELEPHONE NUMBER 1 497-4397
----------------------------------	-------------	---	--	--------------------------------

DATE INVESTIGATED	DAY OF WEEK	TIME INVESTIGATED <input type="checkbox"/> AM <input type="checkbox"/> PM	PERSON INVESTIGATING Jim Reburn	TELEPHONE NUMBER 1
-------------------	-------------	--	------------------------------------	-----------------------

ACTION TAKEN BY DNR
 NO ACTION TAKEN INVESTIGATION 29.29 ENFORCEMENT
 CONTAINMENT; TYPE _____
 CLEANUP; METHOD _____
 SUPERVISE CLEANUP (PERSON) _____
 DISPOSAL; LOCATION _____

LIST HUMAN HAZARDS OR CASUALTIES
 REAL POTENTIAL NONE

ENVIRONMENTAL HAZARD/DAMAGE
 REAL POTENTIAL

VEGETATION _____
 FISH _____
 WILDLIFE _____
 BIRDS _____
 OTHER _____
 NONE _____

OTHER AGENCIES ON SCENE

LOCAL _____

STATE _____

FEDERAL _____

PERSON FILING THIS REPORT (PRINT NAME)
James Reburn

SIGNATURE
James Reburn

DATE SIGNED
8-6-84

ADDITIONAL COMMENTS:
Pumping trichlor from tanker truck to storage tank when hose failed. 30 gallons spilled on blacktop and grass area. Spill was contained with absorbant and cleaned up. No surface water affected.

up to class
4-10-13
H. Howard

8/6/1984

04-36-039873

04-36-039873

SITE NAME Paragon Electric Company, Chgo. Toxic Spill	MAP SITE NUMBER Rd. yellow-12
LOCATION COUNTY Manitowoc	TOWNSHIP N ¹ / ₂ N ¹ / ₂ 1/4 1/4 SEC 11 T19 N R24 E
STREET ADDRESS 606 Parkway Blvd. Two Rivers, WI.	SITE OWNER/MANAGER ADDRESS Tom Mulhane P.O. Box 28 Two Rivers, WI. 54241
MUNICIPALITY CITY VILLAGE <input checked="" type="checkbox"/> TOWN Two Rivers	
DNR PROGRAM Solid Waste	
DECIPTION OF HAZARDOUS SUBSTANCE/CONTAMINATION TYPE	


COMMENTS: AMOUNT OF CONTAMINATION, DATE OF INCIDENT, CLEANUP ACTIONS TAKEN

Two spill incidents have occurred in the past that may have contaminated the soil material adjacent to the Paragon plant.

1) winter 1983, 35 to 40 gallons of TCE (Trichloroethylene) leaked onto the paved storage area after puncturing of the drums. Most of the material evaporated.

2) 8/4/84, 25 to 30 gallons of TCE spilled from a tanker truck.

STS is in the process of sampling the soil and clean-up.



TWO RIVERS