

Spill ID Number  
04-16-042495  
Y Y M M D D 0-99

Date of Incident <u>1-11-88</u>	Day of Week <u>Mon</u>	Time of Incident <u>9:00</u>	<input type="checkbox"/> A.M. <input checked="" type="checkbox"/> P.M.	Reported By (Name) <u>Rick Sandath</u>	Telephone Number <u>(715) 392-5631</u>
Date Reported <u>1-12-88</u>	Day of Week <u>Tue</u>	Time Reported <u>1:15</u>	<input checked="" type="checkbox"/> A.M. <input type="checkbox"/> P.M.	Agency or Firm Reporting <u>Lakehead Pipe Line</u>	Reported thru Div. Emergen. Gov't. <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Substance Involved <u>Crude Oil</u>	Quantity <u>175</u>	Units <u>Barrel</u>	Person or Firm Responsible <u>Lakehead Pipe Line</u>	Contact Name <u>Jon E Staudohar</u>	Telephone Number <u>(715) 392-5631</u>

Physical Characteristics

Solid  Liquid  Semisolid  Gas

Color Black Odor oil

Address - Street or Route  
119 W. 25th St. E. P.O. Box 789

City, State, Zip Code  
Superior, WI, 54880

Cause of Incident  
Pressure put on valve not open while pumping

Exact Location Description (intersection, mileage, etc.)  
At the end of E 21st St. Pump Station

County Location  
Douglas 36, T 49N, R 14W

DNR Dist. N.W. Buile Groundwaters Affected  Yes  No  Potential

Surface Waters Affected  Yes  No  Potential Name of Surface Water \_\_\_\_\_

Action Taken By Spiller

No Action  Notification  Investigate

Taken  Containment; Type Dam w ditches

Cleanup; Method VAC trucks

Amount Recovered 7000 gals

Monitor \_\_\_\_\_

Contractor Hired; Name Baywest

Other Action Lakehead Clean up Crews

Date District Notified  
1-12-88

Day of Week  
Tue

Time District Notified  
9:00

A.M.  P.M.

District Person Notified  
John Menke

Telephone Number  
(715) 635-4151

Date Investigated  
1-12-88

Day of Week  
Tue

Time Investigated  
1:45

A.M.  P.M.

Person Investigating  
Joe Davidowski

Telephone Number  
(715) 392-7988

Spill Location

Industrial Facility/Paper Mill/Chem. Co.

Gas/Service Station/Garage, Auto Dealer, Repair Shop

Ag Coop/Facility/Cheese Factory/Creamery

Other Small Business (bank, grocery, insurance co., etc.)

Public Property (city, county, state, church, school, etc.)

Utility Co., Power Generating/Transfer Facility

Private Property (home/farm)

Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler

Transportation Accident, Fuel Supply Tank Spill

Transportation Accident, Load Spill

Construction, Excavation, Wrecking, Quarry, Mine

Other \_\_\_\_\_

Action Taken By DNR

No Action Taken  Investigation  Supervise/Conduct Cleanup

Spiller Required To Take Action; Type \_\_\_\_\_

Contractor Hired By DNR; Name \_\_\_\_\_

Amount Recovered \_\_\_\_\_

29.29 Enforcement

Spilled Substance Destination

Air  Soil

Groundwater

Surface Water

Storm Sewer

Sanitary Sewer

Contained/Recovered

Other \_\_\_\_\_

Other Agencies on Scene

Local Fire Dept.

State D.N.R.

Federal Coast Guard

Person Filing This Report (print name)  
Joseph E Davidowski

Signature Joseph E Davidowski Date Signed 1-12-88

Additional Comments:  
Crews from Lakehead and Baywest doing very good job on clean up. Took over 4 hrs from time of spill to time Madison notified me. Madison was notified about 1:00 to 1:15 AM spill was at 9:00 PM evening of 1-11-88.