

State Div. Emergency Gov't. (608) 266-3232  
U.S. Nat'l. Response Center (800) 424-8802  
Chemtrec/Pesticides/Chlorine (800) 424-9300

Spill ID Number  
891025-07  
Y Y M M D D 0-99

04-88-044170

Date of Incident <u>10-25-89</u>	Day of Week <u>Wed.</u>	Time of Incident <u>10:30</u>	<input type="checkbox"/> A.M. <input checked="" type="checkbox"/> P.M.	Reported By (Name) <u>Dr. Len Moore</u>	Telephone Number <u>(715) 735-9033</u>
Date Reported <u>10-25-89</u>	Day of Week <u>Wed</u>	Time Reported <u>3:25</u>	<input type="checkbox"/> A.M. <input checked="" type="checkbox"/> P.M.	Agency or Firm Reporting <u>Specialty Chem</u>	Reported thru Div. Emergen. Gov't. <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Substance Involved <u>Xylene</u>	Quantity <u>25</u>	Units <u>gal</u>	Person or Firm Responsible <u>Specialty Chem. Co.</u>		
Substance Involved	Quantity	Units	Contact Name <u>Len Moore</u>	Telephone Number <u>(715) 735-9033</u>	

Physical Characteristics

Solid  Liquid  Semisolid  Gas

Color less Odor \_\_\_\_\_

Cause of Incident  
Broken

Exact Location Description (intersection, mileage, etc.)  
2 Stanton St.

County Location  
SE SENECOG, T30N, R24E

DNR Dist LMD DNR Area MAR Groundwaters Affected  Yes  No  Potential

Surface Waters Affected  Yes  No  Potential Name of Surface Water \_\_\_\_\_

Date District Notified \_\_\_\_\_ Day of Week \_\_\_\_\_ Time District Notified \_\_\_\_\_  A.M.  P.M.

District Person Notified \_\_\_\_\_ Telephone Number \_\_\_\_\_

Date Investigated 10-30-89 Day of Week Mon Time Investigated 12:30  A.M.  P.M.

Person Investigating David Haussman Telephone Number (715) 732-0101

Action Taken By DNR  No Action Taken  Investigation  Supervise/Conduct Cleanup

Spiller Required To Take Action; Type \_\_\_\_\_

Contractor Hired By DNR; Name \_\_\_\_\_

Amount Recovered \_\_\_\_\_

29.29 Enforcement \_\_\_\_\_

Other Agencies on Scene \_\_\_\_\_

Local \_\_\_\_\_

State \_\_\_\_\_

Federal \_\_\_\_\_

Additional Comments: \_\_\_\_\_

Address - Street or Route  
2 Stanton St.

City, State, Zip Code  
Marquette, WI 54443

Action Taken By Spiller

No Action Taken  Notification  Investigate

Containment; Type Absorbant

Cleanup; Method Dug up soil

Amount Recovered \_\_\_\_\_

Monitor Tested Soil found no trace

Contractor Hired; Name \_\_\_\_\_

Other Action \_\_\_\_\_

Spill Location

Industrial Facility/Paper Mill/Chem. Co.

Gas/Service Station/Garage, Auto Dealer, Repair Shop

Ag Coop/Facility/Cheese Factory/Creamery

Other Small Business (bank, grocery, insurance co., etc.)

Public Property (city, county, state, church, school, etc.)

Utility Co., Power Generating/Transfer Facility

Private Property (home/farm)

Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler

Transportation Accident, Fuel Supply Tank Spill

Transportation Accident, Load Spill

Construction, Excavation, Wrecking, Quarry, Mine

Other \_\_\_\_\_

Spilled Substance Destination

Air

Soil

Groundwater

Surface Water

Storm Sewer

Sanitary Sewer

Contained/Recovered

Other \_\_\_\_\_

Person Filing This Report (print name)  
David A. Haussman

Signature David A. Haussman Date Signed 10-30-89

Closed 10/30/89  
TA 1/26/18

RECEIVED  
NOV 7 1989  
BUREAU OF SOLID -  
HAZARDOUS WASTE MANAGEMENT

XIC AND HAZARDOUS INCIDENT ALERT F

OCT 31 1989

Report Prepared by

HENRY NIESSEN

1) Date of Incident <b>OCT. 25, 1989</b>	2) Time of Incident <b>1030</b>	3) Reported by <b>DR. LEONARD MOORE</b>	4) Telephone No. <b>715-735-9033</b>
5) Date Reported <b>OCT. 25, 1989</b>	6) Time Reported <b>1517</b>	7) Person or Firm Responsible <b>SPECIALTY CHEM - PRODUCTS CORP.</b>	
8) Substance Involved <b>ORTHO-XYLENE</b>	9) Quantity(unit) <b>25 GALLONS</b>	10) Contact Name <b>SAME AS (3)</b>	11) Telephone No. <b>715-735-9033</b>
12) Substance Involved	13) Quantity(unit)	14) Address <b>2 STANTON ST.</b>	
15) Physical Characteristics <input type="checkbox"/> Solid <input type="checkbox"/> Semisolid    Odor _____ <input checked="" type="checkbox"/> Liquid <input type="checkbox"/> Gas            Color _____		16) City, State, Zip Code <b>MARINETTE, WI. 54143</b>	
		17) Weather Conditions Wind Speed _____ Direction _____ Precipitation Yes ___ No ___    Temperature _____ Direction of Spill Movement _____	
18) Exact Location (Highways, Intersections, Mileage, Etc.) <b>2 STANTON ST. - MARINETTE, WI. 54143</b>			19) County <b>MARINETTE</b>
20) Cause of Incident <b>HOSE BROKE DURING TRANSFER IN PLANT. MATERIAL SPRAYED AGAINST THE WALL AND RAN OUT ONTO THE GROUND. DURATION WAS 5 TO 10 MINUTES.</b>			21) Transportation Related _____ Transportation Highway _____ Facility _____ Related <input checked="" type="checkbox"/>
22) If Nuclear Facility - Type of Alert _____ Unusual Event    _____ Alert    _____ Site Emergency    _____ General Emergency			
23) Surface Water Affected Yes <input checked="" type="checkbox"/> No _____ Potential _____	24) Ground Water Affected Yes <input checked="" type="checkbox"/> No _____ Potential _____	Agency <b>NR Center /Chemtrec</b>	Person Contacted <b>Agri</b>
25) Distance to - Nearest Water _____ Nearest Well _____ Surface Water Name _____	26) Distance From - Population _____ Medical Care Fac. _____ Correctional Fac. _____ Senior Citizen Center _____	DEG/Area Director	Telephone No. <b>800-424-8802</b>
27) Local Units on Scene <input type="checkbox"/> EG <input type="checkbox"/> Fire <input type="checkbox"/> Enforcement <input type="checkbox"/> EMS <input type="checkbox"/> Other <input type="checkbox"/> Engineering		DNR	Days <b>266-2141</b>
		DNR	Pager No. <b>608-275-9049</b>
28) Actions Taken on Scene <b>MATERIAL WAS COVERED WITH ADSORBANT, ADSORBANT AND SOIL WERE REMOVED, TESTED REMAINING SOIL. RECOVERED MATERIAL WILL BE INCINERATED. LOCAL D.H.R. WILL BE NOTIFIED OF THIS.</b>		DOT/State Patrol	
		H&SS	24 hr. Number <b>608-266-2830</b>
		NRC	<b>312-932-2500</b>
		PSC	
		DILHR	
		MFGR	