

Spill ID Number  
04-16-044817 ✓  
Y Y M M D D 0-99

|                                |                     |                          |   |  |   |
|--------------------------------|---------------------|--------------------------|---|--|---|
| Date of Incident<br>6-17-90    | Day of Week<br>Sun. | Time of Incident<br>6:00 | <input type="checkbox"/> A.M.<br><input checked="" type="checkbox"/> P.M. | Reported By (Name)<br>John Heller              | Telephone Number<br>( 715 ) 392-2221  |
| Date Reported<br>6-18-90       | Day of Week<br>Mon. | Time Reported<br>4:18    | <input type="checkbox"/> A.M.<br><input checked="" type="checkbox"/> P.M. | Agency or Firm Reporting<br>Koppers Industries | Reported thru Div. Emergen.<br>Gov't. <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Substance Involved<br>creosote | Quantity<br>20      | Units<br>gallons         | Person or Firm Responsible<br>Koppers Industries                          |  |   |
| Substance Involved             | Quantity            | Units                    | Contact Name<br>John Heller   | Telephone Number<br>( 715 ) 392-2221           |   |

Physical Characteristics

Solid  Liquid Color black

Semisolid  Gas Odor creosote

Address - Street or Route  
P.O. Box 397, Junctions of A & Z

City, State, Zip Code  
Superior, WI 54880

Cause of Incident  
leaking tank

Action Taken By Spiller

No Action Taken  No Notification  Investigate

Containment; Type \_\_\_\_\_

Cleanup; Method contaminated soil placed in drums

Amount Recovered \_\_\_\_\_

Monitor \_\_\_\_\_

Contractor Hired; Name \_\_\_\_\_

Other Action \_\_\_\_\_

Exact Location Description (intersection, mileage, etc.)  
Koppers Industries - Jnct. A & Z

County Location Douglas  $\frac{1}{4}$ ,  $\frac{1}{4}$ , Section, Town, Range  
\_\_\_\_\_, \_\_\_\_\_, \_\_\_\_\_, T \_\_\_\_\_ N, R \_\_\_\_\_

DNR Dist NWD DNR Area Brule Groundwaters Affected  
 Yes  No  Potential

Surface Waters Affected  Yes  No  Potential Name of Surface Water \_\_\_\_\_

Spill Location

Industrial Facility/Paper Mill/Chem. Co.

Gas/Service Station/Garage, Auto Dealer, Repair Shop

Ag Coop/Facility/Cheese Factory/Creamery

Other Small Business (bank, grocery, insurance co., etc.)

Public Property (city, county, state, church, school, etc.)

Utility Co., Power Generating/Transfer Facility

Private Property (home/farm)

Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler

Transportation Accident, Fuel Supply Tank Spill

Transportation Accident, Load Spill

Construction, Excavation, Wrecking, Quarry, Mine

Other \_\_\_\_\_

Date District Notified 6-18-90 Day of Week Mon. Time District Notified 4:22  
 A.M.  P.M.

District Person Notified John Plenke Telephone Number ( 715 ) 635-4151

Date Investigated 6-18-90 Day of Week Mon Time Investigated 4.00  
 A.M.  P.M.

Person Investigating Joe Davidowski Telephone Number ( 715 ) 392-7988

Action Taken By DNR

No Action Taken  Investigation  Supervise/Conduct Cleanup

Spiller Required To Take Action; Type \_\_\_\_\_

Contractor Hired By DNR; Name \_\_\_\_\_

Amount Recovered \_\_\_\_\_

29.29 Enforcement

Other Agencies on Scene \_\_\_\_\_

Local none

State DNR

Federal none

Spilled Substance Destination

Air

Soil

Groundwater

Surface Water

Storm Sewer

Sanitary Sewer

Contained/Recovered

Other \_\_\_\_\_

Person Filing This Report (print name)  
Joe Davidowski

Signature Joe Davidowski Date Signed 6-19-90

Additional Comments:  
John Heller, Koppers, is one of the best responders on spills that we deal with, and they do an excellent job on clean up.

*L.W.*