

04-05-046478

State Div. Emergency Gov't. (608) 266-3232
U.S. Nat'l. Response Center (800) 424-8802
Chemtrec/Pesticides/Chlorine (800) 424-9300

Spill ID Number

Y Y M M D D 0-99

04.05-046478

Date of Incident 11-7-91	Day of Week Thur	Time of Incident 9:20 AM	<input checked="" type="checkbox"/> A.M. <input type="checkbox"/> P.M.	Reported By (Name) Steve Faryan	Telephone Number (312) 353-9351
Date Reported 11-8-91	Day of Week Fri	Time Reported	<input type="checkbox"/> A.M. <input type="checkbox"/> P.M.	Agency or Firm Reporting U.S. EPA Region II	Reported thru Div. Emergen. Gov't. <input type="checkbox"/> Yes <input type="checkbox"/> No
Substance Involved Chromium Cont. Grd Wtr	Quantity 7	Units gal		Person or Firm Responsible Same	
Substance Involved	Quantity	Units		Contact Name	Telephone Number

Physical Characteristics

Solid Liquid Semisolid Gas

Color _____ Odor _____

Cause of Incident
Transfer Spill

Exact Location Description (intersection, mileage, etc.)
519 Lande St De Pere

County Location
Brown

Groundwaters Affected
 Yes No Potential

Surface Waters Affected
 Yes No Potential

Date District Notified
Observed By Annette Driessbach

District Person Notified
LMD Employee

Date Investigated

Person Investigating

Action Taken By DNR
 No Action Taken Investigation Supervise/Conduct Cleanup

Spiller Required To Take Action; Type _____

Contractor Hired By DNR; Name _____

Amount Recovered _____

29.29 Enforcement _____

Other Agencies on Scene

Local None

State W DNR Only

Federal U.S. EPA Contractor

Address - Street or Route
230 S. Dearborn St

City, State, Zip Code
Chicago Ill 60604

Action Taken By Spiller

No Action Taken No Notification Investigate

Containment; Type _____

Cleanup; Method _____

Amount Recovered > 4 gal

Monitor _____

Contractor Hired; Name _____

Other Action _____

Spill Location

Industrial Facility/Paper Mill/Chem. Co.

Gas/Service Station/Garage, Auto Dealer, Repair Shop

Ag Coop/Facility/Cheese Factory/Creamery

Other Small Business (bank, grocery, insurance co., etc.)

Public Property (city, county, state, church, school, etc.)

Utility Co., Power Generating/Transfer Facility

Private Property (home/farm)

Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler

Transportation Accident, Fuel Supply Tank Spill

Transportation Accident, Load Spill During Transfer

Construction, Excavation, Wrecking, Quarry, Mine

Other _____

Spilled Substance Destination

Air

Soil

Groundwater

Surface Water

Storm Sewer

Sanitary Sewer

Contained/Recovered

Other _____

Person Filing This Report (print name)
Jim Rayburn

Signature _____ Date Signed 11-18-91

Additional Comments:
Shipment of contaminated groundwater from Zinc Shop to Chrome Shop by E&K spilled at Chrome Shop when transferring from tank truck to Pretreatment Plant. Estimated 4 of 7 gal recovered and some soil removed and drummed. S. Faryan to send report to Terry Kobilin (Applied)

Closed 11/18/91

PA 2/28/18

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION V

Wisconsin Department of
Natural Resources
Attn: Terry Koehn
P.O. Box 10488
Green Bay, WI. 54307-0448

Dear Mr. Koehn,

This letter is to formally report a spill of hazardous substances on November 7, 1991 from the Better Brite Chrome Treatment system on 519 Lande St. in DePere, Wisconsin. A verbal notification of the spill was made on November 8, 1991 to Mr. Jim Reyburn of the Wisconsin Department of Natural Resources.

During off-loading of liquid from the Zinc shop approximately 7 gallons of dilute chromic acid containing approximately 200 mg/l of total chromium was spilled. Approximately 4 gallons of the spilled material was recovered. In addition, 1/4 of drum of gravel and soil was excavated and placed into a drum.

The recovered liquid was treated at the chromium treatment plant and the excavated gravel and soil will be stabilized with portland cement and disposed of within the next month at the Envirosafe landfill in Oregon, Ohio.

Feel free to contact me on site if you have any further questions at 312-265-0331.

Sincerely,



Steven J. Faryan, On-Scene
Coordinator, U.S. EPA Region V

Call from S. Faryan 11-18-91

- Collected gravel/soil to be stabilized with concrete and disposed of.
- Collected water placed in pretreatment plant for treatment prior to discharge.

