

State Div. Emergency Gov't. (608) 266-3232
U.S. Nat'l. Response Center (800) 424-8802
Chemtrec/Pesticides/Chlorine (800) 424-9300

Spill ID Number
891106-06
Y Y M M D D 0-99

04-88-044197

Mon

Date of Incident <u>11-6-89</u>	Day of Week <u>Mon</u>	Time of Incident <u>4:45</u>	<input type="checkbox"/> A.M. <input checked="" type="checkbox"/> P.M.
Date Reported <u>11-7-89</u>	Day of Week <u>Tue</u>	Time Reported <u>4:18</u>	<input type="checkbox"/> A.M. <input checked="" type="checkbox"/> P.M.
Substance Involved <u>Sodium Hydroxide</u>	Quantity <u>150</u>	Units <u>Gal.</u>	
Substance Involved	Quantity	Units	

Reported By (Name) <u>Connie-LMD</u>	Telephone Number ()
Agency or Firm Reporting <u>Specialty Chem.</u>	Reported thru Div. Emergen. Gov't. <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Person or Firm Responsible <u>Specialty Chem.</u>	
Contact Name <u>Ken Moore</u>	Telephone Number <u>(715) 735-9033</u>

Physical Characteristics

Solid Liquid Semisolid Gas

Color _____ Odor _____

Address - Street or Route
2 - Stanton St

City, State, Zip Code
Minnette

Cause of Incident
Rupture in line of scrubber

Exact Location Description (intersection, mileage, etc.)
Bldg #69 2 Stanton St.

Action Taken By Spiller

No Action Taken No Notification

Containment; Type _____

Cleanup; Method Naturalized, sent to land fill

Amount Recovered _____

Monitor _____

Contractor Hired; Name _____

Other Action _____

County Location
SE

¼, ¼, Section, Town, Range
SE, NE, 06, T30N, R24E

DNR Dist LMD DNR Area MAR

Groundwaters Affected Yes No Potential

Surface Waters Affected Yes No Potential

Name of Surface Water _____

Spill Location

Industrial Facility/Paper Mill/Chem. Co.

Gas/Service Station/Garage, Auto Dealer, Repair Shop

Ag Coop/Facility/Cheese Factory/Creamery

Other Small Business (bank, grocery, insurance co., etc.)

Public Property (city, county, state, church, school, etc.)

Utility Co., Power Generating/Transfer Facility

Private Property (home/farm)

Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler

Transportation Accident, Fuel Supply Tank Spill

Transportation Accident, Load Spill

Construction, Excavation, Wrecking, Quarry, Mine

Other _____

Date District Notified
11/7/89

Day of Week
Tue

Time District Notified
4:18

A.M.
 P.M.

District Person Notified
Connie

Telephone Number
()

Date Investigated
11-10-89

Day of Week
Friday

Time Investigated
8:30

A.M.
 P.M.

Person Investigating
D. Hausman

Telephone Number
(715) 730-0101

Action Taken By DNR

No Action Taken Investigation Supervise/Conduct Cleanup

Spiller Required To Take Action; Type _____

Contractor Hired By DNR; Name _____

Amount Recovered _____

29.29 Enforcement _____

Spilled Substance Destination

Air Soil Groundwater Surface Water Storm Sewer

Sanitary Sewer

Contained/Recovered

Other _____

Other Agencies on Scene

Local _____

State _____

Federal _____

Person Filing This Report (print name)
David A. Hausman

Signature
David A. Hausman

Date Signed
11-13-89

Additional Comments:
JK, C AC (D. Rossberg DTs)

Closed 11/13/89
TA 1/26/88

RECEIVED
NOV 21 1989
BUREAU OF SOIL & HAZARDOUS WASTE MANAGEMENT

Spill ID Number

Y Y M M D D 0-99

Date of Incident 11/6/89	Day of Week Mon.	Time of Incident 4:45	<input type="checkbox"/> A.M. <input checked="" type="checkbox"/> P.M.	Reported By (Name) Dr. Lenoard Moore	Telephone Number (715) 735-9033
Date Reported 11/7/89	Day of Week Tues.	Time Reported 3:50	<input type="checkbox"/> A.M. <input checked="" type="checkbox"/> P.M.	Agency or Firm Reporting Marty Hoffman	Reported thru Div. Emergen. Gov't. <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Substance Involved Sodium Hydroxide		Quantity 150 gal.	Units	Person or Firm Responsible Speciality Chem Products Corporation	
Substance Involved		Quantity	Units	Contact Name Dr. Lenoard Moore	Telephone Number (715) 735-9033

Physical Characteristics

Solid Liquid Gas Semisolid

Color _____ Odor _____

Address - Street or Route
2 Stanton St.

City, State, Zip Code
Marinette, WI. 54143

Cause of Incident
Rupture in line of a scruber

Exact Location Description (intersection, mileage, etc.)
2 Stanton St. Marinette, WI. 54143

Action Taken By Spiller

No Action Taken No Notification Investigate

Containment; Type _____

Cleanup; Method _____

Amount Recovered _____

Monitor _____

Contractor Hired; Name _____

Other Action _____

County Location
Marinette

_____, _____, _____, T _____ N, R _____

DNR Dist LM DNR Area _____

Groundwaters Affected Yes No Potential

Surface Waters Affected Yes No Potential

Name of Surface Water _____

Date District Notified 11/7/89 Day of Week Tues. Time District Notified 4:10 A.M. P.M.

District Person Notified Connie Schramm Telephone Number (414) 497-4042

Date Investigated _____ Day of Week _____ Time Investigated _____ A.M. P.M.

Person Investigating _____ Telephone Number ()

Action Taken By DNR

No Action Taken Investigation Supervise/Conduct Cleanup

Spiller Required To Take Action; Type _____

Contractor Hired By DNR; Name _____

Amount Recovered _____

29.29 Enforcement

Spill Location

Industrial Facility/Paper Mill/Chem. Co.

Gas/Service Station/Garage, Auto Dealer, Repair Shop

Ag Coop/Facility/Cheese Factory/Creamery

Other Small Business (bank, grocery, insurance co., etc.)

Public Property (city, county, state, church, school, etc.)

Utility Co., Power Generating/Transfer Facility

Private Property (home/farm)

Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler

Transportation Accident, Fuel Supply Tank Spill

Transportation Accident, Load Spill

Construction, Excavation, Wrecking, Quarry, Mine

Other _____

Spilled Substance Destination

Air Soil Groundwater Surface Water Storm Sewer Sanitary Sewer Contained/Recovered Other _____

Other Agencies on Scene

Local _____

State _____

Federal _____

Person Filing This Report (print name)
Jenny Sommers

Signature *Jenny Sommers* Date Signed 11/8/89

Additional Comments: Stopped Leak and nutralized chemical. Chemical will be sent to a landfill. 1 employee was injured, sent to hospitol, treated and released.