

Spill ID Number
04-16-047990
Y Y M M D D 0-99

Date of Incident 1-5-93	Day of Week Tues.	Time of Incident 2:30	<input type="checkbox"/> A.M. <input checked="" type="checkbox"/> P.M.	Reported By (Name) Bruce Krenz	Telephone Number (715) 398-3533
Date Reported 1-5-93	Day of Week Tues.	Time Reported 3:30	<input type="checkbox"/> A.M. <input checked="" type="checkbox"/> P.M.	Agency or Firm Reporting Murphy Oil	Reported thru Div. Emergen. Gov't. <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Substance Involved unleaded gas	Quantity 150	Units gals.	Person or Firm Responsible Murphy Oil		
Substance Involved	Quantity	Units	Contact Name Bill Gustafson	Telephone Number (715) 398-3533	

Physical Characteristics

Solid Liquid Color amber

Semisolid Gas Odor _____

Address - Street or Route
P.O. Box 2066, Stanson Ave.

City, State, Zip Code
Superior, WI 54880

Cause of Incident
pressure valve froze open

Exact Location Description (intersection, mileage, etc.)
vapor recovery unit

Action Taken By Spiller

No Action No Notification Investigate

Taken Containment; Type _____

Cleanup; Method vacuum

Amount Recovered _____

Monitor _____

Contractor Hired; Name _____

Other Action _____

County Location 1/4, 1/4, Section, Town, Range

Douglas _____, T _____ N, R _____

DNR Dist NWD DNR Area Brule Groundwaters Affected

Yes No Potential

Surface Waters Affected

Yes No Potential

Name of Surface Water _____

Date District Notified
1-5-93

Day of Week
Tues.

Time District Notified
3:35

A.M.
 P.M.

District Person Notified
Marcia Johnson

Telephone Number
(715) 635-4051

Date Investigated
1-5-93

Day of Week
Tues.

Time Investigated
4:00

A.M.
 P.M.

Person Investigating
Steve LaValley

Telephone Number
(715) 392-7831

Action Taken By DNR

No Action Investigation Supervise/Conduct Cleanup

Taken

Spiller Required To Take Action; Type contain & submit cleanup

Contractor Hired By DNR; Name _____

Amount Recovered _____

29.29 Enforcement

Spill Location

Industrial Fa

Gas/Service S

Ag Coop/Faci

Other Small I

Public Proper

Utility Co., P

Private Prope

Pipeline, Terr

Transportation Accident, Fuel Supply Tank Spill

Transportation Accident, Load Spill

Construction, Excavation, Wrecking, Quarry, Mine

Other refinery

Murphy 1/11/93

LL 1/13/93

Other Agencies on Scene

Local _____

State _____

Federal _____

Spilled Substance Destination

Air

Soil

Groundwater

Surface Water

Storm Sewer

Sanitary Sewer

Contained/Recovered

Other Most of the material fell into a sump on the vapor recovery unit

Person Filing This Report (print name) Steve LaValley

Signature Steve LaValley Date Signed 1-5-93

Additional Comments:
An air line froze so the valve on the recovery unit shut off. Gas flowed primarily into a sump but also the surrounding area. Bill said he would send a report and a work plan for clean up.

LL