NAR 09-42-549303 5/17/2007 COPY

NAR- 09-42-549303

Piping Closure Site Assessment Report
WI Army National Guard-MATES Facility
Fort McCoy, Wisconsin

May 1, 2007 by METCO



Excellence through experience $^{\text{\tiny{M}}}$

This document was prepared by:

Ronald J. Anderson, P.G.

Senior Hydrogeologist/Project Manager

2956 Airport Road ♦ La Crosse, WI 54603 ♦ 1-800-552-2932 ♦ Fax (608) 781-8893 Email: rona@metcohq.com ♦ www.metcohq.com

May 1, 2007

Pete Schuster State of Wisconsin Department of Military Affairs 2400 Wright Street Madison, WI 53708

Dear Mr. Schuster,

Enclosed is our "Piping Closure Site Assessment Report" concerning the removed underground piping system at the WI Army National Guard-MATES facility in Fort McCoy, Wisconsin. This document presents the procedures, methods, observations, and documentation used to conduct such a project.

As required, a copy of this report will be sent to the WDNR.

We appreciate the opportunity to be of service on this project. Should you have any questions or require additional information, do not hesitate to contact me at our La Crosse office.

Sincerely,

Ronald J. Anderson PG

Senior Hydrogeologist/Project Manager

Cc: Beth Norquist

TABLE OF CONTENTS

INTRODUCTION	1
SCOPE OF SERVICES	. 1
PROJECT CONCERNED PARTIES	1
SITE INFORMATION	2
OBSERVATIONS	- 2
CONCLUSIONS	3
STANDARD OF CARE	. 3
APPENDIX A/ SITE MAPS	. 4
APPENDIX B/ LABORATORY REPORT	5

INTRODUCTION

METCO was retained to perform a Piping Closure Site Assessment at the WI Army National Guards-MATES facility located in Fort McCoy, Wisconsin. The purpose of this site assessment was to: 1) Document piping system removal, 2) Determine if petroleum products have spilled or leaked into the environment, and 3) Determine if additional investigations are needed. This report presents the data and results of this assessment.

SCOPE OF SERVICES

Duties included collecting background information, field observations, laboratory analysis of collected soil samples, and subsequent report generation. All work was done in accordance with the Department of Commerce (DCOMM) and the Department of Natural Resources (WDNR) approved methods.

PROJECT CONCERNED PARTIES

Tank System Owner

Pete Schuster State of Wisconsin Department of Military Affairs 2400 Wright Street Madison, WI 53708 608-242-3355

General Contractor

METCO 102 Enterprise Drive P.O. Box 448 Hillsboro, WI 54634 608-489-2198

State Certified Site Assessor

METCO Ronald J. Anderson (#41861) 2956 Airport Road La Crosse, WI 54603 608-781-8879

SITE INFORMATION

Site Address

242 East G Street, Fort McCoy, Wisconsin.

Tank Closure

On April 10, 2007, METCO removed underground piping that belonged to an existing 2,500 gallon diesel UST.

The piping, which was constructed of double-walled fiberglass, showed no evidence of cracks, holes, or leaks. No petroleum odors or staining were noticed in the surrounding soils.

The piping was properly disposed.

OBSERVATIONS

Geology

Native soils consisted of a tan fine to medium grained quartz sand.

Groundwater was not encountered.

Bedrock was not encountered.

Laboratory Results

SA-1 = < 10 ppm DRO at 2-3 feet below ground surface.

SA-2 = < 10 ppm DRO at 2-3 feet below ground surface.

Soil Sampling

The soil samples were collected for laboratory analysis with as little disturbance and exposure to the air as possible.

Using a clean shovel and gloved hand, the soil samples were collected and placed in a laboratory specified, clean, clear, glass container with a screw on, Teflon lined cap. The sample was then packed in a cooler containing ice and hand delivered to Synergy Environmental Labs located in Appleton, Wisconsin.

Tool Cleaning Methods

No sampling tools were cleaned on-site and no wastewater produced.

CONCLUSIONS

According to the WDNR, if a collected soil sample tests more than 10 ppm for GRO or DRO, the current owner/operator of the facility is required to determine the complete extent of the contamination released from their tank system and possibly clean it up.

Since the laboratory analysis of the soil sample collected beneath the removed piping system showed no detect levels for petroleum products, METCO can only conclude that the piping has not released measurable amounts of contaminants into the areas sampled.

A copy of this report will be sent to the WDNR.


STANDARD OF CARE

The analysis and conclusions expressed in this report are based upon data obtained from the subsurface evaluation at the indicated locations and from other information discussed in this report. Actual subsurface conditions may vary and may not become evident without further assessment.


The conclusions and recommendations contained in this report represent our professional opinions. All work conducted by METCO is in accordance with currently accepted hydrogeologic and engineering practices and they neither imply nor intend warranty.

We appreciate the opportunity to be of service on this project. If you have any questions or require additional information, please do not hesitate to contact us.

Appendix A/ Site Map



SOIL SAMPLING LOCATION



RESULTS

SA-I = (10 PPM DRO AT 2-3 FEET BELOW GROUND SURFACE SA-2 = (10 PPM DRO AT 2-3 FEET BELOW GROUND SURFACE

NOTE: THIS IS NOT A SURVEYED MAP. MEASUREMENTS AND SPACIAL RELATIONSHIPS MAY BE INCORRECT.

Synergy Environmental Lab,

1990 Prospect Ct., Appleton, WI 54914 *P 920-830-2455 * F 920-733-0631

RON ANDERSON METCO 2956 Airport Road La Crosse, WI 54603

Report 18-Apr-07

Project Name Project #	WI ARMY N	ATIONAL GU	JARDS -	Invoice #	E15156					
Lab Sample ID Sample Sample Date	5015156A SA-1 Soil 4/10/2007								-	
	•	Result	Unit	LOD	LOQ	Dil	Method	Run	Analyst	Code
General General		•								
Solids Percent Organic		97.2	%			ì	5021	4/16/2007	DJB	1
General Diesel Range O	rganics	< 10	mg/kg	0.62	2	1	DRO95	4/13/2007	MJR	I
Lab Sample ID Sample Sample Date	5015156B SA-2 Soil 4/10/2007									
•		Result	Unit	LOD	LOQ	Dil	Method	Run	Analyst	Code
General General Solids Percent		96.5	%			1	5021	All Cloops	D.ID.	
Organic General		70. 3	70			ì	5021	4/16/2007	DJB	I
Diesel Range O	rganics	< 10	mg/kg	0.62	2	1	DRO95	4/13/2007	MJR	1

Project #

Project Name WI ARMY NATIONAL GUARDS

"J" Flag: Analyte detected between LOD and LOQ

LOD Limit of Detection

LOQ Limit of Quantitation

Invoice # E15156

Code

Comment

Laboratory QC within limits.

Authorized Signature

Michael J. Ricker

CHAIN C CUSTODY RECORD

Temp. of Temp. Blank. G.Gn. Ice. X

S, nergy

Chain # 8387

Page	of	Later III bell-III bell

Time: 8:15

Date: 4/12/67

Account No.: Quote No.:					3	Errirentella!						-			Page or								
					E CALL									ेहर	Sample Handling Request Rush Analysis Date Required								
Project #:						1990 Prospect Ct. • Appleton.				\M\ 54914					(Rushes accepted only with prior authorization)								
Sampler; (signature)					920-830-2455 • FAX 920-7					31				Normal Turn Around									
Project (Name	/Location): W	IX	rest a	Ma	Wona	l Ga	ards -	MATE	5	Ī				Anai	γsis	Requ	estec	 [
Reports To:					nvoice								\top		Ĭ			Other Analysis					
Company	<u> </u>				Compa					1						 ,							
Address		0 / 11			Address	 5					Sep 95)			, <u>s</u>									
City State Zip					City Sta	te Zip) Sep	-	524.2	Solids									
Phone				-+	Phone	•		-1,		(Mod DRO Sep 95)	(Mod GRO	802	PA	8270)									
FAX					-AX						Mod	(EPA	<u>₩</u>	Suspe		ļ							PID
-Eqb.(5)	Sample I.D.	i	ection Time	Comp	Grab	Filtered Y/N	No. of Containers	Sample Type (Matrix)*	Preservation	DRO (A	GRO (PVOC (EPA 8021) VOC (EPA 8260)	VOC D	PAH (EPA 8270) Total Suspended	Lead	1							FID
54556A	5A-1		200		X		1			X		÷											
charge of	SA-2	1/0/07	240		×		/	2		X													
programme of the control of the cont		<u> </u>		<u>. </u>						<u> </u>		-	11	_ـــ				+		_ _			
And the second of the second			<u> </u>	<u> </u>			\ <u></u>	-		1	_	+	\vdash		 			+	$\dashv \downarrow$				-
spray poly / gardenger region of the file to the spray of		+		<u> </u>			· -									++-		+	+++	\rightarrow			
Selection in the later of the l			_		 					1	+	+	1	-			$\dagger \dagger$						IN
m in a service of the																							
Chronical Control		ļ		<u></u>					7-,			_ _	<u> </u>	<u> </u>				4		\perp	_ _		↓
And the control of th		<u>.</u>		<u> </u>								<u>i</u>		_i_	<u> </u>		Ш.	<u>ــلـــ</u> ــ					
Comments/Spec	rial Instructions (*	Specify	ground	dwater	"GW", [rinking \	Nater "DW", V	Vaste Water	"WW". Soil "S	", Air	Α"	. Oil.	Sluc	ge e	1c.)								
																•							
	y To be comple Significantly				Re	linquish	ed By: (sign)	Time	D	ate		Rece	eived	By:	(sign)				Tin	ne	Da	te
MSHOOLO	Pingle Charles		rui Sarrini	The figure section in the					,														

Received in Laboratory By:

Appendix B/ Laboratory Report