

Elk Mound Fire District - Incident Sheet

Date 3-27-07 EMFD Incident # 307-012
 Notified By COUNTY County CAD #
 Call Type HAZ SF - Structure Fire, WF - Wildland Fire, VF - Vehicle Fire, TA - Traffic Accident, DNR - DNR Fire,
 FA - False Alarm, HAZ - Hazmat, CO - Carbon Monoxide, WA - Weather Alert, O - Other

Location I-94 51 MM Westbound
 Time Called 12:45 Time Out 12:50 Time Back Time In-Service
 Municipality Village of Elk Mound Town of Elk Mound Town of Spring Brook
 Mutual Aid Location: I94 west mile marker 51

Mutual Aid Departments Menomonie Fire

Units Responding	Equip. Used	# of Personnel	5	Personnel Hours	
Engine 5 <input checked="" type="checkbox"/>	Foam <input type="checkbox"/>	Water Gallons Used		0	
Squad 2 <input checked="" type="checkbox"/>	Airpacks <input type="checkbox"/>	Water Source		Station <input type="radio"/> Hydrant <input type="radio"/> Other <input type="radio"/>	
Tanker 83 <input type="checkbox"/>	CO Detector <input type="checkbox"/>				
Tanker 85 <input type="checkbox"/>	Extrication <input type="checkbox"/>				
Engine 82 <input type="checkbox"/>	Gas Detector <input type="checkbox"/>				
Brush 81 <input type="checkbox"/>	Fire Camera <input type="checkbox"/>				
Other <input type="checkbox"/>					

Owner of Property or Vehicle WH Transportation
 Phone Number 740-454-1658
 Insurance Company

Narrative

Paged for a semi, leaking fuel. Found large puncture in Right saddle Tank, center-bottom. Driver had stuffed a rag in the hole.
 Paged for Menomonee Hazmat. Menomonee drained approx 55 gal into storage containers. Menomonee fire notified Bruce Bergner and the DNR.
 Driver stated that he estimated he had approx 80 gal. of fuel. The semi did have a crossover which was closed to prevent fuel to flow to the leaking tank. WRR called by Menomonee fire to pickup ~~about~~ (2) barrels of fuel. Placed floor dry on main spill. Menomonee fire released from scene, state patrol will remain on scene until WRR is finished with picking up barrels. Semi was started to confirm that the crossover was closed. EMFD cleared scene. No fire fighter injuries.

Note: fuel leak appeared to start at approx. 52 mile marker.

Report Completed By Dale W. Adler 1631
 Statement Date Statement By
 NFIRS Complete YES NO



Elk Mound Fire/Rescue Field Incident Report

7/24/11
 4:40 PM
 App. 4 gal. on ground
 WRR called by Men.
 Memomnie put down Floor Dry.
 55 gal - In barrel
 180 gal tank
 Fueled in Maoston

Date / /		Time A P		Incident Location; Fire #, Mile Marker, etc.			Incident #		
							EMFD		
							County		
Incident Type									
Structure Fire			Vehicle Accident			E.M.S.		Mutual Aid Extrication	
Vehicle Fire			Rescue			Carbon Monoxide		False Alarm	
Forest Fire			HAZ-MAT			Mutual Aid Fire		Other	
Apparatus Responding				# of Personnel		Equipment, Supplies, Water Used			
#81	#85			Mutual Aid		Water		Air Packs	
#82	#86					Foam		Oxygen	
#83						Wet-water		Medical Supplies	
#84						Extinguishers		Other	
Description of Incident and Tasks Performed									
Owner of Property		MHT Transportation - Wausau, WI Unit #4750.							
Name		Address					Telephone		
Renter or Driver		1347 Maysville Ave OHIO Lic. Jay Cramer Zanesville, OH 43701					740-454-1658		
Name		Address					Telephone		
Property or Vehicle Description									
Make & Model		Freightliner	Color	White	Plates	TI8380W (WI)	Vehicle Identification # 6LW99778		
Additional Information/Notes									
USDOT. 074454			Trailer Plate			Operators Drivers License #			
IC 23685			535682 (WI)			Trailer # 1-9564			
LC 50759									

Report Prepared By _____