Thompson, Matthew A - DNR

From: Brian Bailey <BBailey@reiengineering.com>
Sent: Wednesday, August 01, 2018 3:47 PM

To: Thompson, Matthew A - DNR

Cc: Dave Larsen

Subject: Pioneer Bank - MW-10 Missing

Attachments: MW-10PhotoLog.pdf

Good afternoon Matt,

Just to give you a heads up, REI was onsite at the Pioneer Bank (Former Texaco Station/Judges Cleaners) on July 19, 2018 to conduct the quarterly groundwater sampling event. The field technician documented that MW-10 could not be located. He searched in the gravel in the area where the previous well was located and used metal detector in the area as well, but could not located. When reviewing photographs, it appears the well would have been located beneath the new concrete sidewalk (see attached photolog).

This well had ES exceedances for PCE and TCE in the most recent sampling round (April 2018), which was similar to previous sample rounds. This well documented off-site CVOC contamination related to the Pioneer Bank / Former Judges Cleaners case.

When would be a good time for you to discuss?

Thank you,

Brian J. Bailey

Brian J. Bailey - Environmental Scientist



Connect with us : III III I

Confidentiality Notice: This message is intended for the recipient only. If you have received this e-mail in error please disregard.





MW-10 Present December 19, 2017

Pioneer Bank – Former Texaco Station/Judges Cleaners	Photographs
701 South Central Ave., Marshfield, WI	REI No. 5403





MW-10 Present January 10, 2018

Pioneer Bank – Former Texaco Station/Judges Cleaners	Photographs
701 South Central Ave., Marshfield, WI	REI No. 5403






MW-10 Present April 26, 2018

Pioneer Bank – Former Texaco Station/Judges Cleaners	Photographs
701 South Central Ave., Marshfield, WI	REI No. 5403





MW-10 July 19, 2018 Could not be located - Removed? Abandoned?

Pioneer Bank – Former Texaco Station/Judges Cleaners	Photographs
701 South Central Ave., Marshfield, WI	REI No. 5403