## **GIS REGISTRY**

## **Cover Sheet**

August 2011 (RR-5367)

Source Prop	perty Information	CLOSURE DATE: Jul 11, 2012
BRRTS #:	03-41-543817	<u> </u>
ACTIVITY NAME:	Former L S Cartage Location Building #17	FID #: 341055770
PROPERTY ADDRESS:	4765 (formerly 4763) North 32nd Street	DATCP #:
MUNICIPALITY:	Milwaukee	PECFA#: 53209-6083-6
PARCEL ID #:	2300692000	
	*WTM COORDINATES:	WTM COORDINATES REPRESENT:
>	X: 686565 Y: <b>294273</b>	
	* Coordinates are in WTM83, NAD83 (1991)	♠ Approximate Source Parcel Center
Please check as appro	opriate: (BRRTS Action Code)	
	Contamin	ated Media:
┌ <u>Gro</u>	undwater Contamination > ES (236)	Soil Contamination > *RCL or **SSRCL (232)
Γ	Contamination in ROW	∇ontamination in ROW
Γ	Off-Source Contamination	Off-Source Contamination
	ote: for list of off-source properties "Impacted Off-Source Property" form)	(note: for list of off-source properties see "Impacted Off-Source Property" form)
	Land Us	e Controls:
Г	N/A (Not Applicable)	ズ Cover or Barrier (222)
	Soil: maintain industrial zoning (220)	(note: maintenance plan for
(no	ote: soil contamination concentrations tween non-industrial and industrial levels)	groundwater or direct contact)  ☐ Vapor Mitigation (226)
Γ	Structural Impediment (224)	Maintain Liability Exemption (230)
Γ	Site Specific Condition (228)	(note: local government unit or economic development corporation was directed to take a response action)
	Monito	ring Wells:
	Are all monitoring wells prope	erly abandoned per NR 141? (234)
	↑ Yes	No (♠ N/A

<sup>\*</sup> Residual Contaminant Level

<sup>\*\*</sup>Site Specific Residual Contaminant Level

State of Wisconsin Department of Natural Resources http://dnr.wi.gov

#### PLEASE ASSEMBLE IN THIS ORDER

**GIS Registry Checklist** 

Form 4400-245 (R 8/11)

Page 1 of 3

This Adobe Fillable form is intended to provide a list of information that is required for evaluation for case closure. It is to be used in conjunction with Form 4400-202, Case Closure Request. The closure of a case means that the Department has determined that no further response is required at that time based on the information that has been submitted to the Department.

NOTICE: Completion of this form is mandatory for applications for case closure pursuant to ch. 292, Wis. Stats. and ch. NR 726, Wis. Adm. Code, including cases closed under ch. NR 746 and ch. NR 726. The Department will not consider, or act upon your application, unless all applicable sections are completed on this form and the closure fee and any other applicable fees, required under ch. NR 749, Wis. Adm. Code, Table 1 are included. It is not the Department's intention to use any personally identifiable information from this form for any purpose other than reviewing closure requests and determining the need for additional response action. The Department may provide this information to requesters as required by Wisconsin's Open Records law [ss. 19.31 - 19.39, Wis. Stats.].

BRRTS #: 03-41-543817 (No Dashes) PARCEL ID #: 2300692000

ACTIVITY NAME: Former L S Cartage Location Building #17 WTM COORDINATES: X: 686565 Y: 294273

CLOSURE DOCUMENTS (the Department adds these items to the final GIS packet for posting on the Registry)

Closure Letter

Maintenance Plan (if activity is closed with a land use limitation or condition (land use control) under s. 292.12, Wis. Stats.)

Continuing Obligation Cover Letter (for property owners affected by residual contamination and/or continuing obligations)

#### **SOURCE LEGAL DOCUMENTS**

Certificate of Completion (COC) (for VPLE sites)

Conditional Closure Letter

- Deed: The most recent deed as well as legal descriptions, for the Source Property (where the contamination originated). Deeds for other, off-source (off-site) properties are located in the Notification section.
  - **Note:** If a property has been purchased with a land contract and the purchaser has not yet received a deed, a copy of the land contract which includes the legal description shall be submitted instead of the most recent deed. If the property has been inherited, written documentation of the property transfer should be submitted along with the most recent deed.
- Certified Survey Map: A copy of the certified survey map or the relevant section of the recorded plat map for those properties where the legal description in the most recent deed refers to a certified survey map or a recorded plat map. (lots on subdivided or platted property (e.g. lot 2 of xyz subdivision)).
  - Figure #: Sheet 1 of 5 Title: Certified Survey Map 8099
- Signed Statement: A statement signed by the Responsible Party (RP), which states that he or she believes that the attached legal description accurately describes the correct contaminated property.

#### MAPS (meeting the visual aid requirements of s. NR 716.15(2)(h))

Maps must be no larger than 11 x 17 inches unless the map is submitted electronically.

- □ Location Map: A map outlining all properties within the contaminated site boundaries on a U.S.G.S. topographic map or plat map in sufficient detail to permit easy location of all parcels. If groundwater standards are exceeded, include the location of all potable wells within 1200 feet of the site.
  - **Note:** Due to security reasons municipal wells are not identified on GIS Packet maps. However, the locations of these municipal wells must be identified on Case Closure Request maps.

Figure #: 1 Title: Site Location Map

Detailed Site Map: A map that shows all relevant features (buildings, roads, individual property boundaries, contaminant sources, utility lines, monitoring wells and potable wells) within the contaminated area. This map is to show the location of all contaminated public streets, and highway and railroad rights-of-way in relation to the source property and in relation to the boundaries of groundwater contamination exceeding a ch. NR 140 Enforcement Standard (ES), and/or in relation to the boundaries of soil contamination exceeding a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Levels (SSRCL) as determined under s. NR 720.09, 720.11 and 720.19.

#### Figure #: 3 Title: Soil Boring/Monitoring Well Location Map

- Soil Contamination Contour Map: For sites closing with residual soil contamination, this map is to show the location of all contaminated soil and a single contour showing the horizontal extent of each area of contiguous residual soil contamination that exceeds a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Level (SSRCL) as determined under s. NR 720.09, 720.11 and 720.19.
  - Figure #: 4B Title: Post-Remedial Soil Quality Map

State of Wisconsin Department of Natural Resource http://dnr.wi.gov	ces	GIS Registry Chec Form 4400-245 (R 8/11	
BRRTS #: 03-41-543817	ACTIVITY NAME:	Former L S Cartage Location	Building #17
MAPS (continued)			
Residual Contaminant I ch. NR 140 Enforcemen	<b>n Map:</b> A map showing the source location and vertic Level (RCL) or a Site Specific Residual Contaminant Lev t Standard (ES) when closure is requested, show the so and locations and elevations of geologic units, bedro	vel (SSRCL). If groundwater cource location and vertical ex	ontamination exceeds a stent, water table and
Figure #: 4C	Title: Cross-Section Location Map		
Figure #: 6, 7, 8, 9	Title: Cross Section A-A', B-B', C-C', D-D'		
extent of all groundwat Indicate the direction a	entration Map: For sites closing with residual ground ter contamination exceeding a ch. NR140 Preventive And date of groundwater flow, based on the most reces show the total area of contaminated groundwater.	action Limit (PAL) and an Enfo	
Figure #:	Title:		
in the second se	rection Map: A map that represents groundwater mo history of the site, submit 2 groundwater flow maps s		
Figure #:	Title:		
Figure #:	Title:		
TABLES (meeting the rec	quirements of s. NR 716.15(2)(h)(3))	- = ,	
	nan 11 x 17 inches unless the table is submitted electro BOLD or ITALICS is acceptable.	onically. Tables <u>must not</u> cor	tain shading and/or
Note: This is one table	A table showing <u>remaining</u> soil contamination with an of results for the contaminants of concern. Contamin remain after remediation. It may be necessary to creat	ants of concern are those tha	it were found during the
Table #: 1	Title: Post-Remedial/Residual Soil analytical Re	sults (Detected Compound	s)
	cal Table: Table(s) that show the most recent analytic vells for which samples have been collected.	al results and collection date	s, for all monitoring
Table #:	Title:		
	s: Table(s) that show the previous four (at minimum) sent, free product is to be noted on the table.	water level elevation measur	ements/dates from all
Table #:	Title:		
IMPROPERLY ABANDO	NED MONITORING WELLS		
	ot properly abandoned according to requirements of ad on the GIS Registry for only an improperly abandoned the GIS Registry Packet.		
Not Applicable			
not been properly aban	nap showing all surveyed monitoring wells with specification.  If a surveyed monitoring wells with specification in the Detailed States are distinctly identified on the Detailed States		
Figure #:	Title:		
	ort: Form 4440-113A for the applicable monitoring w	olls.	

Deed: The most recent deed as well as legal descriptions for each property where a monitoring well was not properly abandoned.

Notification Letter: Copy of the notification letter to the affected property owner(s).

State of Wisconsin Department of Natural Resources http://dnr.wi.gov

# GIS Registry Checklist Form 4400-245 (R 8/11)

Page 3 of 3

BR	RRTS #: 03-41-543817	ACTIVITY NAME: Former L S Cartage Location Building #17
NC	OTIFICATIONS	
So	urce Property	
X	Not Applicable	
Γ		<b>ce Property Owner:</b> If the source property is owned by someone other than the person who is applying a copy of the letter notifying the current owner of the source property that case closure has been
Г	Return Receipt/Signate property owner.	ure Confirmation: Written proof of date on which confirmation was received for notifying current source
Of	f-Source Property	
	oup the following inform f-Source Property" attack	ation per individual property and label each group according to alphabetic listing on the "Impacted ment.
Г	Not Applicable	
	groundwater exceeding under s. 292.12, Wis. Sta	<b>Property Owners:</b> Copies of all letters sent by the Responsible Party (RP) to owners of properties with an Enforcement Standard (ES), and to owners of properties that will be affected by a land use control ts.  source properties regarding residual contamination must contain standard provisions in Appendix A of ch. NR
	Number of "Off-Source	e" Letters:
Γ	Return Receipt/Signat property owner.	ure Confirmation: Written proof of date on which confirmation was received for notifying any off-source
	property(ies). This do	<b>Property:</b> The most recent deed(s) as well as legal descriptions, for all affected deeded <b>off-source</b> as not apply to right-of-ways.
	which includes the legal	een purchased with a land contract and the purchaser has not yet received a deed, a copy of the land contract description shall be submitted instead of the most recent deed. If the property has been inherited, written operty transfer should be submitted along with the most recent deed.
		A copy of the certified survey map or the relevant section of the recorded plat map for those properties on in the most recent deed refers to a certified survey map or a recorded plat map. (lots on subdivided or t 2 of xyz subdivision)).
	Figure #:	Title:
×	municipality, state ager within or partially withi	tal Unit/Right-Of-Way" Owners: Copies of all letters sent by the Responsible Party (RP) to a city, village, cy or any other entity responsible for maintenance of a public street, highway, or railroad right-of-way, a the contaminated area, for contamination exceeding a groundwater Enforcement Standard (ES) and/or all Contaminant Level (RCL) or a Site Specific Residual Contaminant Level (SSRCL).

Number of "Governmental Unit/Right-Of-Way Owner" Letters: 2

State of Wisconsin DEPARTMENT OF NATURAL RESOURCES 101 S. Webster Street Box 7921 Madison WI 53707-7921

Scott Walker, Governor Cathy Stepp, Secretary Telephone 608-266-2621 Toll Free 1-888-936-7463



July 11, 2012

Bishop's Creek Family Housing, LLC Attn: Amanda Novak 328 Kellogg Blvd. West St. Paul MN 55102

Subject:

Final Case Closure with Continuing Obligations for the Former L S Cartage Location Building

#17 (Lot 2), 4765 (formerly 4763) North 32nd Street Milwaukee, WI

FID: 341055770

BRRTS: 03-41-543817 PECFA: 53209-6083-63-B

Dear Ms. Novak:

On July 10, 2012, the Wisconsin Department of Natural Resources ("the Department") reviewed the above referenced case for closure. The Department reviews environmental remediation cases for compliance with state laws and standards to maintain consistency in the closure of these cases. On July 2, 2012, the Department received information or documentation indicating that you have complied with the requirements for final closure by submitting to the Department the Case Closure Request and GIS Registry for soil packets.

The Department reviewed the case closure request regarding the petroleum, metals, and CVOC soil contamination at this site. Based on the correspondence and data provided, it appears that your case meets the closure requirements in Ch. NR 726, Wisconsin Administrative Code. The Department considers this case closed and no further investigation or remediation is required at this time. However, you and future property owners must comply with certain continuing obligations as explained in this letter.

#### **GIS Registry**

This site will be listed on the Remediation and Redevelopment Program's internet accessible GIS Registry, to provide notice of residual contamination, and of any continuing obligations. The continuing obligations for this site are summarized below:

- Residual soil contamination exists that must be properly managed should it be excavated or removed
- Pavement, an engineered cover or a soil barrier must be maintained over contaminated soil and the state must approve any changes to this barrier

All site information, including the maintenance plan, is also on file at the Southeast Regional DNR office, at 2300 Dr. M.L. King Drive Milwaukee, WI. This letter and information that was submitted with your closure request application, including the maintenance plan, will be included on the GIS Registry, in a PDF attachment. To review the sites on the GIS Registry web page, visit the RR Sites Map page at http://dnr.wi.gov/org/aw/rr/gis/index.htm. If the property is listed on the GIS Registry because of remaining contamination and you intend to construct or reconstruct a well, you will need prior Department approval in accordance with s. NR 812.09(4) (w), Wis. Adm. Code. To obtain approval, Form 3300-254 needs to be completed and submitted to the DNR Drinking and Groundwater program's regional water supply specialist. This form can be obtained on-line at http://dnr.wi.gov/org/water/dwg/3300254.pdf or at the web address listed above for the GIS Registry.



#### **Closure Conditions**

Please be aware that pursuant to s. 292.12 Wisconsin Statutes, compliance with the requirements of this letter is a responsibility to which the current property owner and any subsequent property owners must adhere. You must pass on the information about these continuing obligations and the maintenance plan to the next property owner or owners. If these requirements are not followed or if additional information regarding site conditions indicates that contamination on or from the site poses a threat to public health, safety, welfare, or the environment, the Department may take enforcement action under s. 292.11 Wisconsin Statutes to ensure compliance with the specified requirements, limitations or other conditions related to the property or this case may be reopened pursuant to s. NR 726.09, Wis. Adm. Code. The Department intends to conduct inspections in the future to ensure that the conditions included in this letter including compliance with the attached maintenance plan are met.

#### Residual Soil Contamination

Residual soil contamination remains at areas located on the attached map Figure 4B, and in the information submitted to the Department of Natural Resources. If soil in the specific locations described above is excavated in the future, then pursuant to Ch. NR 718 or, if applicable, Ch. 289, Stats., and chs. 500 to 536, the property owner at the time of excavation must sample and analyze the excavated soil to determine if residual contamination remains. If sampling confirms that contamination is present the property owner at the time of excavation will need to determine whether the material is considered solid or hazardous waste and ensure that any storage, treatment or disposal is in compliance with applicable standards and rules. In addition, all current and future owners and occupants of the property need to be aware that excavation of the contaminated soil may pose an inhalation or other direct contact hazard and as a result special precautions may need to be taken to prevent a direct contact health threat to humans.

#### Cover or Barrier

Pursuant to s. 292.12(2)(a), Wis. Stats., the pavement, building foundation, and landscaped areas that currently exists in the location shown on the attached map Figure 1, shall be maintained in compliance with the attached maintenance plan in order to prevent direct contact with residual soil contamination that might otherwise pose a threat to human health.

Soil contamination remains at areas located on the attached map Figure 4B, and in the information submitted to the Department of Natural Resources. If soil in the specific locations shown on the attached map is excavated in the future, the property owner at the time of excavation must sample and analyze the excavated soil to determine if residual contamination remains. If sampling confirms that contamination is present the property owner at the time of excavation will need to determine whether the material is considered solid or hazardous waste and ensure that any storage, treatment or disposal is in compliance with applicable statutes and rules. In addition, all current and future owners and occupants of the property need to be aware that excavation of the contaminated soil may pose an inhalation or other direct contact hazard and as a result special precautions may need to be taken during excavation activities to prevent a health threat to humans.

The attached maintenance plan and inspection log are to be kept up-to-date and onsite. Please submit the inspection log to the Department only upon request.

#### **Prohibited Activities**

The following activities are prohibited on any portion of the property where [pavement, a building foundation, soil cover, engineered cap or other barrier] is required as shown on the attached map, unless prior written approval has been obtained from the Wisconsin Department of Natural Resources: 1) removal of the existing barrier; 2) replacement with another barrier; 3) excavating or grading of the land surface; 4) filling on capped or paved areas; 5) plowing for agricultural cultivation; 6) construction or placement of a building or other structure.

Upon Department approval to replace the existing barrier, the replacement barrier must be one of similar permeability, until contaminant levels no longer exceed the applicable standards.

#### **Post-Closure Notification Requirements**

In accordance with ss, 292.12 and 292.13, Wis. Stats., you must notify the Department before making changes that affect or relate to the conditions of closure in this letter. For this case, examples of changed conditions requiring prior notification include, but are not limited to:

Disturbance, construction on, change or removal in whole or part of pavement, an engineered cover or a soil barrier that must be maintained over contaminated soil

Please send written notifications in accordance with the above requirements to the Southeast Regional RR Program Office, to the attention of the Regional RR Program Environmental Program Associate.

Please be aware that the case may be reopened pursuant to s. NR 726.09, Wis. Adm. Code, if additional information regarding site conditions indicates that contamination on or from the site poses a threat to public health, safety, or welfare or to the environment.

The Department appreciates the actions you have taken to investigate and remediate the contamination at this site. If you have any questions or comments, please feel free to contact John J. Hnat, at the above address or at (414) 263-8644. Please refer to the FID number at the top of this letter in any future correspondence. Future correspondence should be sent directly to the Remediation and Redevelopment Program Assistant Vicky Stovall (414-263-8688) at the above address.

Sincerely,

James A. Schmidt

Southeast Region Team Supervisor Remediation and Redevelopment

mes a. Shurdy

Enclosures:

Figure 4B, Post-Remedial Soil Quality Map, Giles Engineering, dated 06-08-12


Figure 1, Cap/Barrier Maintenance Location Plan, Giles Engineering, dated 06-08-12


Engineered Building/Pavement Cap & Landscape Barrier Maintenance Plan, dated June 28, 2012

C: Linda Michalets, DS &PS Milwaukee

Stephen Owens & Kevin Bugel, Giles Engineering

WDNR SER Files





#### ENGINEERED BUILDING/PAVEMENT CAP & LANDSCAPE BARRIER MAINTENANCE PLAN

June 28, 2012

Property Located at:

4763 North 32nd Street Milwaukee, Wisconsin

FID: 341055779 / BRRTS No. 03-41-543817

SEE "EXHIBIT A" FOR LEGAL DESCRIPTION

TAX KEY NO. 230-0692-000

#### Introduction

The purpose of this document is to present a Maintenance Plan for an engineered cap and/or barrier system at the above-referenced property per the requirements of NR 724.13(2) of the Wisconsin Administrative Code. The maintenance activities relate to the existing building, landscaped areas, and paved surfaces occupying the area over the contaminated soil on site. The soil is impacted by polynuclear aromatic hydrocarbons (PAHs) chromium, and arsenic. The locations of the building, landscaped areas, and paved surfaces to be maintained in accordance with this Maintenance Plan are identified on the attached map Figures 1, included as Exhibit B.

#### Engineered Cap/Barrier Purpose

The building and paved surfaces over the contaminated soil serve as a cap, and clean soil over contaminated soil serve as a barrier to prevent direct human contact with residual soil contamination that might otherwise pose a threat to human health. Surfaces covered with an impervious cap also restrict infiltration to minimize future soil-to-groundwater contamination migration that would violate the standards of NR 140 of the Wisconsin Administrative Code. Based on the current and future use of the property, the cap should function as intended unless disturbed.

#### Annual Inspection

The cap/barrier surfaces overlying the contaminated soil will be inspected once a year for cracks, erosion, and other potential exposure pathways to underlying soil. The inspections will be performed to evaluate damage due to exposure to the weather, wear from traffic, increasing age and other factors. Areas where contaminated soil has become or are likely to become exposed will be documented. A log of the inspections will be maintained by the property owner and is included as Exhibit C, *Cap Inspection Log*. The log will include recommendations for necessary repair of any areas where underlying soil is exposed. Once repairs are completed, they will be documented in the inspection log.

#### Maintenance Activities

If exposed contaminated soil is noted during the annual inspections or at any other time during the year, repairs will be scheduled as soon as practical. Maintenance activities can include patching and filling operations or they can include larger resurfacing or construction operations. In the event that necessary maintenance activities expose the underlying soil, the owner must inform maintenance workers of the direct contact exposure hazard and provide them with appropriate personal protection equipment ("PPE"). The owner must also sample any soil that is excavated from the site prior to disposal to ascertain if contamination remains. The soil must be treated, stored and disposed of by the owner in accordance with applicable local, state and federal law.

In the event the cap/barrier surfaces overlying the contaminated soil are removed or replaced, the replacement barrier must be equally impervious or thick, with an infiltration rate equal to or less than 1 x 10<sup>-7</sup> cm/s. Any replacement barrier will be subject to the same maintenance and inspection guidelines as outlined in this Maintenance Plan unless indicated otherwise by the Wisconsin Department of Natural Resources ("WDNR") or its successor.

The property owner, in order to maintain the integrity of the cap/barrier surfaces, will maintain a copy of this Maintenance Plan on site and make it available to all interested parties (i.e. on-site employees, contractors, future property owners, etc.) for viewing.

#### Amendment or Withdrawal of Maintenance Plan

This Maintenance Plan can be amended or withdrawn by the property owner and its successors with the written approval of WDNR.

#### Prohibition of Activities and Notification of DNR Prior to Actions Affecting a Cover or Cap

The following activities are prohibited on any portion of the property where [pavement, a building foundation, soil cover, engineered cap or other barrier] is required as shown on the attached map, unless prior written approval has been obtained from the Wisconsin Department of Natural Resources: 1) removal of the existing barrier; 2) replacement with another barrier; 3) excavating or grading of the land surface; 4) filling on capped or paved areas; 5) plowing for agricultural cultivation; or 6) construction or placement of a building or other structure.

# Contact Information (as of June 2012)

Site Owner and Operator:

Bishop's Creek Family Housing, LLC.

Attn: Mr. Amanda Novak 328 Kellogg Blvd. West St. Paul, Minnesota 55102

Consultant:

Giles Engineering Associates, Inc.

Attn: Mr. Stephen Owens, P.G. N8 W22350 Johnson Drive, Suite A1

Waukesha, Wisconsin 53186

262-544-0118

WDNR:

John Hnat

Wisconsin Dept. of Natural Resources

2300 N Martin Luther King Jr Dr Milwaukee, Wisconsin 53212

414-263-8644

**Attachment** 


#### **EXHIBIT A**

#### Legal Description

Lot 2 of Certified Survey Map No. 8099, recorded on October 21, 2008, as Document No. 9662359, a division of part of Lot B of Block 21 of North Milwaukee Townsite Company's Addition No. 2, in the Northwest ¼ of the Northeast ¼ of Section 1, Town 7 North, Range 21 East, in the City of Milwaukee, County of Milwaukee, State of Wisconsin.

Part of Tax Key No.: 230-0328-100 (Old)

Tax Key No: 230-0692-000



Attachment

## **EXHIBIT C**

## **BARRIER INSPECTION LOG**

Inspection Date	Inspector	Condition of Cap	Recommendations	Have Recommendations from previous inspection been implemented?
		*		
				0

#### State Bar of Wisconsin Form 1-2003 WARRANTY DEED

Document Number	Document Nar	ne		
	Bishop's Creek Community Deve	lopment		
Corporation	("Grantor," wh			
and Bishop's Creek Family Ho	\			
	("Grantee," wh	nether one or more).		
estate, together with the rents,	•	rtenant interests, in	Recording Area  Name and Return Address  William R. Curmmings, Es Reinhart, Boerner, Van D  1000 North Water Street  Milwaukee, WI 53202	
			See Exhibit A  Parcel Identification 1	Number (DDI)
			Thisis not homestee	,
	the Property is good, indefeasible hose matters listed on <u>Exhibit B</u> at		(is) (is not) and clear of encumbrances ex	
Dated May 19,2009  BISHOP/S CRIVER COMMU  By: Survey Communication of the Communication of th	NITY DEVELOPMENT COR			(SEAL)
	ch Daniels	**		
*	(SEAL)	)		(SEAL)
		*		
AUTHENT	ICATION		ACKNOWLEDGMENT	
Signature(s)		STATE OF WISCO	NSIN	)
authenticated on	-	MILWAUKEE	COUNTY	Y PUBLIC III
*		Personally came bef	fore me on May 19 18	C IIII
TITLE: MEMBER STATE B	AR OF WISCONSIN			CYNTHIA
authorized by Wis. Stat. § 7	706.06)	instrument and ack	e the person(s) who execu	Healting Joses and
THIS INSTRUMENT DRAFTI	ED BY:	Cen	tua fich s	A CONTROL OF
Karen DaCosta Perzan, Esq.		* (4	nthia Vide	ME OF Migray
Quarles & Brady LLP		Notary Public, State	of Wisconsin permanent) (expires:_ <i>2/</i>	16.12011
NOTE: THIS IS A ST WARRANTY DEED *Type name below signatures.	(Signatures may be authenticated of FANDARD FORM. ANY MODIFICA © 2003 STAT	r acknowledged. Both ar	e not necessary.) SHOULD BE CLEARLY IDEN	STIFIED. FORM NO. 1-2003

#### EXHIBIT A

#### Legal Description


Lot 2 of Certified Survey Map No. 8099, recorded on October 21, 2008, as Document No. 9662359, a division of part of Lot B of Block 21 of North Milwaukee Townsite Company's Addition No. 2, in the Northwest ¼ of the Northeast ¼ of Section 1, Town 7 North, Range 21 East, in the City of Milwaukee, County of Milwaukee, State of Wisconsin.

Part of Tax Key No.: 230-0328-100 (Old)

Tax Key No: 230-0692-000

#### EXHIBIT B

- 1. General taxes for the year 2009, not yet due and payable.
- 2. Municipal and zoning ordinances and agreements entered under them.
- 3. Recorded easements, restrictions and covenants.
- 4. Water and sewer service charges, if any. None now due and payable.
- 5. Conditions contained in Certified Survey Map No. 8099, which state:
- a. That all utility lines to provide electric power and telephone services and cable television or communications systems lines or cables to all lots in the Certified Survey Map shall be installed underground in easements provided therefore, where feasible.
- That no lots created by this land division shall be conveyed, except in conformance with applicable zoning regulations.
- 6. Access Easement Agreement by and between Bishop's Creek Community Development Corporation and Bishop's Creek Family Housing, LLC dated as of May 19, 2009 and to be recorded in the Office of the Register of Deeds for Milwaukee County, Wisconsin.
- 7. Memorandum of Right of First Refusal of Bishop's Creek Community Development Corporation by and between Bishop's Creek Community Development Corporation and Bishop's Creek Family Housing, LLC dated as of May 19, 2009 and to be recorded in the Office of the Register of Deeds for Milwaukee County, Wisconsin.
- 8. Release Agreement by and between Bishop's Creek Community Development Corporation and Bishop's Creek Family Housing, LLC dated as of May 19, 2009 and to be recorded in the Office of the Register of Deeds for Milwaukee County, Wisconsin.
- 9. Storm Water Drainage Easement Agreement by and between Bishop's Creek Community Development Corporation and Bishop's Creek Family Housing, LLC dated as of May 19, 2009 and to be recorded in the Office of the Register of Deeds for Milwaukee County, Wisconsin.
- 10. Memorandum of Right of First Refusal of Commonbond Communities by and between Commonbond Communities and Bishop's Creek Family Housing, LLC dated as of May 19, 2009 and to be recorded in the Office of the Register of Deeds for Milwaukee County, Wisconsin.



8/20/2008

9 10 16 AM

Bishop's Creek Family Housing, LLC, as the party responsible for the impacts originating at 4765 North 32<sup>nd</sup> Street, in the City of Milwaukee, Milwaukee County, Wisconsin (BRRTS No. 03-41-543817), believes that the current legal description has been attached for the subject property. That legal description is:


Lots 2 of Certified Survey Map No. 8099, recorded on October 21, 2008, as Document No. 9662359, a division of part of Lot B of Block 21 of North Milwaukee Townsite Company's Addition No. 2, in the Northwest 1/4 of the Northeast 1/4 of Section 1, Town 7 North, Range 21 East, in the City of Milwaukee, County of Milwaukee, State of Wisconsin.

Part of Tax Key No.: 230-0328-100 (Old)

Tax Key No.: 230-0692-000

Title: Managing member Browning Leads Family Housing LP

Date: May 8 2012



USGS *Milwaukee, Wisconsin* 7.5-Minute Series (topographic) Quadrangle Map (1958; photorevised in 1971)

Scale:


1:24,000


Contour Interval:


10 Feet


FIGURE 1 SITE LOCATION MAP Bishop's Creek CommmonBond Property 4765 (formerly 4763) North 32<sup>nd</sup> Street Milwaukee, Wisconsin Project No. 1E-1205002




















# TABLE 1 POST-REMEDIATION / RESIDUAL SOIL ANALYTICAL RESULTS (DETECTED COMPOUNDS)

Bishops Creek Family Housing, LLC

Lot 2

4763 N. 32nd Street Milwaukee, Wisconsin

Project No. 1E-0912014

	Sample Location										Suggested PAH Generic RCLs											
Analyte					LUST Site 17 (1,000-gallon UST) Hot Spot Excavation										Playgroun	d Excavatio	n				Direct Contact.	
0.00000	GP-1/TW-1		SMW-3		SW Wall	S Wall	SE Wall	NW Wall	NE Wall	N Wall	N Base	C Base	S Base	W Base	SE Base	SE Wall	NE Wall		W-4	WAC NR	Non-Industrial	Groundwater
Sample Depth (feet)	2-4	2-4	6-8	13-15	5-7	5-7	5-7	5-7	5-7	5-7	14	14	14	8-9	8-9	5-6	5-6	2-4	10-12	720 RCLs	Pathway	Pathway
Sample Date	4/8/04	6/27/08	6/27/08	6/27/08	11/6/08	11/6/08	11/6/08	11/6/08	11/6/08	11/6/08	11/6/08	11/6/08	11/6/08	11/13/08	11/13/08	11/13/08	11/13/08	9/28/10	9/28/10			
PID (instrument units)	2	BDL	BDL	BDL	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	BDL.	BDL	0.0004	NO	NS
Arsenic (mg/kg)	5.8	5.2		2.0	127	5.5	3.3	5.4	4.6	5.1	4.6	6.96	3.7	3.21	1.81	2.49	3.3	<u>18</u>	10	0.039*	NS	NS NS
Baarium (mg/kg)	33.4				169	37.5	40	86	112	137	54.1	43	36.4	46.2	41.6	41.1	23.7			NS	NS	NS NS
Cadmium (mg/kg)	<0.588	#	1221		<6.24	<5.88	<6.03	<6.15	<6.18	<6.5	<5.58	<5.45	<5.7	0.085	0.063	0.12	<5.77			8	NS	NS NS
Total Chromium (mg/kg)	13.9	<u>==</u>			124	23.9	16.1	576	27.1	20.8	36.2	33.8	77	18	19.5	15.9	8.24	<u>59</u>	42	14**	NS	NS NS
Hexavalent Chromium (mg/kg)		<0.052		<0.052			:	-			-		22				••			14	NS	NS NS
Trivalent Chromium (mg/kg)		23		24																16,000	NS	NS NS
Total Lead (mg/kg)	12.5	17		9.6	34.7	10.4	6.88	8.63	9	10.4	9.05	10.2	6.56	7.29	6.61	6.61	8.55	26	20	50	NS	NS NS
Mercury (mg/kg)	<0.0420				0.034	0.056	0.019	0.047	0.032	0.044	0.018	0.037	0.029	0.036	0.029	0.058	0.017			NS	NS	NS NS
PCBs - Arochlor 1260 (mg/kg)			0.04		-	-			Œ											NS	NS	INS
Detected VOCs (ug/kg)																					NO	NC
Benzene	<25	<20		<20	<18.3	<u>16</u>	<15.9	<16.9	<16.3	<17.3	<14.9	<15.4	<15.5	<13.3	<12.7	<12.6	<16.3	<29	<29	5.5	NS	NS NS
Chloromethane	<25	<43	175	<43	120	130	<98.1	100	<101.0	<107.0	<91.9	100	<95.8	<82	<78.6	<77.5	<100	<58	<58	NS	NS	NS NS
Methylene Chloride	<100	<44	157	<44	79	<64.5	<66.3	180	210	230	69	190	210	<55.4	<53.1	<52.3	<67.7	160	160	NS	NS	NS NS
Naphthalene	<25	<117		<117	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	<58	110	NS	NS	NS NS
Tetrachloroethene	<25	<18	355	<18	46	53	47	43	49	64	46	46	45	<19.9	<19.1	<18.8	<24.4	<29	<29	NS	NS	NS NS
Trichloroethene	<25	<20		<20	210	41	30	160	30	39	29	120	29	<19.9	<19.1	<18.8	<24.4	<29	<29	NS	NS NS	NS NS
1,1,1-Trichloroethane	<25	<27	1223	<27	43	<20.6	<21.2	<22.5	<21.7	<23.1	<19.9	<20.5	<20.7	<17.7	<17	46	<21.7	<29	<29	NS	INS	INO
Detected PAHs (mg/kg)																		1	0.050	I NO	000	38
Acenaphthene	<0.118	<0.013	322	<0.013	0.008	0.0019	<0.0048	<0.0050	<0.0050	<0.0052	<4.56	<0.0045	<0.0046	<0.004	<0.004	<0.004	<0.0046	<0.056	<0,056	NS	900 5.000	3,000
Anthracene	<0.118	0.0088 J		<0.0088	<0.0252	<0.0242	<0.0242	<0.0252	<0.0252	<0.026	<22.8	<0.0226	<0.0023	<0.020	<0.019	<0.019	<0.023	0.21	<0.0062	NS	-1	17
Benzo (a) anthracene	<0.0588	0.0249		0.01	0.0052	0.0046	<0.0243	0.0021	<0.0252	<0.026	<22.8	<0.0226	<0.0023	<0.020	<0.019	<0.019	<0.023	0.045	0.19	NS	0.088	48
Benzo (a) pyrene	<0.0588	0.0204	1	<0.0077	<0.090	<0.090	<0.090	<0.090	<0.090	<0.090	0.0044	<0.090	<0.090	<0.09	<0.09	<0.09	<0.09	(0.048)	0.18	NS	0.0088	360
Benzo (b) fluoranthene	<0.0588	0.037		<0.011	0.0061	0.0036	<0.0486	<0.050	<0.050	<052	0.0053	<0.045	<0.0458	<0.040	<0.039	<0.039	<0.046	0.056	0.16	NS	0.088	6,800
Benzo (g,h,i) perylene	<0.118	0.0202 J	-	<0.012	0.0040	0.0033	<0.121	<0.126	<0.126	<0.130	0.0160	0.0038	<0.0075	<0.099	<0.099	<0.099	<0.116	0.049	0.20	NS	1.8	870
Benzo (k) fluoranthene	<0.118	0.0185 J		<0.011	0.0024	0.0018	<0.0243	0.0007	0.0008	<0.026	0.0015	<0.0226	<0.0021	<0.020	<0.019	<0.019	0.0009	0.022	0.076	NS	0.88	37
Chrysene	<0.118	0.040	-	0.0145 J	0.0047	0.0029	<0.0097	0.0011	0.0022	<0.010	<0.0091	<0.0093	<0.0092	<0.008	<0.008	0.001	0.0074	0.031	0.17	NS	8.8 0.0088	38
Dibenzo (a,h) anthracene	<0.00588	<0.0097		<0.0097	<0.090	<0.090	<0.090	<0.090	<0.090	<0.090	<0.090	<0.090	<0.090	<0.090	<0.090	<0.090	<0.090	(0.047)	0.21	NS		500
Fluoranthene	<0.118	0.057		<0.011	0.0087	0.0062	<0.0486	0.0024	0.0012	<0.052	0.0054	0.0013	0.0018	0.0008	0.0014	0.0015	0.0013	0.14	0.39	NS	600 600	100
Fluorene	<0.118	<0.012	-	<0.012	0.0007	<0.0096	<0.0097	<0.010	<0.010	<0.010	<0.0091	0.0008	<0.0092	<0.008	<0.008	<0.008	<0.009	<0.011	<0.011	NS	0.088	680
Indeno (1,2,3-cd) pyrene	<0.0588	0.0176 J		<0.0099	<0.126	<0.121	<0.121	<0.126	<0.125	<0.130	<0.114	<0.113	<0.115	<0.100	<0.010	<0.010	<0.116	0.043	0.19	NS		0.4
Naphthalene	<0.118	<0.012	8 <u>000</u> 0	<0.012	0.0022	0.0009	<0.0097	<0.010	0.0017	<0.010	<0.0091	<0.0090	0.0014	<0.008	<0.008	<0.008	<0.009	<0.033	<0.034	NS	20	1.8
Phenanthrene	<0.118	0.024 J		0.0096 J	0.0073	0.0046	0.0008	0.0016	0.0025	<0.0054	0.0079	0.0030	0.0049	0.0007	0.0012	0.0011	0.0011	0.044	0.096	NS	18	8,700
Pyrene	<0.118	0.051		<0.0099	0.0066	0.0046	< 0.0243	0.0022	0.0007	<0.002	0.0082	0.0019	0.0042	0.0008	0.0011	0.0012	0.0016	0.046	0.240	NS	500	8,700

NOTES:

PID: Photoionization Detector (Field)

**BDL:** Below Detection Limit

PCBs: Polychlorinated Biphenyls

VOCs: Volatile Organic Compounds
PAHs: Polycyclic Aromatic Hydrocarbons

RCRA: Resource Conservation and Recovery Act

RCL: Residual Contaminant Level

NP: Not Provided

mg/kg: Milligrams per kilogram; equivalent to parts per million (ppm)

ug/kg: Micrograms per kilogram; equivalent to parts per billion (ppb)

J: Result detected between laboratory method detection limit and quantitation limit

WAC: Wisconsin Administrative Code

NR: Natural Resources

NS: No Standard Established


--: Not Analyzed

Results indicated in red/underlined exceed the WAC NR 720-Table 1 or Table 2 Residual Contaminant Levels (RCLs)

Results indicated in green / parenthesis exceed the WDNR suggested generic non-industrial direct contact pathway RCLs (applies to samples collected within 4 feet of the ground surface)

<sup>\*:</sup> The Chapter NR 720 Table 2 RCL for non-industrial direct contact for arsenic (0.039 mg/kg) applies to samples collected within 4 feet of ground surface.

<sup>\*\*:</sup> The Chapter NR 720 Table 2 RCLs for non-industrial direct contact for hexavalent chromium (14 mg/kg) and trivalent chromium (16,000 mg/kg) apply to samples collected within 4 feet of ground surface. For soil samples submitted for total chromium, the lower RCL (14 mg/kg) was used.





GEOTECHNICAL, ENVIRONMENTAL & CONSTRUCTION MATERIALS CONSULTANTS

· Atlanta, GA

· Baltimore/Wash. DC

Dallas, TX

· Los Angeles, CA

Milwaukee, WI
 Orlando, FL

June 7, 2012

Mr. Ronald Leonhardt City Clerk, City of Milwaukee 200 E. Wells Street, Room 205 Milwaukee, WI 53202

RE:

Notice of Residual Soil Impacts
Within Public Street or Right-of-Way
Bishop's Creek Family Housing Facility
4763 North 32<sup>nd</sup> Street
Milwaukee, Wisconsin
WDNR\*BRRTS #03-41-543817
Project No. 1E-1205002

Dear Mr. Leonhardt:

Enclosed please find a copy of the Notice of Residual Soil Impacts letter which was submitted to the City of Milwaukee-Department of Public Works. Chapter NR 726.05 (2)(b)(4) of the Wisconsin Administrative Code requires the Municipal Clerk and Municipal Department responsible for maintaining the street or highway be given written notification of the potential presence of residual soil or groundwater impacts within the right-of-way. The attached letter serves as this notification. Please place a copy of this notification in the appropriate files.

If you have any questions or comments regarding this notification, please feel free to contact us at (262) 544-0118.

Sincerely,

GILES ENGINEERING ASSOCIATES, INC.

Stephen M. Owens, P.G.

Project Hydrogeologist

Kevin T. Bugel, PG., C.P.G.

**Environmental Department Manager** 

Distribution:

City Clerk, City of Milwaukee

Attn: Mr. Ronald Leonhardt (1 USPS)
Bishop's Creek Family Housing, LLC
Attn: Ms. Amanda Novak (1 USPS)

Wisconsin Department of Natural Resources

Attn: Ms. Victoria Stovall (1 USPS)

G:/1E-1205002-citynot.let1/00env3/smo



# GILES ENGINEERING OSSOCIATES, INC.

GEOTECHNICAL, ENVIRONMENTAL & CONSTRUCTION MATERIALS CONSULTANTS

- · Atlanta, GA
- · Baltimore/Wash. DC
- · Dallas, TX
- · Los Angeles, CA
- · Milwaukee, WI
- · Orlando, FL

June 7, 2012

Mr. Jeffrey Polenske City Engineer, City of Milwaukee Department of Public Works Infrastructure Services Division 841 North Broadway Milwaukee, WI 53202

RE: Notice of Residual Soil Impacts
Within Public Street or Right-of-Way


Bishop's Creek Family Housing Facility 4763 North 32<sup>nd</sup> Street Milwaukee, Wisconsin WDNR BRRTS #03-41-543817 Project No. 1E-1205002

Dear Mr. Polenske:

On behalf of Bishop's Creek Family Housing, LLC, Giles Engineering Associates, Inc. (Giles) is notifying the City of Milwaukee Department of Public Works regarding the potential presence of residual soil impacts (arsenic) located along the east property line (adjacent to North 32<sup>nd</sup> Street) at the above referenced site. Giles has petitioned the Wisconsin Department of Natural Resources (WDNR) for case closure for the site, conditional upon filing of the appropriate GIS registry information and notifying municipal authorities of residual soil impacts potentially extending into public right-of-ways.

Giles is notifying your department pursuant to Wisconsin Administrative Code, Chapter NR 726.05 (2)(b)(4), of the potential presence of soil impacts beneath the right-of-way, which may exceed applicable Wisconsin Administrative Code, Chapter NR 720 standards for soil.

Giles has enclosed a table presenting residual soil analytical results, and a Post-Remedial Soil Quality Map showing soil boring and monitoring well locations and areas with impacted soil exceeding Wisconsin Administrative Code (WAC), Chapter NR 720 residual contaminant levels (RCLs). Arsenic impacted soil above WAC NR 720 Soil Standards is present within the North 32<sup>nd</sup> Street right-of-way.



Bishop's Creek Family Housing Facility 4763 North 32<sup>nd</sup> Street Milwaukee, Wisconsin Project No. 1E-1205002 Page 2



If future construction activities disturb soil in the vicinity of the above referenced site, the excavated soil may be considered a solid waste and require proper disposal. In addition, if future construction activities require dewatering, or if groundwater is to be otherwise extracted in the vicinity of the above-referenced site, the groundwater should be sampled and managed in compliance with applicable statutes and rules.

If you have any questions or comments, please contact us at (262) 544-0118.

Sincerely,

GILES ENGINEERING ASSOCIATES, INC.

Stephen M. Owens, P.G.

**Project Hydrogeologist** 

Kevin T. Bugel, P.G., C.P.G.

**Environmental Department Manager** 

Enclosure:

Soil Quality Table and Map (2)

Distribution:

City Engineer, City of Milwaukee

Attn: Mr. Jeffrey Polenske (1 USPS) Bishop's Creek Family Housing, LLC Attn: Ms. Amanda Novak (1 USPS)

Wisconsin Department of Natural Resources

Attn: Ms. Victoria Stovall (1 USPS)

City of Milwaukee City Clerk

Attn: Mr. Ronald Leonhardt (1 USPS)

G:/1E-1205002-citynot.let1/12env2/smo/ldk