
Directorate of Public Works ENVIRONMENTAL COMPLIANCE BRANCH 2171 South 8th Avenue Fort McCoy, WI 54656-5136

HAZARDOUS MATERIALS SPILL FORM

| SUBJECT: | Fuel Spill | LOCATION: | North Post |
|--|---|--|--|
| DATE of Release: DATE of Reporting: | 5/16/2018 5/16/2018 | INCIDENT #: COORDINATES | 16MAY18-01 461453 395070 |
| HAZARDOUS MATERIALS: | <u>F-24</u> | GALLONS RELEASED: | 20-25 gallons |
| TIME OF INCIDENT: | 2000 | TIME OF REPORTING: | 2030 |
| CAUSE OF SPILL: | HUMAN ERROR (TYPE OF ERROR): Humvee was driving up Burma Road and the the engine caught on fire | EQUIPMENT FAILURE: | (WHAT PART FAILED) Engine Failure |
| VEHICLE SOURCE: (ECS, MATES, IMMA, TMP, OFF-POST, POV, ETC.) UNIT INVOLVED (IF APPLICABLE): | IMMA HHC 1/178TH INFANTRY Illinois | MOB- RELATED, AT, OR OTHER. SUPPLIES USED: | TRAINING RELATED DRIVING work order to Roads & Grounds to remove contaminated soil from site. |
| HOME ADDRESS: | Illinois | | |
| DODDAC #: | | TOTAL MAN- HOURS: | 12 |
| about a mile north of the feet long. At the location wide. It appears that the location is the second of the secon | ON OF INCIDENT: vas F-24. It appears that between 20 and 25 gallons the Ski Hill. It appears that all of the firel in the tanktion of the spill the contaminated soil is 6-8 feet wich the firefighting efforts spread the contamination fart toadway and in the ditch. Spill was dug up 28JUN18 | k was released. The a le, and at the bottom of her than it would hav | area of contaminated soil is approximately 225 end of the contaminated area it is about 2 feet |
| REPRESENT- | | | (Use back if needed) |
| ATIVE PERSON: | | TITLE: | |
| PHONE: | | Soil Excavated: | 32.6 ton |
| RESPONSE PERSON: | Mathew L. Varner | | |



W912ES-16-C-0004 RG SO 1013-0004 Spill clean-up, transport, restore Weigh Ticket Computations

| Truck | Empty Wt. Lb. | Ticket # | Loaded Wt. Lb. | Ticket # | Loaded - Empty Wt. Lb. |
|---------|---------------|----------|----------------|-------------|------------------------|
| Load 1 | 25,860 | 35516 | 56,660 | | |
| Load 2 | . 27,600 | blank | 61,900 | | 34,300 |
| Load 3 | | | | | 0 |
| Load 4 | | | | | 0 |
| Load 5 | | | | | 0 |
| Load 6 | | | | A | 0 |
| Load 7 | | | | | 0 |
| Load 8 | | | | | 0 |
| Load 9 | | | | | 0 |
| Load 10 | | | | | 0 |
| Load 11 | | | | | 0 |
| Load 12 | | | | | 0 |
| Load 13 | | | | | 0 |
| Load 14 | | | | - 5 | 0 |
| Load 15 | | | | | 0 |
| Load 16 | | | | | 0 |
| Load 17 | | | | | 0 |
| Load 18 | | | | - 28 | 0 |
| Load 19 | | | | | 0 |
| Load 20 | | | | | 0 |
| Load 21 | | | | - 3 | 0 |
| Load 22 | | | | | 0 |
| Load 23 | | | | | 0 |
| Load 24 | | | | | 0 |
| | | | | T-4-1144 10 | 55.100 |

Total Wt. LB. 65,100
Total Tonnage 32.55

Drange truck Empty weight

Orang Frank

Cend # /

SPARTS WILL SAGES ENDINE # 600 380 2755 ONDINE # 600 508 3715

26666 10

White Tauck 100d#2

10nd # 2 White Truck



Spill on top of hill going downhill towards the truck. Debris left from the fire.



Spill ran down into forest following ditch line.



Excavation



Back filling with gravel



Finished Project